

PICHARD P. CROUSE (419) 259 5221

:

Docket No. 50-346 *License No. NPF-3 Serial No. 1-95

October 19, 1979

Mr. James G. Keppler Regional Director, Region III Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

IE Bulletin No. 79-14, dated July 2, 1979, requested that we develop and implement an inspection program to verify that the Davis-Besse Nuclear Power Station Unit 1 seismic analysis input of safety related piping systems conforms to the actual field conditions.

Our inspection of normally accessible safety related piping was completed September 21, 1979. Discrepancies found during the inspection were reviewed in accordance with the guidance provided in Supplement Nos. 1 and 2 to IE Bulletin 79-14. On October 1, 1979 we submitted to you the results of our detailed engineering reviews for approximately 50% of the field inspection packages. Attached is our detailed engineering reviews for all remaining field inspection packages. These reviews indicate that none of the discrepancies found during the inspection of accessible safety related piping affect system operability. Our schedule for follow-on analytical work required under Item 4B of the bulletin to support the results is also attached.

OCT 22 1979

7911050 186 TOLEDO, OHIO 43652

Based on favorable results of the completed detailed engineering reviews of our inspection of accessible safety related piping, we have established a high degree of confidence that Davis-Besse's seismic analysis acceptably conforms to the as-built safety related systems. Therefore, as proposed in our letter of August 1, 1979 (Serial No. 1-81), Toledo Edison will delay the inspection of normally inaccessible piping systems until the spring outage currently scheduled to begin March 1980.

Yours very truly,

Molom

RPC: CLM

Attachments

bj a/7

cc:

U. S. Nuclear Regulatory Commission Office of Inspection & Enforcement Division of Reactor Operations Inspection Washington, D.C. 20005

U.S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Division of Operating Reactors Washington, D.C. 20555 Docket No. 50-346
License No. NPF-3
Serial No. 1-95
October 19, 1979

Seismic Analysis For As-Built Safety Related Piping Systems

Response to NRC IE Bulletin No. 79-14

Davis-Besse Nuclear Power Station Unit 1

I. Introduction

NRC IE Bulletin 79-14, dated July 2, 1979, Revision 1, dated July 18, 1979, Supplement 1, dated August 15, 1979, and Supplement 2, dated September 7, 1979, require all power reactor facility licensees to verify that the seismic analysis of safety-related piping systems applies to the actual as-built configuration of systems. The action items identified in the bulletin apply to all safety-related piping, 2-1/2 inches in diameter and greater, and to Seismic Category I piping, regardless of size, which was analyzed by computer.

The response to Item 1 of the bulletin was submitted on August 1, 1979 (Serial No. 1-81). A partial response to Item 2 of the bulletin, describing the inspection procedures and discrepancies reviewed prior to September 30, 1979 for normally accessible piping systems, as defined by the bulletin, was submitted on October 1, 1979 (Serial No. 1-93). This report provides a complete response to Item 2 of the bulletin and for the normally accessible piping that has been inspected, it provides a response to Item 4 of the bulletin.

II. Action Item 2

For portions of systems which are normally accessible, inspect one system in each set of redundant systems and all non-redundant systems for conformance to the seismic analysis input information set forth in design documents. Include in the inspection: piping run geometry; support and restraint design, locations, function and clearance (including floor and wall penetration); embedments (excluding those covered in IE Bulletin 79-02); pipe attachments; valve and valve operator locations and weights (excluding those covered in IE Bulletin 79-04). Within 60 days of the date of this bulletin, submit a description of the results of this inspection.

III. Response

Inspection of all normally accessible safety-related piping as defined in the bulletin, including both redundant trains, was performed as described in our response to Item 1 of the bulletin. The inspection teams began the walkdown inspections at the site on July 30, 1979 and completed the effort on September 21, 1979. Preliminary evaluation of the discrepancies discovered by the inspection team have been completed and the results indicate that none of these discrepancies adversely affect system operability. Detailed engineering reviews of the walkdown inspection packages have been completed. Discrepancies identified by both the inspection team and the stress analyst have been tabulated and are shown in Attachment 1. This tabulation includes the discrepancies that were previously submitted on October 1, 1979. Detailed engineering review of all discrepancies are complete and support the preliminary evaluation that the operability of safety-related systems is unaffected by these discrepancies.

IV. Action Item 4

If nonconformances are identified:

- A. Evaluate the effect of the nonconformance upon system operability under specified earthquake loadings and comply with applicable action statements in your technical specifications including prompt reporting.
- B. Submit an evaluation of identified nonconformances on the validity of piping and support analyses as described in the Final Safety Analysis Report (FSAR) or other NRC approved documents. Where you determine that reanalysis is necessary, submit your schedule for: (i) completing the reanalysis, (ii) comparisons of the results to FSAR or other NRC approved acceptance criteria and (iii) submitting descriptions of the results of reanalysis.
- C. In lieu of B, submit a schedule for correcting nonconforming systems so that they conform to the design documents. Also submit a description of the work required to establish conformance.
- D. Revise documents to reflect the as-built conditions in plant, and describe measures which are in effect which provide assurance that future modifications of piping systems, including their supports, will be reflected in a timely manner in design documents and the seismic analysis.

V. Response

The discrepancies identified by the field inspection and the stress analyst are arranged in Attachment 1 by system, stress calculation number and pipe support or anchor number. As shown in the attachment, an engineering review has been made as to what kind of reanalysis, if any, is required to make the as-built configuration of the piping and supporting systems agree with the design.

This reanalysis may consist of a structural calculation for a pipe support or anchor, a hand calculation to evaluate the affect of a relocated support, or a complete reanalysis of a piping system. After the required reanalysis is complete, the determination will be made as to the necessity of any field rework.

If at any time, this reanalysis results in a conclusion that a deficiency exists in either the piping or its supporting system that affects system operability, applicable technical specification action will be taken.

The earliest projected completion date for reanalysis of the piping and support systems is February 1, 1980. A report on the results of the reanalysis is presently scheduled for mid-February, 1980. The current completion date for revising engineering documents to reflect the as-built conditions in the ctation is March 1, 1980.

To assure that modifications are reflected in the engineering documents, all modifications to safety-related piping systems, including their supports, are made only by a Facility Change Request (FCR). Prior to the start of any physical work, the FCR is forwarded to engineering for detailed design. The required engineering is then performed, including: field routing of piping, field location of supports, stress analysis of piping, design and/or revisions to supports, and issue of drawings for construction. Once the rework is completed at the site, engineering documents are updated to reflect the as-built configuration.

ATTACHMENT 1

Response to NRC IE Bulletin 79-14

The discrepancies identified by the field inspection effort and the detailed engineering reviews are listed on the attached sheets.

The stress calculations are grouped by system and the description of all the discrepancies identified that appear in each stress calculation are tabulated accordingly.

If, for a given stress calculation, no discrepancies are noted, reanalysis of the calculation is not required.

If a discrepancy is of small significance and affects only a pipe support or anchor, the support itself is reanalyzed. If found adequate, a drawing change may be required. This required reanalysis is indicated by a single asterisk (*).

If a discrepancy includes location of supports beyond the established tolerance, a simple hand calculation to evaluate the affect on the pipe and adjacent supports will be performed. This required reanalysis is indicated by two asterisks (**).

If a discrepancy includes use of preliminary valve weights in the analysis, different response spectra to be considered, missing piping supports, etc., the stress calculation will require a complete reanalysis. This is indicated on the following sheets by three asterisks (***).

PACE 1 01 62 By Gally Gall DATE toll 16 169

			TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS		HECKE	9	I	-	DATE 10/13
			SYSTEM MAIN STEAM	100 E	T TO N. DESTGR			STE	H BILITY
CALCUIATION NO. NALKINGTO PACKACK NO.			DIS CREPANCIES	OK AS IS OR DAG	CORRECT TO	ANALYSIS REQUIRED	UNAFFECTED	AFFECTED	IF AFFECT REFER TO REMARK NO.
	NO NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	+	-				
418 3			EED-19-E17 Welds not in accordance with H-190-E037-1916-6 EED-19-E28 Welds not in accordance with H-190-E037-1927-6 EED-19-E30 Welds/configuration not in accordance with H-190-E037-1929-7 Anchor A221 moved 1'-1" towards West 3A E-D-19 E34 moved 1'-6" towards North EC, %B, EA, the supports are added 24 EED-19 E14 moved 1'-11" towards West 3A EBD-19 E9 moved 14" towards East 3A EBD-19 E10 moved 16" towards East						:
		1	Evaluation			700	x		
404 4.5			EBB-2-E29 Welds not is accordance with N-190-E03J-228-3 EBD-19-E49 moved 13½" South EBD-19-E136 moved 1'-0" up (was below floor) 19-E39 moved 5'-1½" down A309 moved 1'-2" West 2-E27 moved 2'-2" South						
			Weight of valves 262-2 and 262-3 used in the analysis differs from the wendor supplied weights			***	x		
40B 3 4			EBD-19-E55 Plate size mot shown on N-190-E03E-1954-3 EBD-19-E56 Plate size not shown on N-190-E03E-1954-4 EBD-19-E142 Welds not in accordance with N-190-E03E-A1941-2 EBD-19-E154 moved West 16" EBD-19-E147 not installed EBD-19-E145 moved 2'-4" West and 1'-2" South 3A EBD-19-E72 moved 19" towards West						
		x	Evaluation			Tes	x		
40C 4			Anchor A-294 pipe motch cut into Support for drain line Ancho: A-372 pipe motch cut into Support for drain line EXAMPLE Welds mot in accordance with M-190-E03H-10207-6 EED-102-E6 moved 13 1/16" East EED-102-E9 E10 in accessible Evaluation			7	I		

by haly ful DATE LO/18 H IE BULLETIN 79-14 DESCRIPTION OF IMSPECTION RESULTS ENECKED OR AS IS OR DAG/ CALC CHCS REQU CORRECT TO ORIGINAL DESIGN SYSTEM SYSTEM MAIN STEAM **OPERABILITY** UNAFFECTED IF AFFECTE STRESS
CALCULATION
NO.
WAYNOCATI
PACCACE
NO. AKALTSTS REQUIRED AFFECTED. REFER TO REMART NO DISCREPARCIES IF YES, DESCRIPTION OF DISCREPANCIES NO YES Anchor A-2 not installed 120B 5 Yes × Evaluation X No Discrepancies 1200 5 Evaluation x No X X Ebb-2-E36 Structural Number not in accordance with M-190-E03J-235-2 120E 5 EED-19-880 Welds not in accordance with M-190-803J-1979-5 Extra Support R "A" located between EBB-2-H18 and EBB-2-H19 Anchor A-2 not installed Weights of walve B62-4 used in analysis differs from wander supplied weight Tes T Evaluation EBD-19-H105 Structural Member not in accordance with 120G | 5 H-190-E03J-A1904-6 EBD-19-E107 Structural Member not in accordance with N-190-E03J-A1906-4 ERD-19-E1 8 Structural Momber not in accordance with H-190-HU3J-A1917-5 19-E116 moved 1'-3" fouth 19-E100 moved 1'-3" Best 4-309 moved 1'-2" West Pipe Susports EBD-19-H104 and H105 span the Seismic joint Evaluation x EBD-19-882 Configuration/Structural Member not in accordance with M-190-803J-235-2 120H 5 EBD-19-E96 Welds not in accordance with M-190-E03J-1997-6 19-#91 moved 1'-44" Mortheast Supports in areas 7 & 8 Envelope ased be Yes 1 Evaluation x EBB-2-R7A Welds not in accordance with H-190-H03J-206A-1 120A Support 2-H8 moved 2'-0" South Support 2-16 moved 3'-7" South Support 2-86A moved 1'-3" South Yes -1 Eveluetion 1265 166

.

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

				IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	OH		Ca	7		MTE D/13/N
				SYSTEM HAIN STEAM	Se C	TO DESTON			TRA	BILITY
CALCULATION NO.	WALKAGUN PACKACE NO.			DISCREPANCIES	OK AS TS OF TO	CORRECT TO	ANALTSIS REQUIRED	UNAFFECTED	AFFECTED	TE AFFECT CEFER TO KEMARK NO.
5 2	328	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	-	-	-	_		
1200	,		x	EBB-2-Hill Weld not in accordance with M-190-1403J-210-5 Evaluation			Yes	×		
10A	1			SR-11 moved 4'-2\" South SR-10 moved 3'-6" East (Snubber only)						*
			x	Weight of the valves 8109-2 and FV-101 used in the analysis differs from wendor supplied weight Evaluation			Yes	x		
108	2		x	EBB-1-SR-18 snubber eyelet pads are undersized EBB-1-SEC-Y braced located on opposite side of support Restraint (anchor) at shield building wall SR-18 moved 3'-8 1/8" East Valve Bl09-1 (Valve weight) Valve FV-100 (Valve weight) Weight of the Valve. Bl09-1 and FV-100 used in the analysis differs from vendor supplied weight Evaluation				x	***	
1201	5		x	EBD-19-H125 weld not in accordance with M-190-H03J4-A1924 EBD-19-H128 weld not in accordance with M-190-H03J4-21927 Anchor A221 Noved 1'-1" towards West 19-H-124 moved 1'-2" South Weight of valve B62-1, used in analysis differs from wendor supplied weight Evaluation			Yes	x		
				1265 167		,				

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS SYSTEM TO TO SYSTEM AUXILIARY PEELWATER CALC CHGS REGO OPERABILITY IF AFFECTE STRESS
CALCULATION
NO.
WALKINGS
PACKAGE
NO. UNAFFECTED CORRECT TO ANALYSIS REQUIRED AFFECTED REFER TO REMARK NO DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES NO YES EBD-14-El Welds not in accordance with H-190-E06F-1400-8 18 ERD. 4-H7 not in accordance with H-190-H06F-1406-6 *** X Evaluation x ERD-14-E17A Welds not in accordance with M-190-E17A-14168-4 10 ERD-14-E19A Welds not in accordance with H-190-E067-1418A-4 ERD: 14-E16 Spans Areas 7 and 8 Yes Evaluation I 4 EED-14-835 moved 14" South Envelope of areas 7 and 9 should be used in the analysis Yes × Evaluation Extra Hanger located on 6" - EED-137 between Anchor A8 and EED-137-88 20 EBD-14-E90 moved 1'-9" South EBD-14-E74 moved 2'-10" East Tes x Evaluation x 7 23A X Evaluation x 23B Evaluation X × EED-272-E5 Not in accordance with M-190-E06G-27204-7 7 2.3C Extra Support UH-1 located between HBD-22-R5 and HBD-22-H8 EBD-272-E3 coved 14 3/4" down Weight of valve 425-1 used in analysis does not agree with wendor suppled weight X Evaluation *** I 1265 168

BY & aly AL MITTO AT TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS DIECKED DATE DO 10/19 OK AS IS OR DAG/ CALC CHGS REQD CORRECT TO ORIGINAL DESIGN ANALYSIS REQUIRED SYSTEM STEAM GENERATOR DRAINS SYSTEM OPERABILITY STRESS CALCULATION NO. WALKDOWN PACKAGE. 150. UNAFFECTED IF AFFECT REFER TO REMARK DISCREPANCIES NO NO YES IF YES, DESCRIPTION OF DISCREPANCIES Anchor A021 moved 8" West and 13%" Down EBD-61-361 moved down 2'-0" EBD-61-843 moved 2'-0" West EBD-61-842 moved 18" West EBD-61-847 moved 15" South . Evaluation Yes X 64A Weight of valve \$15-2, used in the analysis differs from wendor supplied weight Envelope of areas 7 and 9 should be considered in seismic enalysis x Evaluation Yes IX EBD-61-H-6 moved 2'-3" Merth EBD-61-H53 moved 4'0" East 64B Seismic curves for ares 8 should be used in analysis x Eveluation X Yes 64C EBD-61-H13 configuration/clearances not in accordance with H-190-H073-6112-6 EBD-61-H9 moved 1'-7" West EBD-61-H11 moved 3'-3" West EBD-61-H12 moved 2'-0" East EBD-61-H13 moved 2'-0" East x Evaluation Yes X 640 Anchor A-16 moved 13-1/8" Morth Valve A85-7 (walve weight) Valve B15-1 (valve weight) Seismic Joint Mismatch Weight of valves A85-7 and B15-1 used in analysis differs from wender supplied weight. Envelope of areas 9 and 7 should be used in seismic analysis X Evaluation 64E Extra hanger located between EBD-61-H20 and EBD-61-H66 Anchor A016 moved North 13-1/8" Envelope of areas 7 and 9 should be used in seismic analysis I Evaluation Yes 647 . Anchor A018 moved 1'-11" East I Evaluation Yes X . Length of pipe increased by 3'-6" Anchor A020 moved 1'-11" Bast Anchor A021 moved 8" West and " @ The . Evaluation Yes x 1205 169

PACE 5

_ OF 62

:

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CALC CHCS REQUIRECT TO OR EGINAL DESIGN SYSTEM SYSTEM FEEDWATER OPERABILITY STRESS
CALCUTATION
NO.
WALKINKES
PACKALS
NO. REFER T IF AFFECTES ANALYSIS REQUIRED REFER TO DISCREPANCIES ~ YES IF YES, DESCRIPTION OF DISCREPANCIES 42B EBD-12-SE20 Structural Member not in accordance with C-619 EBD-12-SH21 Structural Member not in accordance with Extra Support UR-1 located between EBD-12-SR27 and EBD-12-SH13 12-5R30 moved 1' -8"S. 12-5R39 moved 12t"E. 12-5R40 moved 12t"E. 12-5R42 moved 1'-4 3/4"W. The weight of Valve 15-1 used in seismic analysis differs from wendor supplied weight. Yes x Evaluation x 42D Anchor A-171 moved 5'1 3/4" Bast Weight of valve A15-2 differs from wendor supplied weight x Evaluation Yes X POOR ORIGINAL 1265 170

0F 62 DATE 9/20/24

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS		ECKET	Om	7	7	MTE 7/20/
					-				STE	
CALCULATION NO.	PACKAGE NO.			DISCREPANCIES	OK AS TS OR DAG/ CALC CHCS REGO	CORRECT TO ORIGINAL DESIGN	ANALYSIS REQUIRED	UNAFFECTED	_	IF AFFECT REFER TO REMARK NS.
3 %	NON	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	00	0.5	22	5	~	
192	25			HBC-44-H5 Additional Load Attached MCB-49-H1 Welds not in accordance with Grannell SK. B-4900 MCB-49-H2 Welds not in accordance with Grannell SK. B-4901 MCB-44-H-10 moved 13" South MCB-44-H-7 moved 144" South MCB-44-H-2 moved 15" Up Support HCB-44-H10 Spans areas 7 6 9 Envelope of these 2 areas should be considered in analysis.						:
				Evaluation			700	*	L	
1190	25			HBC-74-H3 Welds not in accordance with Grinnell SK. 11-7402 RBC-74-H10 Welds not in accordance with Grinnell SK. 11-7469 HBC-74-H11 Welds not in accordance with Grinnell SK. 11-7410 HBC-74-H13 Welds not in accordance with Grinnell SK. 11-7412 HBC-74-H14 Welds not in accordance with Grinnell SK. 11-7413 HBC-74-H14 Welds not in accordance with Grinnell SK. 11-7413 EBC-74-H16 word 13" South EBC-74-H18 moved 13" South EVALUATION EVALUATION EVALUATION EVALUATION			7	1		
119E	25	+	+	HBB-16-B) Welds not in accordance with M-190-H29-1600-3				T	T	
				RBB-16-H2 moved 1'-10" North			** yes	,		
11911	25	1		Extra Support No. 1 located next to HBC-73-H9						
		1			+	+	-	+	+	-
1191	25			Evaluation					=	
1193	25	1		HBC-73-B4 Welds not in accordance with Grinnell SK. 11-7303 HBC-73-B7 Welds not in accordance with Grinnell SK. 11-7306 HBC-73-B8 Welds not in accordance with Grinnell SK. 11-7307						
1198	25	+	7	NBC-73-R6 Welds not in accordance with Grinnell SK. 11-7305	T	T	T		1	
			1.	Evaluation			;			
		1	1	A	1	1				
				1265 171						

BY Lacyte DATE 19/18/19

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS		CHI	CKE	C	int		DATE	p/s/r
				SYSTEM REACTOR OCCULANT DRAIN AND GASEOUS MADMASTE	/SMG	200	SIGN			YST	EM ABILIT	Y
NO. WALKDONS: PACKAGE NO.	7				AS 15 OR	CALC CHCS REGO	CORRECT TO ORIGINAL DESIGN	ANALYSIS	MATERIAL	AFFECTED	IF A	FFECTI
MCK.	_	_	_	DISCREPANCIES	- 8	CAL	8 8	AN OF		1	NO.	
	NO	YE	5	IF YES, DESCRIPTION OF DISCREPANCIES	+	\dashv	_	-	+	+	+	
45				EBC-33-ES Configuration not in accordance with M-190-H40C-330A-2 ESC-42-K1 welds not in accordance with M-190-H40C-4200-8 ESC-42-H2 welds not in accordance with M-190-H40C-4201-8 ESC-42-H26 welds not in accordance with M-190-H40C-4225-5 ESC-4-2-H29 configuration not in accordance with M-190-H40C-4228-4 ESC-4-2-H32 welds not in accordance with M-190-H40C-4231-7 ESC-4-2-H33 configuration not in accordance with M-190-H40C-4231-7 ESC-42-H36 welds not in accordance with M-190-H40C-4235-6 Extra support UH-1 loce-sd next to HSC-42-H37 Extra support UH-2 between ESC-42-H33 and ESC-42-H34 ECB-42-H29 moved 15" East ECB-42-H28 moved 15" East ECB-42-H28 moved 16" South Weight of value HV1119B used in analysis differs from vandor supplied weight Envelope of 7 and 9 should be used in analysis						X		
765 4				RSC-84-H2 welds not in accordance with M-190-H40C-8401-9 RSC-42-H9 welds not in accordance with M-190-H40C-4208-5 RSC-42-H11 welds not in accordance with M-190-H40C-4213-7 RSC-42-H13 configuration/welds not in accordance with M-190-H40C-4212-6 Extra support located between HSC-42-H1 and HSC-42-H18 Extra support located between HSC-131-H4 and HSC-131-H5 RSC-130-H1 moved 12 7/8" East HSC-131-H3 moved 14 5/8" West Weight of valves PSV-1801 and B65-36 used in analysis differ from vendor supplied weight Evaluation					···· Yes	x		
78C	49	×		Evaluation		,			No	x		

1

DATE 9/20/29
DATE 9/20/29 IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED O SYSTEM TO DESIGN OK AS IS OR DWG CALC CHGS NEQD CORRECT TO ORIGINAL DESIGN SYSTEM MAKEUP AND PURIFICATION OPERABILITY IF AFFECTI' ANALYSIS REQUIRED STRESS
CALCULATIO
RG.
WALKIOUN
PACKAGE
NO. REFER TO REMARK NO. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES YES 31-BCC-2-R5 lowered 15%" 81 Yes x Evaluation 1 BCC-36-El Welds not in accordance with M-190-E31D-3600-4 698 28 ECC-36-E7 Welds not in accordance with M-190-E31D-3606-4 MCC-36-Hill Configuration/Structural Members not in accordance with M-190-H31D-3610-7 MCC-36-H12 Structural Mombers not in accordance with M-190-E31D-3611-6 BCC-36-H13 Configuration/Structural Members not in accordance with M-190-8310-3612-5 MCC-36-#14 Structural Mombers not in accordance with M-190-H31D-3613-5 BCC-36-E16 Structural Members not in accordance with M-190-8310-3615-3 BCC-36-E19 Structural Mambers not in accordance with H-190-H31D-3618-10 BCC-36-H12 moved 1'-4" up BCC-36-H11 moved 13" up S.A. Support MCC-36-H5 spens Seismic joirt X Yes Eveluetion I CCB-13-H1 Structural Member not in accordance with 27 69C H-190-H31D-1300-5 CCB-13-E2 Configuration not in accordance with M-190-E31D-1301-5 OCB-13-84 Welde not in accordance with M-190-831D-1303-8 CCB-13-E5 Welds not in accordance with M-190-E31D-1304-8 CCB-13-E11 Welds not in accordance with H-190-E31D-1510-4 CCB-13-826 Welds not in accordance with M-190-831C-1324-1 CCB-13-H28 Welds not in accordance with M-190-H31C-1326-2 Extra Sepert UH-1 located next to CCB-13-H27 Extra Support UH-2 located mext to CCB-15-H28 Anchor A-308 moved 3'-4" West OCB-13-E25 moved 1'-0" South then 1'-2h" East along pipe around elbow CCB-13-F11 moved 124" East Weight of the walve Bll-3 used in Seismic analysis differs from wender supplied weight. Pipe Supports 33 CCB13-84 and %5 spans the seismic joint between areas 7 and 8 I Evaluation Te. I 1265 174

PAGE_

OF_62

				SYSTEM MAKEUP AND PURIFICATION		ECKE			STE	BILITY
CALCULATION NO.	WALKDOAN PACKACE. NO.			DISCREPANCIES	OK AS IS OR DUC	CORRECT TO ORIGINAL DESIGN	ANALYSIS	UNAFFECTED	AFECTED	IF AFFE.
38	X 4 5	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	80	0.6	55	5	7	
69 D	20		1	Extra Support E "A" located between Anchor A368 and CCB-15-E5 Extra Support E "B" lasted between CCB-15-E5 and CCB-15-E6 Anchor A368 moved 3'-4" West 31-CCB-15-E5 moved 3'-5" East 31-CCB-15-E8 inaccessible for inspection 31-CCB-15-E9 inaccessible for inspection			Yes	x		
692	28		1	Extra Hanger H "C" located between Aschor A68 and NCC-36-H21 31-HCC-36-H22 moved 17" East 31-HCC-36-H24 inaccessible for inspection 31-HCC-36-H25 inaccessible for inspection Evaluation				x		
80 c	26		1	31-mcc-35-m103, m104 not accessible			e. Yes	x		
70	26		x	31-CCB-9-El located in Area 9 Evaluation			Yes	x		
704	26			BCC-35-H-13 not installed Anchor A-166 structural numbers not in accordance with C-882 BCC-1-H3 welds/structural numbers not in accordance with M-190-H31B-102-7 BCC-1-H5 welds not in accordance with M-190-H31B-109-5 BSC-66-H8 welds not in accordance with M-190-H31B-6614-6 BSC-66-H15 welds/clearances not in accordance with M-190-H31B-6614-6 BSC-66-H23 clearance not in accordance with M-190-H31B-6622-2 31-HSC-66-H8 moved 13" East 31-HSC-66-H14 moved 13" East 31-RSC-66-H21 moved 23" East 31-RSC-66-H23 moved 23" East			To.	1		
				1265 175						

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

			SYSTEM MAKEUP AND PURIFICATION	8 8	SIGN			STER	BILITY
STRESS CALCULATION NALKDOWN PACKAGE NO.	1		DISCREPANCIES	OK AS IS OR DMG/ CALC CHGS REQU	CORRECT TO ORIGINAL DESIGN	ANALYSIS REQUIRED	UNAFFECTED	AFFECTED	IF AFFECTE REFER TO REMARK NO.
E3 5 3 5 5	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	100	00		_		
69A 26 20 32		x	ESC-66-H16 welds not in accordance with M-190-H31B-6619-7 CSC-66-H26 structural member not in accordance with M-190-H31B-6625-2 ECC-5-H3 welds not in accordance with M-190-H31D-504-3 ECC-5-H7 welds not in accordance with M-190-H31D-506-2 ESC-62-H1 welds not in accordance with M-190-H31D-6200-2 ESC-62-H2 configuration not in accordance with M-190-H31D-6201-3 Extra hanger UR-1 located between anchor A-4 and ECC-124-H4 ESC-71-H3 structural member not in accordance with M-190-H40C-7102-3 ESC-71-B4 welds not in accordance with M-190-H40C-7103-5 ESC-71-H6 welds not in accordance with M-190-B40C-7103-3 ESC-71-H8 snubber piston position not in accordance with M-190-B40C-7107-4 ESC-71-H10 snubber piston position not in accordance with M-190-B40C-7109-1 ESC-71-H13 configuration not in accordance with M-190-B40C-7112-2 ESC-5-H6 moved 15½" Horth on branch line Weight of the value PSV-1893 used in analysis differs from vendor supplied weight Envelope of areas 7 and 8 should be used in analysis Evaluation					x	

1265 176

BY haghe DATE 9/20/29 CHECKED C DATE 9/20/79 OR AS IS OR DUG/ CALC CHCS REQD CORRECT TO ORIGINAL DESIGN SYSTEM SYSTEM DECAY HEAT REMOVAL OPERABILITY UNAFFECTED IF AFFECTIVE ANALYSIS REQUIRED REFER TO NO. DISCREPANCIES IF YES, DESCRIPTION OF DESCREPANCIES GCB-8-H2 Spring travel stops still installed GCB-7-H7 Structural member not in accordance with M-190-B33C-706A-3 GCB-7-H9 Configuration not in accordance with GCB-7-H9 Configuration not in accordance with M-190-H33C-708-3

GCB-8-H6 moved 1' 10" south

GCB-8-H5 moved 2' 4 5/16" south

Weight of valves EV-DH9B and B97-1 used in the analysis differs from the vendor supplied weight.

Envelope of areas 7 & 8 should be used in seismic analysis yes Evaluation Envelope of areas 7 and 9 should be used in analysis yes × Evaluation Envelope of areas 7 and 9 should be used in analysis yes 4 Evaluation x 1265 177

:

STRESS CALCULATION NO. WALKDOWN PACKAGE. NO.

30

31

31

32E

32G

32H

YES

.

.

*

NO

DATE PAR whalf IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED CO OR BUC/ SYSTEM TO DESIGN SYSTEM LOW PRESSURE INJECTION OPERABILITY OK AS IS OR CALC CHCS R CORRECT TO ORIGINAL DE ANALYSIS REQUIRED IF AFFECT CALCULATION NO. WALKNOWS PACKAGE NO. VFECTED REFER TO REMARK NO. DISCREPANCIES IF YES. DESCRIPTION OF DISCREPANCIES NO YES GCB-1-H5 moved 8 3/4" West CCB-1-H7 moved 8 3/4" West GCB-1-H11 moved 2'-2" West 188 33 Yes Evaluation I GCB-10-H17 moved 18 3/4" West GCB-10-H16 moved 12" West GCB-10-H10 moved 15" Horth 33 185 Envelope of areas 7 & 8 and 9 should be used in the analysis Evaluation × The weight of Valve \$56-5 used in the seismic analysis differs from wender supplied weight. 45B 33 Ravelope of areas 8 and 9 should be in the analysis. x Y .. Evaluation x BCB-36-HS moved 134" East 45C 33 HCB-36-H6 moved 3'-75" North fnchor A-067 moved 24" down Support 33B-HCB36-H7 spans areas 7 and 8 X Evaluation X 26 33 37 BOA BCC-35-H3 welds not in accordance with M-190-H31B-3502-7 HCC-35-H5 Clearances not in accordance with M-190-H31B-3504-4 BCC-35-E19 Not installed HCC-35-H22 Welds not in accordance with M-190-H31B-3521-5 QCB-1-E36 not installed Extra Support located next to GCB-1-Hl 33 B-MCC-36-H12 includes as - 0 not in stress iso. GCB-1-H2 moved 12%" down GCB-1-H32 moved 134" North BCC-34-84 moved 21" up BCC-34-E2 moved 21 3/4" up Weight of the following valves used in Seismic analysis differs from vendor supplied weight: B135-1,2; EV-DE 13A, 13B, 6 14B Yes Evaluation x 1265 :78

BY half he DATE 9/80/21 IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED CA OK AS IS OR EACH CALC CHGS REQO COARECT TO ORIGINAL DESIGN ANALYSIS REQUIRED SYSTEM SYSTEM BIGH PRESSURE INJECTION OPERABILITY UNAFFECTED IF AFFECTE STRESS CALCULATIONO NO. WALKDOWN PACKACE NO. REFER TO REMARK NO. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES YES NO Anchor A055 moved up 144" 32 53 OCB-19-812 moved up 2'-15" CCB-19-H12 moved up 2'-14"
CCb-2-R18A moved up 104"
CCB-19-H9 moved 134" east
CCB-19-H7 moved 2'-64" morth
CCB-19-H8 moved 184" north
Pipe CCB-19 (H7 & R8) was 7'-84" long
CCB-19-H6 moved 124" east
CCB-19-H5 moved 12 7/8" east 3 Anchor A054 in area 8. Envelope of 7 & 8 meeds to be used in analysis Weight of the valves B7-1 & B7-4 used in the seismic malysis differs from wender supplied weight. Yes X Evaluation X CCB-2-E17 Welds not in accordance with M-190-E33D-216-8 32 CCB-12-HI Welds not in accordance with M-190-E330-1200-2 CCB-19-H2 Configuration not in accordance with M-190-H33D-1901-8 CCV-19-H3 Welds not in accordance with M-190-H33D-1902-8 CCP-19-E3 moved 6 5/8" east New hanger H-2 installed 4'-11t" east of CCB-19-E1 OCB-12-81 moved 14 3/8" west Support #3 spane joint. Envelope of 7 & 8 meeds to be used in analysis Yes I Evaluation 1 CB-2-H7 Structural Members not in accordance with 56A 32 H-190-B33D-206-5 CCB-2-E11 Walds not in accordance with M-190-E33D-210-6 Extra Hanger UH-1 located between Anchor A-46 and BCC-124-B4 Envelope of Areas 7 & 9 needs to be used in analysis CCB-2-H12 moved 12 3/4" Morth Yes Evaluation X x OCB-2-H3 Welds not in accordance with M-190-H33D-202-5 Extra Manger UR-3 located between CCB-2-84 and CCB-2-85 OCB-2-84 moved 234" north Anchor 4-055 moved up 14t" Yes x Evaluation . The weight of the walve EV-EP2B used in the analysis differs from 56B2 the wender supplied weight. Envelope of Aress 7 6 9 should be used in the analysis. Evaluacion Tes X 1 1265 179

PAGE

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKE SYSTEM TO DESIGN SYSTEM MIGH PRESSURE INJECTION CHCS REQU OPERABILITY IF AFFET STRESS CALCULATION NO. WALKINGTN PACKACE: NO. CORRECT TO ORIGINAL ANALYSIS REQUIRED AFFECTED REFER TO OK AS REMARK DISCREPANCIES NO. 17.5 IF YES, DESCRIPTION OF DISCREPANCIES MCC-91-E2 Welds not in accordance with M-190-E33D-9101-4 36C 32 BCC-91-H3 Welds not in accordance with M-190-H33D-9102-10 . Yes I Evaluation X 56D 32 ECC-91-E9 Welds not in accordance with M-190-E33D-9108-7 MCC-91-H12 Welds not in accordance with M-190-H33D-9111-6 BCC-91-H9 moved 13 1/8" west BCC-91-88 moved 13 1/8" west x Evaluation X 32 BCC-91-H13 Configuration not in accordance with M-190-E33D-9112-4 56E BCC-91-H17 Welds not in accordance with Grimmell 14-9116 MCC-91-H19 Welds not in accordance with M-190-H33D-9116-6 MCC-91-H21 Welds not in accordance with M-190-H33D-9120-6 HCC-91-H23 Welds not in accordance with H-190-H33D-9122-4 3"-HCC-91 E1. 580'-3"(J-3) increased length by 1'-10 3/16" Yes Evaluation 56F 32 BCB-2-E36 Welds not in accordance with M-190-E33D-235-2 BCB-2-E38 Welds Fot in accordance with M-190-E33D-237-2 BCB-2-E39 Belds not in accordance with H-190-E33D-238-3 BCB-2-840 Welds not in accordance with M-190-E33D-239-2 BCB-2-H41 Welds not in accordance with M-190-E33D-240-2 BCB-2-843 Welds/Places not in accordance with M-190-833D-242-2 Minor modification from originally analyzed piping configuration. New Manger installed 7" from east elbow at El. 559'-9" 4"MCC-124 Evaluation 56B3 28 CCB-3-H1 Configuration not in accordance with M-190-H31D-300-1 CCB-3-W2 Welds not in accordance with M-190-E31D-301-5 CCB-3-E3 Welds not in accordance with %-190-E31D-302-3 CB-3-H2 moved 2'-2" Hortheast Anchor A369 moved 2'-0" Bast Area 9 should be enveloped in Seismic analysis I Evaluation Tes 1265 180

PAGE

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED CAL OK AS IS OR DUC/ CALC CHCS REGO CORRECT TO ORIGINAL DESIGN ANALYSIS REQUIRED SYSTEM SYSTEM ENERGENCY CORE COOLING OPERABILITY UNAFFECTED IF AFFECTS STRESS
CALCULATION
NO.
PACKACS.
NO. REFER TO NO. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES NO YES MCB-2-H18 moved 2'-43" Bast 32A BCB-2-E17A moved 125" West Weight of walve HV-DH9A used in the analysis differs from the wender supplied weight X Yes Evaluation X GCB-8-H8 welds not in accordance with M-190-H33B-807-6 30 32B Weight of walve B97-2 differs from the wendor supplied weight Yes Evaluation x GCB-2-H11 moved 15" West 29 30 33 32D BCB-3-H11 moved 13" South 33A-HCB-2-H74 to mineing Weight of valves \$25-1, \$26-1 differ from the supplied wendor weights Envelope of areas 7, 8 and 9 should be considered in analysis Yes Evaluation X 1265 181

POOR	UE	olei	A î	1	TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	a	ECKE	an		_	MTE 19/3/14
FUUN	U	IUI	NA	IL	SYSTEM EMERGENCY CORE COOLING	E DNC/	ESTON		OF	_	BILITY
	STRESS CALCULATION NO.	WALKDOWN PACKAGE NO.			DISCREPANCIES	OK AS IS OR DMC/	CORRECT TO	AKALTSIS	UNAFFECTED	AFFECTED	IF AFFEC EN REFER TO REMARK NO.
	55 2	325	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	+-	-		Н		
	180	30		x	GCB-4-B6 moved 8" down Weight of valve B25-2 used in the analysis differs from wendor supplied weight Evaluation				x		;
	25	29		1	Extra Support located between ECB-2-E24 and ECB-2-E32 Extra Support located between ECB-2-E11 and ECB-2-E32 Extra Support located between ECB-2-E23 and ECB-2-E32 Extra Support located between ECB-2-E4 and ECB-2-E32 Extra Support located between ECB-2-E4 and ECB-2-E32 Extra Support located between ECB-2-E4 and ECB-2-E32 ECB-2-E13 Configuration not in accordance with M-190-E33A-204-13 ECB-2-E13 Configuration not in accordance with E:190-E33A-212-9 ECB-2-E31 Structural Number not in accordance with M:190-E33A-226-8 ECB-2-E31 Structural Number not in accordance with M:190-E33A-230-6 Weld missing in ECB-2-E44 33A-ECB-2-E3 moved 28" in to Tank 33A-ECB-2-E3 moved 28 15/16" East for AZ 33A-ECB-2-E3 permits + AY deflection 33A-ECB-2-E14 moved 15½" West 33A-ECB-2-E17 moved 10" East Evaluation			Ye		*	
	129	5P 29		x	HCC-93-H1 Welds/Structural Number not in accordance with M-190-H33A-9300-1 ECC-93-H2 Welds not in accordance with M-190-H33A-9301-1 Extra Support located mext to ECC-93-H5 33A-ECC-93-H1 moved up 23" (SA) 33A-ECC-93-H2 moved down 11'-2½" (SA) 33A-ECC-93-H6 not in the math model Evaluation			Ye	•	x	
	12	50 29			33A-BCC-122-E5 moved 23 1/8" West HSC-122-H2 welds not in accordance with M-190-H33A-122-1-2 Evaluation			Ye		x	
					1265 182				•		

:

IF BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

CHECKED 10/13/19 OR DMC/ SYSTEM to DESTON SYSTEM_ CONTAINMENT SPRAY OPERABILITY CALC CHCS OR CORRECT TO OR IGINAL DE STRESS CALCULATION NO. WALKDOWN PACKAGE NO. IF AFFECTI A:WLYSIS REQUISED UNAFFECTE SFECTED. REFER 30 REMARK DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES NO YES GCB-5-E3 Welds not in accordance with M-190-E34D-502-8 194 GCB-5-B4 Welds not in accordance with H-190-B34D-503-7 GCB-5-E33 moved 7" East Weight of walves B24-10 and B31-2 used in the analysis differ from vendor supplied weights. Yes × Evaluation x GCB-5-E7 Load-Carrying Number not in accordance with 19B 36 H-190-H34D-506-9 GCB-5-H9 Welds not in accordance with M-190-H34D-508-5 GCB-5-E35 not in accordance with M-190-E34D-534-1 ECC-38-E3 Structural Number not in accordance with H-190-#34D-3802-5 Extra Banger UE-3 located between Anchor A80 and BCC-38-E5 Weight of the valves \$24-11, \$31-3 and \$98-1 used in analysis differ from wendor supplied weight Envelope of Areas 7 & 9 med be considered in analysis Yes Evaluation X MCC-38-H7 Clearances and additional loading not in 19C 36 accordance with SE-14-3806 BCC-38-H8 Welds not in accordance with SK-14-3807 MCC-38-H9 Configuration of additional Hanger not in accordance with SK-14-3808 MCC-38-Hll Structural Mamber size, shim size, and clearance not in accordance with M-190-H34D-3810-6 MCC-38-E12 Welds not in accordance with M-190-E34D-3811-4 MCC-38-H13 Additional loads attached to Manger Anchor A-81 moved 1'-6" West ECC-38-E8 moved 1'-7" Bast Support MCC-38-H12 Spans Areas 7 and 9 Envelope of Areas 7 & 9 should be used in analysis X Evaluation Yes I HCC-37-H17 Shims, Wrapper Plate and Associated Welds not in accordance with M-190-H34D-3716-3 19F 36 Extra hanger UH-1 located between HCC-37-H14 and HCC-37-H15 Extra hanger UH-2 located between MCC-37-H14 and MCC-37-H15 Extra hanger UR-4 located between BCC-37H15 and BCC-37-H16 BCC-37-H17 moved 1'-34" West Envelope of areas 76 8 meed be considered in seismic analysis X Yes Evaluation I 1265 183

OF 62 INTE 9/20/24

DY kaly and DATE 10/13/29 TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS Cu DATE 1 /3/79 CHECKED POOR ORIGINAL SYSTEM OK AS IS ON DAG! TO DESIGN SYSTEM CONTAINMENT SPRAY OPERABILITY. UNAFFECTED IF AFFECTE CORRECT TO ANALYSIS REQUIRED REFER TO STRESS CALCULAT NO. WALKDOAN PACKAGE NO. REMARK no. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES 100 YES Anchor AllO moved 13 1/8" South 35 Envelope of area 7 should be included in the analysis Tes Evaluation . x 34 BCC-38 E-22 moved 1" North S.A. 35 318 34 BCC-38 E21 moved 14" East S.A. 34 BCC-38 E19 woved 34" down 34 BCC-38 E16 & E17 moved 2" West 34 BCC-38 B15 mover 5" up 34 BCC-38 E23 moved 4" East S.A. Anchor AllC moved 13 1/8" South Anchor A174 moved 12" down Evaluation T.. I I MCB-9-H10 additional loads attached to hanger 190 BCB-9-H18 welds not in accordance with M-190-H34D-917-8 BCB-9-H19 Load-Carrying member not in accordance with 37 H-190-H34D-918-7 BCB-9-H30 moved 125" South BCB-9-H20 moved 1'-3" West Weight of valve B24-4 differs from vendor supplied weight Support HCB-9-H13, H14 and H18 span areas 7 and 9 Yes x Evaluation x HCC-37-H7 hanger and baseplate not in accordance with 19E H-190-H34D-3706-8 BCC-37-H9 beseplate not in accordance with M-190-H34D-3708-8 36 HCC-37-H10 moved 1'-45" East Support HCC-37-H10 spans areas 7 and 8 Alternate supports attached to areas 7 and 8 X Yes Evaluation X GCB-10-H23 melds not in accordance with M-190-H33F-1022-6 180 HCB-9-H14 welds not in accordance with H-190-H34D-913-7 HCB-9-H15 welds not in accordance with H-190-H34D-914-6 CCB-6-H12 moved 3" way from shield building CCB-6-H13 moved 7" up CCB-6-H1 moved 1" North GCB-10-H34 moved 3" down GCB-10-H20 moved 11 7/8" South GCB-10-H21 moved 2" South GCB-10-H24 moved 4 3/4" Southwest ECB-9-R15 moved 1 1/8" North ECB-9-R13 moved 11 1/8" North ECB-9-R14 moved 12 1/8" North GCB-10-H26 moved 24" up GCB-10-H27 moved 34" down Envelope of areas 7 and 9 should be used in the analysis

X

Yes X

Evaluation

1265 184

U	NIU	INA	SYSTEM SPENT PUEL POOL COOLING	EQD.	SIGN			YSTE
STRESS CALCULATION NO.	PACKACE NO.		DISCREPANCIES	OK AS IS OR DAG CALC CHGS REQD	CORRECT TO ORIGINAL DESIGN	ANALYSIS REQUIRED	UNAFFECTED	AFFECTED
E S S	3 2 2	NO YES	IF YES, DESCRIPTION OF DISCREPANCIES	83	88	52	5	\$
●OB	37	x	Extrs Hanger H "H" located mext to MCC-26-H10 Anchor A-222 moved 27" West Anchor A-231 moved 18 1/8" South 35-HCC-26-H9 moved 12½" down 35-HCC-26-H11 moved 11 3/4" South			** Yes	x	
930	37 36		Extra Support H "D" located between ESC-20-H19 and ESC-20-H20 35-ESC-32-H20 moved 66%" E, H around elbow					
	-	1	Systemation			Yes	x	1
643	8 37		Extra Hanger H "B" located next to Anchor A-368 Extra Hanger H "G" located next to HSC-32-H2 EBD-61-H55 moved 2'-6\" West Anchor A-117 moved 13" North 35-HSC-32-H6 moved 2'-7" Hast for Y 35-HSC-32-H6 moved 1'-7" Hast for X 35-HSC-32-H2 moved 13" South ESC-32-H18 moved 9'-7" down ESC-32-H18 moved 9'-7" down ESC-32-H1 is missing Weight of the valves A85-6 and B68-4 used in the activate differs from the wendor sumplied weight Evaluation			Tes	x	
93E	29		HSC-122-E103 not installed HSC-122-E107 Welds not in accordance with M-190-E33A-A12206-3 HSC-122-E111 Welds not in accordance with M-190-E33A-A12210-2 Extra Support installed between HCC-93-E107 and HCC-93-E109 33A-HSC-122-E111 moved 30 11/16" East 33A-HSC-122-E102 moved 12 11/16" East			-		And the second s

00	"	UINI	uı	IVA	TE BULLETIN 79-14 DESCRIPTION OF INSPECTION SESULTS . SYSTEM SPENT FUEL POOL COOLING	EQ0	DESTON			STEM ERABIL
	CALCULATION	WALKDOWN PACKAGE NO.			DISCRE/ANCTES	OK AS IS ON DAG CALC CHGS REQD	CORRECT TO ORIGINAL DE	ANALYSIS REQUIRED	UNAVPECTED	AFECTED
	63.	342	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	-				1
	••	36 37			ECC-7-E9 Weld not in accordance with M-190-E35B-708-2 ECC-7-E5 moved 23h" West ECC-7-E8 moved 9" North ECC-7-E10 moved 1'-9h" North Differential movement between areas 7 & 8 should be considered Evaluation			yes Yes	x	
	934	38		x	ECC-18-B4 Welds not in accordance with M-190-E35B-1803-2 ECC-18-E6 Welds not in accordance with M-190-E35B-1805-4 ECC-75-E1 Welds not in accordance with M-190-E35B-7500-3 ECC-75-E2 Welds not in accordance with M-190-E35B-7501-3 ECC-75-E3 Welds not in accordance with M-190-E35B-7502-3 35-ECC-13-E5 moved 13" West 35-ECC-18-E8 moved 13 3/4" North 35-ECC-18-H9 - no Z Bastraint installed 35-ECC-75-E4 moved 3'-7 3/4" North Anchor A-219 spans Seismic joint Evaluation			700	x	*
	931	38		1	HCC-18-H11 Clearance not in accordance with M-190-H358-1810-5 Extra Support EH-1 located next to Anchor A-331 Extra Support EH-2 located next to Anchor A-184 Extra Support EH-4 located next to BCC-18-H12 Extra Support ER-5 located next to BCC-18-H12 Extra Support ECC-50-H326 Anchor A-400 moved 8 3/8" up 35-HCC-18-H12 moved 144" West Weight of the Valve B126-1 considered in analysis differs from wender supplied weight Evaluation			70		
	93	38			Section of piping system is inaccessible Evaluation	,		,	0 7	
	7-0	093 36	•		OZ Soubber missing-1'-0" below MCS-6-M4 on analysis Evaluation			1	:	

		/		IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS			Con			MTE (0/13/79
					/			SY	STE	
STRESS CALCULATION NO.	KAGE			DISCREPANCIES	OK AS IS OR DWG.	CORRECT TO ORIGINAL DESIGN	AHALYSIS REQUIRED	UNAFFECTED	AFFECTED	IF APPECTED REFER TO REMARK NO.
E 3 5 3	MO.	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	00	00	-	_		
T-009A	33			ECC-21-E2 Configuration not in accordance with M-190-E35B-2101-4 ECC-21-E4 Welds not in accordance with M-190-E35B-2103-6 ECC-21-E5 Welds not in accordance with M-190-E35B-2104-6 ECC-21-E17 Welds not in accordance with M-190-E35B-2116-2 ECC-21-E18 Welds not in accordance with M-190-E35B-2117-3 ECC-21-E19 Welds not in accordance with M-190-E35B-2118-4 ECC-21-E1 moved 244" North ECC-21-E2 moved 14 1/8" East I-Restraint not on analysis Evaluation			Yes	x		
т-009в	37 38		x	BCC-21-R10 Structural Number not in accordance with N-190-E357-2109-4 BCC-75-B6 Configuration not in accordance with N-190-E35B-2112- BCC-21-R16 moved 6'-2 3/4" West BCC-21-R11 moved 1'-8½" up BCC-75-E7 moved 13½" down	,		to Te	2 3		
т-009к	37 38		x	Extra Support EH-3 located next to MCB-10-R1 BCB-10-R1 moved 2'-1" North 35-ECC-76-E3 moved 20t" South Support ECB-10-E1 spans Seismic joint Evaluation			Ve Ye	•	x	
93F	37	1	ļ,	Anchor A408 moved 25t" West Evaluation	+	1	Y		x	
				1265 187						

:

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS DATE 10/13/79 Cin CHECKED POOR ORIGINAL OR AS IS OR DWG/ CALC CHGS REGO CORRECT TO ORIGINAL DESIGN SYSTEM OPERABILITY SYSTEM COMPONENT COOLING WATER IF AFFECT ANAL'YSTS REQUIRED AFFECTED STRESS
CALCULATION
NO.
VAI KDG/FN
PACKAGE
NO. REFER 1" REMARY NO. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES YES 42 61E X I Ro Evaluation X EBC-3-El Structural Member not in accordance with 42 61N M-190-H36D-300-6 HBC-3-H2 Structural Mamber/Welds not in accordance with N-190-301-8 EBC-3-E3 Belds not in accordance with M-190-E36D-302-6 A 113 moved 3'-0" up EBC-3-E2 moved 14 7/8" Morth EBC-3-E3 moved 15" South 700 Evaluation T EBB-1-El Structural Number sot in accordance with 61H H-190-8360-100-6 EBC-39-84 Welds not in accordance with M-190-836D-3903-7 EBC-39-E9 Welds not in accordance with M-190-E36D-3908-8 EBC-39-H16 Structural Member not in accordance with H-190-H36D-3911-7 Extra Banger UH-3 handled next to EBC-39-86 A106 moved 2'-8" East Yes Evaluation Anchor A-114 delds not in accordance with C-856 42 611 HBC-3-HS Extra Hanger attached X Tes Evaluation X ERC-10-R1 Welds not in accordance with M-190-R36A-1000-3 61P EBC-10-E2 Welds not in excordance with M-190-E36-1001-3 Support 36-EBC-10-H2 goved 1'-04" Borth x Yes Evaluation x EBC-22-E1 Welds not in accordance with M-190-E36C-2200-7 37 61X BBC-22-E2 Helds not in accordance with M-190-E36C-2201-7 EBC-22-H1 moved 1'-7 5/8" West Yes Evaluation x 1265 188

DISCREPANCIES DISCREPANCIES DISCREPANCIES NO VES 1F YES, DESCRIPTION OF DISCREPANCIES Anchor A-091 moved 13" South ENGLIPED 18-20-20 Reliable 20-20-20 Reliabl
Anchor A-091 moved 13" South ENC-2-E5 Configuration not in accordance with H-190-E168-204-; ENC-2-H5 Configuration not in accordance with H-190-E168-204-; ENC-23-H6 Welds/Structural Mamber not in accordance with H-190-E168-205-7 ENC-50-H2 Configuration not in accordance with H-190-E168-5001-6 ENC-50-H2 Configuration/Structural Mamber not in accordance with H-190-E168-5001-9 Valve B41-4 has been two.cated into this problem Anchor A-094 moved 1"Borth Anchor A-095 moved 2'-84" East ENC-23-H5 moved 1'-54" up D_smaions 16"ENC-50 minor changes (C-5) 2 welded attachments added 1b, below ENC-23-H1 ENC-50-H1 moved 1" West ENC-50-H2 moved 24" Borth ENC-50-H2 moved 24" East Weights of valves B146-1, B146-2 differ from wender supplied weights
Evaluation EBC-2-E5 Configuration not in accordance with H-190-E368-204-: Evaluation Evaluation Evaluation Tes X Evaluation Tes X Evaluation Tes X Evaluation Tes X Evaluation EBC-23-E6 Welds/Structural Member not in accordance with N-190-E368-2305-7 EBC-50-E7 Configuration not in accordance with N-190-E368-5001-6 EBC-50-E7 Configuration/Structural Member not in accordance with H-190-E368-5002-9 Valve B41-4 has been talled into this problem Anchor A-094 moved 1"Borth Anchor A-095 moved 2'-8\frac{1}{2}" East EBC-23-E5 moved 1'-5\frac{1}{2}" up Dimensions 16"EBC-50 minor changes (C-5) 2 welded attachments added 18, below EBC-23-E1 EBC-23-E15 moved 2\frac{1}{2}" Borth EBC-50-E1 moved 1" West EBC-50-E2 moved 2" East Weights of valves E146-1, B146-2 differ from vendor supplied weights
Braination BC-23-B6 Welds/Structural Mamber not in accordance with N-190-E068-2305-7 BC-50-B2 Configuration not in accordance with N-190-E068-5001-6 BC-50-B3 Configuration/Structural Member not in accordance with N-190-E068-5002-9 Valve B41-4 has been to reacted into this problem Anchor A-094 moved 1"Borth Anchor A-095 moved 2'-84" East BC-23-B5 moved 1'-55" up Disensions 16"BC-50 minor changes (C-5) 2 welded attachments added 1b3 below EBC-23-B1 EBC-23-B15 moved 2½" Borth EBC-50-B2 moved 2" East Weights of valves B146-1, B146-2 differ from wendor supplied weights
BBC-23-B6 Welds/Structural Mamber not in accordance with N-190-B36B-2305-7 BBC-50-H2 Configuration not in accordance with N-190-B36B-5001-6 BBC-50-B3 Configuration/Structural Member not in accordance with M-190-B36B-5002-9 Valve B41-4 has been to seated into this problem Anchor A-094 moved 1"Borth Anchor A-095 moved 2'-84" East BBC-23-B5 moved 1'-54" up Dimensions 16"BBC-50 minor changes (C-5) 2 welded attachments added 185 below BBC-23-B1 BBC-23-B15 moved 2½" Borth BBC-50-H1 moved 1" West BBC-50-H2 moved 2" East Weights of valves B146-1, B146-2 differ from wendor supplied weights

half L DATE 1 1/3/7

			TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS			Cin	V		MTE DOS
	,		SYSTEM COMPONENT COOLING WATER	REGO	esig.		OP		BILITY
CALCULATION NO. HALKING E: PACKAGE. NO.			DISCREPANCIES	OK AS IS OR DAG/	CORRECT TO ORIGINAL DESIGN	ANAL PSIS REQUIRED	UNAFFECTED	AFFECTED	REFER TO REMARK NO.
SEEE	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	-	-		-	1	
61M 41	AU .	TES	Anchor A-401 welds/structural numbers not in accordance with C-676 Anchor A-402 welds/structural numbers not in accordance with C-673 HBC-23-H22 configuration/welds not in accordance with H-190-H36C-2321-10 HBC-23-H26 clearances/welds not in accordance with M-190-H36C-2321-10 HBC-23-H27 configuration not in accordance with M-190-H36C-2326-9 HBC-23-H28 configuration not in accordance with M-190-H36C-2326-9 HBC-28-H8 welds not in accordance with M-190-H36C-2327-6 HBC-28-H6 welds not in accordance with M-190-H36C-2803-6 HBC-28-H6 configuration not in accordance with M-190-H36C-2804-7 HBC-28-H6 configuration not in accordance with M-190-H36C-2805-HBC-28-H9 structural number not in accordance with M-190-H36C-2807-HBC-28-H9 structural number not in accordance with M-190-H36C-2807-HBC-28-H15 welds not in accordance with M-190-36C-2809-6 HBC-28-H16 welds not in accordance with M-190-36C-2814-3 HBC-28-H16 welds not in accordance with M-190-36C-2814-3 HBC-28-H17 moved 12½" Horth HBC-23-H27 moved 12½" Horth HBC-23-H27 moved 26" West Valve F7-2 and flange on vertical run exchange position Weights of valves F 7-1, F 7-2 and F 7-3 used in analysis differ from vendor supplied weights Evaluation	1		Yes			
			1265 190						

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS Ci CHECKED OR DMC/ DESIGN SYSTEM SYSTEM COMPONENT COOLING WATER **OPERABILITY** STRESS
CALCULATION
NO.
WALPHOUS
PACKACE.
NO. UNAFFECTED IF AFFECTIVE CHCS CALC CHCS
CORRECT TO
ORIGINAL (
ANALYSIS
REQUIRED AFFECTED REFER TO REMARK NO. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES YES 20D 43 X x x Evaluation No EBC-2-H1 Configuration not in accordance with M-190-R36A-200-9 39 55A Tes I I Evaluation HBC-2-H3 Weld's not in accordance with M-190-H36A-202-7 55B 39 Support 36HBC-2-H4 moved 1'-0" east extra clamp added (not included in the analysis) Yes I Evaluation z 39 55C Evaluation x × No I MBC-27-84 Welds not in accordance with M-190-836A-2703-7 55D 39 Valve P6-5 Welded directly to elbow X X Evaluation X Yes Anchor A-095 moved 2'-8; east HBC-52-H3 moved 3'-1" south Valve B41-4 is relected beyond the 39 61D 40 42 Problem Yes X Evaluation x Anchor A-398, Welds/Structural Members not in accordance 41 61J with C-674 1-814 moved 8" down 1-817 moved 11½" South 1-818 moved 9½" South Yes Evaluation x HBC-2-H9 Structural Members not in accordance with 61F 42 M-190-F36D-208-6 HBC-2-H110 Strucutral Number not in accordance with R-190-H36D-209-8 Anchor A-106 configuration not in accordance with C-854 Extre Henger UH-1 located next to Anchor A-116 Weight of Values B39-1,2,3,4 and F3-1, 2 of 3 used in the analysis differs from wonder supplied weight Evaluation Yes X I 1265 191

PAGE

OF_62

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

PAGE

DATE 9/20/7

CHECKED C OR BMC/ SYSTEM DESIGN SYSTEM COMPONENT COOLING WATER **OPERABILITY** OK AS 15 OF CALC CHGS CORRECT TO ORDERINAL DIAMALYSIS REQUIRED IF AFFECTION STRESS CALCULATION NO. NALKDOWN PACKAGE NO. AFFECTED REFER TO REMARK DISCREPANCIES NO. NO YES IF YES, DESCRIPTION OF DISCREPANCIES Anchor A-399 Welds/Structurel Members not in accordance with C-672 61K 41 EDC-1-87 Configuration/Structural Number not is accordance with M-190-8360-106-5 HBC-1-H20 Configuration/Structural Number not in accordance with M-190-H36C-119-4 HBC-1-H21 Configuration/Structural Mamber/Weld not in accordance with M-190-H36C-120-3 1-823 moved 1'-24" South 1-821 moved 84" North-West Yes Evaluation X Anchor A-400 Welds/Structural Member not in accordance with C-675 61L 41 EBC-1-E25 Structural Members not in accordance with M-190-836C-124-3 EBC-1-E26 Structural Members Welds not in accordance with H-190-H36C-125A-7 1-E25 moved 9" down 1-E26 moved 11 5/16" North-East Yes X Evaluation HBC-28-H11 Welds not in accordance with M-190-H36C-2810-4 61T 41 Weight of the walve B81-2 used in the analysis differs from wendor supplied weight Tes I Evaluation 61V 41 Valve B81-1 Orientation not in accordance with M-236C Weight of the valve B81-1 used in the analysis differs from wendor supplied weight Yes X Evaluation I HBC-80-H1 Configuration not in accordance with M-190-H36C-8000-6 61W 41 Yes I Evaluation 83L Anchor A379 Structure! Member not in accordance with C-866 1. 27-R34 moved 2'-0 3/4" Southeast 2. A375 moved 1'-0 7/8" East 3. A 379 moved 1'-0 7/8" East x x Evaluation 700 1265 192

DATE 19/5/79 IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS DATE ANIBA CHECKED TO DESIGN SYSTEM OK AS 15 OR DWG/ CALC CHCS REQD CONRECT TO ORIGINAL DESIGN SYSTEM COMPONENT COOLING WATER OPERABILITY MAFFECTED IF AFFECTIVE STRESS CALCULATION ANALYSIS REQUIRED REFER TO KINNIN PACKACE. RE" LARK NO. DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES YES EBC-26-E5 Welds/Structural not in accordance with BJA 44 M-190-H36H-2604-5 EBC-26-86 Welds not in accordance with M-190-8368-2605-8 EBC-26-H7 Welds not in accordance with N-190-E36R-2606-4 EBC-26-88 Welds not in accordance with M-190-836H-2607-6 EBC-26-E9 Welds not in accordance with M-190-E36H-2608-5 EBC-26-H10 Welds not in accordance with M-190-H36R-2609-4 EBC-26-R15 Welds not in accordance with H-190-E36R-2614-7 Extra Support E'A" located next to anchors A87, A88, A89, A90 26-E14 moved 3'-11k morthwest The correct location of the Seismic joint between areas 6 6 7 meed to be considered in analysis Yes Evaluation T EDC-26-H20 Welds not in accordance with M-190-E36H-2619-3 83R EDC-26-E21 Welds not in accordance with N-190-E36E-2620-3 ERC-26-E22 Welds not in accordance with H-190-E36H-2621-3 HBC-26-H24 Welds not in accordance with M-190-H36H-2623-4 HBC-26-H23 Welds not in accordance with N-190-H36H-2622-4 EMC-26-H28 Welds not in accordance with M-190-H36H-2627-5 4376 moved 1'-1 7/8" West The correct locations of the Seismic joint between areas 6 & 7 need to be considered in analysis Yes X Evaluation X HBC-27-H9 Welds not in accordance with N-190-H36H-2708-4 83C EBC-27-E10 Welds not in accordance with M-190-E36H-2709-3 EBC-27-H11 Welds/clearance not in accordance with H-190-H36H-2710-3 EBC-27-E12 Welds not in accordance with M-190-E36H-2711-2 EBC-27-E14 Welds, clearances/structural members not in accordance with M-190-H36H-2713-3 ESC-27-E15 Welds not in accordance with M-190-E36H-2714-5 HBC-26-H16 extra support exists in the field EBC-27-E17 Welds not in accordance with H-190-E36H-2716-4 27-E16 moved 1'-3 1/16" Southeast 27-58 moved 1'-0 1/16" Southeast The correct location of the Seismic Joint between areas 6 & 7 meed to be considered in the analysis Tes x Evaluation x 1265 193

PAGE 29

OF_62

OF INSPITION RESULTS OF CHILD DATE TO 19 39

URIGINAL			SYSTEM_ COMPONENT COOLING WATER	E DUC/	SIGN		SYSTEM OPERABILITY		
MO, WALKDOWN PACKACE NO.			DISCREPANCIES	OK AS IS ON DWG.	CORRECT TO ORIGINAL DESIGN	ANALYSIS	UNAFFECTED	REFER	IF AFFECT REFER TO REMARK NO.
S S S S S S S S S S S S S S S S S S S	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	55					
83D 44		TI	WEC-27-E23 Welds not in accordance with N-190-E36E-2722-3				1		
630			EBC-24-E24 Helds/clearance not in accordance with						
			M-190-H36H-2723-3 WEC-27-E26 Welds not in accordance with M-190-E36H-2725-4					13	
			EBC-27-E.7 Welds/added weight not in accordance with						
			M-190-E36H-2726-3 EBC-27-E26 Welds not in accordance with M-190-E36H-2727-6		1				- 10
			MBC-27-E29 Configuration not in accordance with	1					
			M-190-E36H-2728-6 EBC-27-H30 Welds not in accordance with M-190-E36H-2729-5						
			EBC-27-H30 Weids not in accordance with H-190-B308-2/179-3						1
1		1	M-190-E36H-2731-3 Extra Support H "B" located maxt to EBC-27-E22						
			The connect location of the Seismic Joint between areas						
			6 & 7 need be considered in the analysis						
		x	Evaluati on		L	Yes	x		
83F 44			IBC-26-B40 Welds/direction of support act in accordance						
			with M-190-H36H-2639-4 MBC-26-B41 Welds/direction of support not in accordance						
			with M-190-E36H-2640-3						10
			Anchor A376 Structural Number not in accordance with C-866	1		١.			
		x	Evaluation	\perp	\perp	Yes	x		
837 44	.		EEC-27-E50 Weld/direction of support not in accordance with M-190-E36E-2749-3						
			HBC-27-H55 Configuration not in accordance with					1	
			Anchor A377 Structural Homber not in accordance with C-866						
		x	Eveluation			Yes	x		
	1			+	+	+	\dagger	+	1
83G 4	4		A-374 moved 13" East				-	1	
1	i	x	Evaluation			Yes	X		
83H 4			27H36 moved 1'-6" South		T				
63R			A-375 moved 1'-0 7/8" East Support 36-HBC-27-B47 spans the joint between areas 6 & 9						
		2	Svaluation	\perp	1		X	1	
63K 44	4		Anchor 378 Structural Member Not in accordance with C-866 26-E32 moved 2'=0 3/4" Southeast						
			A374 moved 13" East A378 moved 15" East						
		x	Evaluation			To	×		
			1265 194	1.		1	-		

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED C SYSTEM OK AS IS OR DAG, TO DESIGN SYSTEM SERVICE WATER OPERABILITY STRESS CALCULATION NO. WALKINGUE PACKACI. NO. DRAFECTED IF AFFECTI CORRECT TO ANALYSIS REQUIRED AFFECTED REFER TO REMARK DISCREPANCIES NO. YES IF YES, DESCRIPTION OF DISCREPANCIES NO 51 Extra Hanger "HA" located between EDD-96-N4 & EBD-96-H5 51 Manger EBD-96-H4 sketch calls for weld all-around, but welded at 2 of 4 sides. EBC-34-841 moved 14 11/16" southwest along pipe Anchor A137 inaccessible Weight of the valves E -14 and E3-15 used in the seismic analysis differs from wendor supplied weight. X X Evaluation Yes Weight of the valves PSV-3962 and 51B 51 PSV-3963 in the seismic analysis differs from wender supplied wight. Tes x Evaluation X 1104 55 BBC-37-B27 Welds not in accordance with M-190-B411-3726-2 HBC-37-E34 Structural Member pr in accordance with M-190-H41L-3733-4 RBC-37-H35 Welds not in accordance with M-190-B411-3734-2 HBC-37-H36 Structural Homber not in accordance with H-190-B41L-3735-4 HBC-37-H37 Welds not in accordance with H-190-H41L-3736-6 HBC-37-B40 Structural Members not in accordance with H-190-B411-3739-4 HBC-37-H42 Welds not in accordance with H-190-H41L-3741-3 HBC-37-B43 Welds not in accordance with M-190-B41L-3742-4 37-246 moved 1'-4" N. 37-H36 moved 1'-7" S. 37-845 moved 1'-4 3/4" SE. 41 EBC-37 E39 Inaccessible x Evaluation x 63B 53 41-EBC-42-E2 moved 18" East Weights of following valves used in analysis differs from endor supplied weight: P4-9,P4-10, P4-11, P6-7, P6-8, P6-9, P6-10, TV1429, TV1434 I Yes X Weight of the following valves used in analysis differs from vendor supplied weight: Fl1-7, Fl1-9, Fl1-11, Fl1-12, Fl1-13, Fl1-14, TV-1356, TV-1357 and TV-1358 63C 53 I Evaluation Yes 1265 195

PAGE 31

DF 62

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED SYSTEM CHCS REGO TC VESTON SERVICE WATER SYSTEM OPERABILITY UNAFFECTED STRESS CALCULATION NO. WALKFORY PACKAGE NO. IF AFFECT! OR AS 19 CALC CHGS CORRECT TO ORIGINAL ANALYSIS REQUIRED AFFECTED GEFER TO REMARK NO. DISCREPANCIES IF YE', DESCRIPTION OF PISCREPANCIES YES Support NBC-45 A7 Not welded in accordance with N-190-R41M-4906-3 34A 4 Support MBC-45-El/ not welded in accordance with the sketch. Support MBC-45-H13 not welded in accordance with M-190-N41H-4512-3 Valve B86-3 orientatics not in accordance with M-241A Valve B86-4 orientation not in accordance with M-241H HBC-45-H3 moved 1'5" East HBC-45-H11 moved 14" East RBC-45-H13 moved 15" West MBC-45-R14 moved 3'-6" Down HBC-45-H9 moved 14" South Weight of the valve B12-1 used in the analysis differs from the vendor supplied weight X Evaluation Yes x HBC-45-H20 welds not in accordance with M-190-B41H-4519-4 EBC-45-H26 weld not in accordance with H-190-H41H-4525-3 HBC-45-H27 welds not in accordance with M-190-H-18-4526-6 HBC-45-H32 configuration not in accordance with H-190-H41H-4531-5 HBC-45-834 welds not in accordance with N-190-B41H-4533-6 HBC-45-H37 welds not in accordance with M-190-H41H-4536-9 EBC-45-H23 moved 2'-6" South HBC-45-H29 moved 1'6" Bast RBC-45-H31 moved 23" South Evaluation HBC-45-B41 Welds not in accordance with M-190-B41E-4540-5 84C 54 Valve B12-1 orientation must in accordance with 3"-HBC-45 H-241H Valve B86-18 orientation not in accordance with 3"-HBC-45 HBC-45-H39 moved 12t" South HBC-45-H41 moved 16" South X Evaluation EBC-37-E16 Welds not in accordance with N-190-B41D-3715-4 63A EBC-45-82 moved 14" Borth Yes x Evaluation X POOR ORIGINAL 1265 196

PAGE 32 OF 62 By hay & MATE 19/3/24

				IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS		L	C	7		DATE 19/3/2
				SYSTEM SERVICE WATER	The same of			SI	YSTE	THE RESERVE TO SERVE THE PARTY.
ALCULATION 10.	PACKAGE NO.			DISCREPANCIES	OR AS IS ON DWC/	CORRECT TO ORIGINAL DESTON	ANALYSTS REQUIRED	UNAFFECTED	AFFECTED	IF AFFECT REFER TO REMARK NO.
3 5	PAC.	NO.	I.		5 5	88	NE NE	20	2	
		NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	1			ī		
•0	50 53 56			#EDC-36-#7 Elevation/Configuration not in accordance with M-190-H507-3606-5 #EDC-36-H11 moved 3'-1 7/16" Hortheast #EC-36-H10 moved 2'-1 7/16" Hortheast #EDC-36-H9 moved 3'-0 3/4" Hortheast #EDC-36-H2 moved 3'-0 3/4" Hortheast #EDC-36-H2 moved 2'-1" East #EDC-36-H2 moved 4'-5" East 41-HBC-36-H26 moved 7'-9" West Anchor A145 moved 1 3/4" East						,
				41-EBC-36-E12 moved 19" South			ee Yee	x		
84D	54			EBC-44-E5 Clearance not in accordance with M-190-E41H-4404-8 EBC-44-E50 Welds not in accordance with M-190-E41H-4404-2 EBC-44-E50 moved 16" Seath EBC-44-E50 moved 1"-3" South \$1-EBC-44-E17 DB Support added not analyzed on old problem						
			1	Evaluation			Tes	x		
841	34			EBC-44-H22 Welds not in accordance with H-790-B-12-421-5 EBC-44-H28 Configuration not in accordance with H-190-B-1R-4427-6 EBC-44-H30 Welds not in accordance with H-190-B-1R-4429-3 EBC-44-H20 moved around corner 2'-6" north (8\frac{1}{2}" east) EBC-44-H21 moved around corner 2'-6" north (8\frac{1}{2}" east) EBC-44-H28 moved 21" Borth EBC-44-H29 moved 21" Borth EBC-44-H30 moved 2'-7" East EBC-44-H31 moved 2'-7" East	and New York Control of the Control					
				Exclusion			 Tes	x		
647	54			EBC-44-E36 Welds not in accordance with M-190-E41E-4436-8 EBC-44-E40 Welds not in accordance with M-190-E41E-4436-8 EBC-44-E40 Welds not in accordance with M-190-E41E-4439-4 EBC-44-E36 moved 1'-10" West EBC-44-E36 moved 15" East EBC-44-E37 moved 15" East EBC-44-E30 moved 15" East EBC-44-E40 moved down 14"						
-	-	+	*	Evaluation	+	+		x	+	
				POOR ORIGINAL						
		1		1265 197	1.		1		-	

POOR	NR	ıcı	N	11	TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	-	ECKET	ACCRECATE AND ADDRESS OF		DATE 10/13/29
1 UUN	U	liui	11/	ıL	SYSTEM_ BERVICE WATER	R DUC/	ESIGN			TFH RABILITY
	STRESS CALCULATION NO.	CKAGE.			DISCREPANCIES	OK AS IS ON ISHO!	CORRECT TO ORIGINAL DESIGN	ANALYSIS REQUIRED	UNAFFECTED	REFER TO REMARY NO.
	22 5	2 2	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	-			+	+-
	52A	58	1		Evaluation	1		No	x	-
	52C	58			EBC-34-H23 Configuration not in accordance with H-190-E50F-3422-5 Evaluation			· To:	x	
	37A	52		1	42-EBC-43-E2 moved 22" down 41-EBC-43-E3 moved 9'-6" South Anchor A-138 moved 31" East Evaluation			,::	x	
	378	52			Penetration P-3 not shown on M-241C Penetration P-5 not shown on M-241C Aschor A-139 moved 48" West 41-EBC-43-E5 moved 22" down Evaluation			er Yer	x	*
	370	52		x	Penetration P-4 not shown on M-241C 41-HBC-43-H12 moved 21" North 41-HBC-43-H8 moved 14" down			***	. x	
	372	31 34			Penetration P-1 not shown on M-241C Extra Support UH-1 located next to EBC-44-B4 EEC-35-H17 Welds not in accordance with M-190-B41C-3516-8 Anchor A-142 moved 22" East 41-HBC-35-H24 moved 20" South			70		
	-			-						
					1265 198		-		-	

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS TO TO SYSTEM OK AS IS ON INC. SYSTEM SERVICE WATER OPERABILITY STRUSS CALCULATION NO. WALKGOON PACKACK. NO. UNAFFECTED IF AFFECTE CORRECT TO ANALYSIS REFER TO DISCREPANCIES NO. YES IF YES, DESCRIPTION OF DISCREPANCIES 37F 92 Weights of the following valves used in analysis differ from rendor supplied weights: 711-1, 2, 3, 4, 5 and 6 x Evaluation Yes X 37D Penetration P-2 mot shown on H-241C 52 41-TBC-35-E10 moved 19" South 41-RBC-35-Eli moved 34" Around corner, W & N (axia! - lateral) Anchor A-141 moved 22" Bast 41-HBC-35-H7 moved 20 3/4" South Tes I Evaluation ï No discrepancies X Evaluation × X 52B Hanger missing on the horizontal run Weights of walves F2-1, F2-2, F2-3, F2-4, F4-7 and F4-8 differ from vendor supplied weights x Evaluation Yes X POOR ORIGINAL 1265 199

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

DY CLAST OF 62

BY CLAST ON 62

DATE 9/30/79

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	a	ECKET	Cin	_	_	MTE 9/20/7
				SYSTEM SUMP PUMP DISCHARGE	EQ0	SIGN			STE	
CALCUATION	WALKINGS PACKACE. NO.				CALC CHGS REQU	CORRECT TO ORIGINAL DESIGN	ANALYSIS REQUIRED	UNAFFECTED	AFECTED	IF AFFECT REFER TO REMARK NO.
CALCL.	PAC.	-	T I		8 5	9 8	REG	2	15	NO.
	-	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES						
96.4	57			BC-145-E36 Welds not in accord with N-190-B468-14535-4 BC-145-H37 Clearances not in accordance with N-190-B468-14536-4 Additional loads extached BC-145-E39 Structural Numbers not in accordance with N-190-B468-14538-3 BC-145-B46 Welds not in accordance with N-190-B468-14545-4						;
				Evaluation			Yes	x		
96C	57		1	ESC-155-E10 Welds not in accordance with M-190-E46B-15509-1 ESC-155-E11Welds not in accordance with M-190-E46B-15510-2 EC-145-E4 moved 1'-6 7/8" morth ESC-155-E12 moved up 1'-24" Eveluation			** .	x		
∞	57		x	ESC-145-E16 Welds not in accordance with H-190-E46E-14515-6 ESC-145-E19 Welds not in accordance with H-190-E46E-14518-3 ESC-145-E21 Welds not in accordance with H-190-E46E-14520-1 Evaluation			Ťe.	x		
96E	57			Extra Hanger located between ESC-155-E3 and ESC-155-E4 Anchor A355 has moved to horizontal pipe from vertical position (2½" ESC-155). 8" from elbow toward north ESC-155-E3 moved 3'-5" east Anchor A-356 moved 2'-3" west			Yes	x		
967	57			EC-155-E9 Configuration not in accordance with M-190-E468-14506 EC-155-E16 Welds not in accordance with M-190-E468-15515-2 Anchor A356 moved 2'-3" west Pipe routing changed-elbows added-used to be 28'-5" @ E1. 561'-3" now 23'-6" @ E1. 561'-3" & 5'-0" @ 559'-3" EC-155-E18 moved 1'-6" west ESC-155-E19 previously only banger support-now rigid x support added Anchor A357 moved up 3'-7%" Evaluation	5		Ť.	x		
				POOR ORIGINAL		1		-	-	

			SYSTEM_SING FING DISCHARGE		EQ0	SIGN		SY	ERAI	BILITY
CALCULATION NO. UAIXOCCI PACCOCE NO.			DISCREPANCIES		CALC CHCS REQU	CORRECT TO ORIGINAL DESIGN	AKALTSIS	UNAFFECTED	AFT SCTED	IF AFFE REFER T REMARK NO.
WAL WAL	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES		80	0.6	22	5	-	
168 37 77		x	Extra Hanger H "F" located between ESC-32-H16 and SExtra Hanger H "F" located next to EBC-32-H16 Extra Hanger H "F" located next to EBC-32-H14 Hanger HSC-145-H49 moved 1'-2 5/8" South 35-RSC-32-H15 moved 14" East		-3		** ***	x		
			1265 20	1						

BY bash DATE 10/1/29 TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED CAL OK AS IS OR DAG/ CALC CHCS REQD CORRECT TO ORIGINAL DESIGN ANALTSIS REQUINED SYSTEM SYSTEM DERGENCY DIESEL GENERATOR OPERABILITY IF AFFECTED AFFECTED CALCULATE MO. WALEDOWN PACKAGE. NO. REFER TO REMARK NO. DISCREPANCIES TES IF TES, DESCRIPTION OF DISCREPANCIES EBC-53-E5 Welds not in accordance with M-190-E62C-534-2 122A 59 EBC-53-86 Welds/Structural Mambers not in accordance with M-190-862C-535-2 EDC-53-E7 Welds not in accordance with H-190-M62C-536-2 ESC-53-E9 Welds not in accordance with H-190-M62C-5308-" BC-53-E10 Welds not in accordance with M-190-B62C-539-2 MDD-183-H7 Welds not shown on M-190-M62C-1836-1 EBC-53-E1 moved 1'-6" South TBC-53-E2 moved 1'-6" Bast Evaluation 1 60 123A No Manger Problem Evaluation x I 123B 60 HBD-359-H2 Weld not in necordance with H-190-H268D-35901-4 HBD-359-H10 Weld not in accordance with M-190-H268D-35909-4 EBD-359-H2 moved ? 3/4" Mortheast EBD-359-k14 moved 1'-1 3/4" West HBD-359-H8 moved up 7 7/8" x Tes Eveluation x 1265 202

PACE_ 35 OF_ 62

PACE_39 07_62 By half L DATE 9/20/20

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	_ 0	RECKE	ou.	7.		DATE 9/20/1
E T		7		SYSTEM AINTILIAN STEAM	002M	ESIGN		OP	ERA	BILITY
STRESS CALCULATTICS NO. WALKDOWN	PACKAGE.			DISCREPANCIES	OK AS IS OR DUC/	CORRECT TO ORIGINAL DESIGN	ANALTSIS REQUIRED	UNAFECTED	AFFECTED	IF AFFECT REFER TO REHARK NO.
-		MO	YES	IF TES, DESCRIPTION OF DISCREPANCIES	-	-	-	-	-	
48 C	21		ı	GBD-12-E4 Welds not in accordance with M-190-E208-1203-3 Restraint 20 GBD-12 E6 moved 2'-11" down Bestraint 20 GBD-12 E3 moved 1'-11" north Evaluation			÷	1		;
774	22			Extra Banger located maxt to EED-37-E77 EED-44-E2 Configuration not in accordance with Grinnell SE 12-4401 EED-44-E4 Welds not in accordance with M-190-E20D-4403-2 EED-44-E11 Structural Number not in accordance with N-190-E20D-4410-3 Anchor A-238 moved 2'-0" east						
			x	Eve heation			Ŧ	x	,	
778	22		x	ERD-44-E8 Configuration not in accordance with N-190-E20D-4407-3 EBD-44-E9 additional load attached Evaluation			i.	I		
77C	22	1		Evaluation			B o	x		
772	22			EBD-86-E3 Additional Load attached Support 20 EBD86-84 moved 1'-4" east Evaluation			÷.			
777	22			The weight of the valve HV-2073 used in the analysis differs from the wundor supplied weight						
4			*	Evaluation			7	x		
774	22			Evaluation			Bo	x	1	
				1265 203						

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED CO OK AS IS OR DUG/ CALC CHCS REQU CORRECT TO ORIGINAL DESIGN SYSTEM SYSTEM AUXILIARY STEAM OPERABILITY IF AFFECTS REFER TO REMARK UNAFECTED CALCULATION NALKOON PACKAGE PACKAGE PO. ANALYSIS REQUIRED AFFECTED DISCREPARCIES MO. YES IF YES, DESCRIPTION OF DISCREPANCIES 778 22 Bestraist 20- MBD-86-H17 moved 1'-7 5/8" down 700 . Evaluation 85 24 EBD-87-820 Structural Member not in accordance with H-190-820L-8719-3 EBD-87-R21 welds not in accorance with H-190-R20L-8720-3 Extre Support H "A" located next to HBD-87-H15 87-E15 moved 1'-10" West 87-E18 moved 2'-2" Borth Evaluation Tes 948 23 Anchor A278 Configuration/dimensions not in accordance with C-889 Anchor A279 Dimensions not in accordance with C-889 HBD-46-34 Configuration not in accordance with N-190-H20G-44603-6 HBD- 5-H108 Welds not in accordance with H-190-H20G-44607-2 Support 20 EBD-46-E5 moved 1'-114" Borth 87-E29 moved 1'-3" down 87-E11 moved 2'-4" Bast I Evaluation I Tes 1265 204

or half mire 14/1/24

CALL CALL OK AS 15 OR EWG/ CALC CHGS REQD CORRECT TO ORIGINAL DESIGN SYSTEM SYSTEM CIRCULATING WATER OPERABILITY IF AFFECTED REFER TO REMARK NO. AFFECTED DISCREPANCIES YES IF YES, DESCRIPTION OF DISCREPANCIES Valve EV-2929 orientation not in accordance with M-241A 15 Valve NV-2932 orientation not in accordance with M-241A EBD-96-El welds not in accordance with H-190-H41A-9800-3 HBD-191-H1 structurel members not in accordance %5'% N-190-B41A-19100-3 MBD-194-H1 moved 35" South EED-194-84 moved 15" South HBD-98-H1 soved 24" South HBD-98-H2 moved 23" South EBD-28-HLA moved 18 3/8" Berth HBD-28-H2A moved 13" South Anchor A182 moved 3'6" Morth Aschor A371 moved 15" Morth Anchor A370 woved 15" Borth x Eveluation Yes Valve PV-2944 orientation not shown on M-21/18 59B 15 Valve PV-2945 orientation not shown on M-2128 HBD-100-H6 welds not in accordance with H-190-H128-10005-5 Yes x I Evaluation 1265 205

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

BY Lagle DATE OF 52

		,		SYSTEM FIRE PROTECTION SYSTEM	E DU	ESIG		OF	ERA	BILITY
CALCULATION FIG.	PACKAGE NO.			DISCREPANCIES	G. AS IS ON DWG CALC CHGS REQU	CORRECT TO ORIGINAL DESIGN	ANALTSIS REQUIRED	UNAFFECTED	AFFECTED	IF AFFECTI REFER TO REMARK NO.
SES	ZE	NO	YES	IF TES, DESCRIPTION OF DISCREPANCIES	30	0.6	**	•	<	
"	1,			EBE-2-H100 welds not in accordance with N-190-H16E-299-6 EBE-2-H103 welds not in accordance with N-190-H16E-A202-6 EBE-2-H104 welds not in accordance with N-190-H16E-A203-6 EBE-2-H105 weld not in accordance with N-190-H16E-A203-6 EBE-2-H107 welds not in accordance with N-190-H16E-A206-8 EBE-2-H108 welds not in accordance with N-190-H16E-A207-7 EBE-2-H108 welds not in accordance with N-190-H16E-A207-7 EBE-2-H319 welds not in accordance with N-190-H16E-A207-7 EBE-2-H319 welds not in accordance with N-190-H16E-C218-2 Hanger EBE-2 H98 missing			-			;
			1	Byalustion			Yes	1		
794	19		*	EBE-2-H236 welds and configuration not in accordance with N-190-H16E-B235-3 EBE-2-H237 welds and configuration not in accordance with M-190-H16E-B236-4 EBE-2-H238 welds and configuration not in accordance with M-190-H16E-B237-4 EBE-2-H243 plate and clearance not in accordance with M-190-H16E-B242-5 EBE-2-H244 weld not in accordance with M-190-H16E-B243-5 EBE-2-H245A weld not in accordance with M-190-H16E-B244A-6 EBE-2-H320 welds not in accordance with M-190-H16E-B244A-6 EBE-2-H320 melds not in accordance with M-190-H16E-B24A-6 EBE-2-H320 melds not in accordance with M-190-H16E-B24A-6 EBE-2-H320 melds not in accordance with M-190-H16E-B24A-6 EBE-2-H			Yes	x	*	
798	19			EBE-2-E251 welds not in accordance with N-190-E16E-B250-3 EBE-2-E255 welds not in accordance with N-190-E16E-B254-3 EBE-2-E258 plates not in accordance with Grinnell 18-B257 EBE-2-E259 welds not in accordance with N-190-E16E-B250-5 EBE-2-E260 welds not in accordance with N-190-E16E-B259-5 EBE-2-E262 dimensions not in accordance with N-190-E16E-B261-7 EBE-2-E266 dimensions not in accordance with N-190-E16E-B263-7 EBE-2-E266 welds not in accordance with N-190-E16E-B265-5 EBE-2-E268, welds not in accordance with N-190-E16E-B265-4 A361 dimensions not in accordance with M-190-E16E-B267-4 Extra Hanger UB-4 located next to Anchor A361 Extra Hanger UB-5 located next to Anchor A361 Extra Hanger UB-8 located next to Anchor A369 Valve FP-3 orientation of operator not in accordance with N-216E Beotraint 16EBE-2 not in the math model Weight of valves, FP-3 and FP-4 used in the analysis different from vandor supplied weight			1			20

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS		4	C	7	_	MTE 10/15/
*		1		SYSTEM PLUE PROTECTION SYSTEM	OR AS IS OR INC.	TO TO		01	EM	BILITY
CALCULATION NO.	WALKDOWN PACKAGE NO.				AS TS	GINAL	AWALTSTS REQUIRED	DRAFFECTED	AFFECTED	REFER TO
CALK	PAC.	NO	YES	DISCREPANCIES IF YES, DESCRIPTION OF DISCREPANCIES	8 5	98.1	NA PA	DRA	M	₩O.
CONT I 798	19		1	Envelope of areas 7 and 8 should be used in seismic analysis Evaluation			 Y	x		
790	19		1	EBE-2-H109 welds not in accordance with N-190-H16E-A208-8 EBE-2-H285 welds and configuration not in accordance with N-190-H16E-B284-3 EBE-2-H286 welds not in accordance with N-190-H16E-B285-4 EBE-2-H289 welds not in accordance with Grinnell 18-B288 EBE-2-H290 welds/dimensions not in accordance with N-190-H16E-B289-4 Extra hanger DH-1 located next to EBE-2-H109 Extra hanger DH-2 located next to EBE-2-H109 Extra hanger UH-2 located next to ECS-29 16-EBE-2-H289 moved 124" North Extra Hanger UH-3 (SA) @ Elbow Anchor between 79 & 79C is built @ blockwell not accessible Weight of the Valve FF-4 used in analysis differs from wendor repplied weight				x	-	
87A	18		1	Anchor A-414 Structural Number not in accordance with C-670 Anchor A-415 Structural Number not in accordance with C-670 IRE-2-E218 Configuration not in accordance with N-190-E16D-E217-3 IRE-2-E223 Welds not in accordance with N-190-E16D-E222-3 Extra Support E "A" located next to ERE-2-E217 Anchor A-413 moved 31 3/4" East Weight of the walve F7-245 meed in the analysis differs from wender supplied weight Support IRE-2-E214 spans areas 7 & 6						
				POOR ORIGINAL						

POOR ORIGINAL

TE BULLETIN 79-14 DESCRIPTION OF INSTITUTE RESULTS

DATE 10/13/29

CRECKED CALL DA

111	lull	IN	-	SYSTEM PILE PROTECTION SYSTEM	STOP OF	T TO UL DESIGN		01		BILITY
LCULATION	WALKDOWN . ACKAGE			DISCREPANCIES	ME AS IS ON	MIGINAL D	ANALTSIS REQUIRED	U PECTED	CTED	IF AFFECT REFER TO WHARK NO.
531	3.8	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	100	00		-		
873	10		*	EEE-2-E229 Structural Number not in accordance with H-190-E16D-E228-3 EEE-2-E23 Welds not in accordance with N-190-E16D-E238-3 EEE-2-E248A Configuration not in accordance with N-190-E16D-E247A-3 EEE-2-E315 Welds not in accordance with N-190-E16D-C214-2 Extra Support E "I" located next to EEE-2-E229 Extra Support E "I" located between EEE-2-E230 and EEE-2-E314 Extra Support E "E" located between EEE-2-E230 and EEE-2-E314 Extra Support E "L" located next to EEE-2-E248A Weight of valve FP-3 used in the Seismic analysis differs from wender supplied weight. Svaluation		K.	Tes	x		
870	18		x	Anchor A-318 location not in accordance with C-651 ERE-2-E173 Welds not in accordance with M-190-E16D-A272-6 ERE-2-H177 Structural Mumber not in accordance with M-190-E16D-A276-2 ERE-2-H180 Configuration/Welds not in accordance with M-190-E16D-A279-3 Extra Support E "F" located next to ERE-2-E180 Extra Support E "G" located next to Anchor A-318 Extra Support E "H" located next to Anchor A-315 Valve FF-6 "A" Orien:ation not in accordance with M-216D 16"ERE-2-E176 moved North 154" 16"ERE-2-E321 Eanger dwg. is missing Weight of the walve FF-4 used in analysis differs from wender supplied weight.			Tes			
870	16			EBE-2-E191 Structural Mamber not in accordance with M-190-E16D-290-5 EBE-2-E192 Welds not in accordance with M-190-E16D-291-4 EBE-2-E193 Welds not in accordance with M-190-E16D-292-5 EBE-2-E194 Welds not in accordance with M-190-E16D-293-6 EBE-2-E203 Welds not in accordance with M-190-E16D-293-4 EBE-2-E207 Welds not in accordance with M-190-E16D-B205-5 EBE-2-E208 Welds not in accordance with M-190-E16D-B206-5 COntinued						

BY LAR MIE 10/18/19

SYSTEM
OPERABILITY

IP AFFECTED

TO

				SYSTEM FIRE PROTECTION SYSTEM	NE QD	T TO TESTON	7, 3		STE ERA	M BILITY
ULATION	DOWN				AS IS OR	CORR S.T TO	0.320	FECTED	VPECTED	IP AFFECT
E3 :	WALKDOW PACKACE NO.	-			CALC C	800	ARAL	UNA	M	NO.
00nt. 870	18	100	YES	Extra Support E "D" located mext to EBE-2-H196 Extra Support E "C" located mext to Anchor A-243 Extra Support E "D" located mext to EBE-2-H210 Extra Support E "E" located res to EBE-2-H211		*				,
			x	16-ERE-2-E146 moved 13' Cal 26-ERE-2-E213 moved 15" Sast 16"ERE-2-E207 moved 25 3/4" North 16-ERE-2-E194 moved 16 3/4" South Evaluation				x		
82G	17	T		No Discrepancies						
			x	Rvaluation	x		Bo	x	,	
820	17			ERE-2-E140 configuration not in accordance with Grinnell SK 18-4239 ERE-2-E144 configuration not in accordance with M-190-E15C-A243-EBE-2-E145 configuration not in accordance with M-190-E15C-A244-EBE-2-E146 structural member not in accordance with M-190-E16C-A246-4 ERE-2-E148 welds not in accordance with M-190-E16C-A247-4 ERE-2-E158 configuration not in accordance with M-190-E16C-A257-/ ERE-2-H159A and B c-nfiguration mot in accordance with M-190-E16C-A258-4 ERE-2-E162 configuration/welds not in accordance with M-190-E16C-A261-4 ERE-2-E163 structural member not in accordance with M-190-E16C-A262-2 ERE-2-E169 structural member not in accordance with M-190-H16C-A268-5 Valve FP-6F orientation not in accordance with M-216C Extra support H "B" located next to ERE-2-E141 Extra support H "B" located next to ERE-2-E166 Extra support H "C" located next to ERE-2-E166 Extra support H "F" located next to ERE-2-E166						

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS CHECKED CAL OR AS IS OR DUC/ CALC CHCS NEGO CORNECT TO ORIGINAL DESIGN SYSTEM SYSTEM FIRE PROTECTION SYSTEM OPERABILITY STRESS CALCULATION NO. WALKINGAN PACKACE NO. IF AFFECT ANALTSIS MAFFECTE REFER TO REMARK DISCREPANCIES NO. TES IF YES, DESCRIPTION OF DISCREPANCIES NO Valve FF-1 Orientation not in accordance with M-21of, rotated 30° East 118A 20 Extra Support ERE-3-82 is installed Extra Support ERE-16-E14 is installed Extra Support EBE-16-E15 to installed The weight of the valve FP-47 used in the analysis differs from the wendor supplied weight I Evaluation Yes 7P "A" type and operator orientation not specified (actual orientation shown) 82A 17 ERE-2-E305 welds not in accordance with H-190-E16C-C204-1 ERE-2-H309 welds not in accordance with H-190-H16C-C208-3 Hanger 309 moved 15" North x Evaluation Yes ERE-1-H2 welds not in accordance with M-190-H16C-101-2 82B 17 ERE-1-H3 welds not in accordance with H-190-H16C-102-2 EBE-1-84 configuration not in accordance with H-190-H160C-103-2 EBE-1-E7 configuration not in accordance with 9-190-816C-106-2 Extre hanger # "E" located next to anchor #34 Anchor A434 moved from North-South run pipe to East-West run pipe Restraint 16-EBE-1 E9 has extre +Y 16ERE-1-H8 moved 8'-5" Morth 7 Evaluation Yes 82D 17 KBE-2-R291 structural member not in accordance with H-190-H16C-B290-4 KBE-2-H292 configuration/type not in accordance with N190-H16C-B291-2 EBE-2-H300 welds not in accordance with M-190-H16C-B299-4 ERE-2-8296 configuration not in accordance with M-190-816C-8295-6 2-H-59 added 20" South 2-H-296 added 19" Borth x Evaluation Yes BZE 17 I Tvaluation I 1265 210

=

PACE_47 NF 42

BY Land LL DATE 10 13 79

CHECKED CALL DATE 10 13 79

				IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	15		2012	C	_		DATE 10/13/7
STRESS CALCULATION NO.	MALKDOWN PACKAGE NO.	1		DISCREPANCIES	AS IS OR DA	CALC CHGS REQU	CORRECT TO ORIGINAL DESIGN	AMALYSIS REQUIRED		ZRA	IF AFFECTS REFER TO REMARK NO.
2 5	PAC.	WO.	1	IF TES, DESCRIPTION OF DISCREPANCIES	- 8	3	88	35	25	5	
\$2C XXXI'E	17		YES	2-E167 moved 2'-4' Horth A434 moved from Borth-South run to East-West run 2-E163 moved 16' Horth Weight of the valve FP-6 meed in emalysis differs from vendor supplied weight Evaluation				Yes	x		:
82F	17		1	FF-6B operator orientation not per design Extra supports UE7 and UE8 provided in the piping Weight of the valve FF4 used in the anlaysis differs from vendor supplied weight Envelope of areas 7 and 8 should be used in analysis Support 16KBE-2-E55 spans areas 7 and 8 Evaluation				 Yes	x		
				1265 211							

:

POOR ORIGINAL

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS Cu CHECKED OK AS 15 OR DAG/ CALC CHGS REGO CORRECT TO ORIGINAL DESIGN TO TO SYSTEM SYSTEM MAKEUP WATER TREATHENT OFERABILITY. UNAFFECTED STRESS CALCULATIONS NO. NALKROWN PACKACE NO. IF AFFECT AKALTSIS REQUIRED REFER TEMAPE REFER TO DISCREPANCIES YES IF YES, DESCRIPTION OF DISCREPANCIES MC-23-El Welds/Confirguration not in accordance with M-190-El0E-2300-3 102A 12 MC8-23-E2 Configuration not in accordance with M-190-E10E-2301-5 BCB-23-84 Structural Members not in accordance with M-190-E10E-2303-3 BCB-23-86 Configuration not in accordance with M-190-E10E-2305-4 Envelope of areas 8 and 9 should be used in analysis Evaluation T.. 1 102B 13 Anchor A185 Configuration not in agreement with C-883 BCD-4-E73 Welds not in accordance with M-190-E109-472-3 BCD-4-E53 Structural Member not in accordance with M-190-H107-452-4 Extre Support No. 2 located next to MCD-4-H53 Extra Support No. 3 located between MCD-4-M50 and MCD-4-M51 Extra Support No. 4 located next to MCD-4-847 Extra Support No. 5 located next to BCD-4-855 Extra Support No. 6 located next to MCD-4-H57 Extra Support No. 7 located mext to BCD-4-860 Extra Support No. 8 located mext to MCD-4-H61 Extra Support No. 9 located next to BCD-4-R63 Extra Support No. 10 located between MCD-4-M69 and MCD-4-M70 Extra Support No. 11 located mext to BCD-4-H78 Extra Support No. 12 located between MCD-4-M80 and MCD-4-M81 Extra Support No. 33 located part to ECD-4-862 Extra Support No. 14 located between BCD-4-H73 and BCD-4-H75 inchor A-168 meres 3'-1" to Bast 10r BCD-4-8-76 moved 1'-1" to West 105 ECT-4-E-62 moved 13" to Borth TSE (E-3) moved 1'-3" to South 105 ECD-4-E-59 moved 1'-6" to East BCD-4-H61 Spans Seismic Joint I Evaluation *** X 1020 12 Anchor A389 Configuration not in ag coment with C-897 Anchor A183 Configuration not in agreement with C877 BCD-4-H39 Structural Member , not in agreement with H-190-E10E-438-3 BCD-4-B41 Welds/Configuration not in agreement with M-127-E10E-440-4 Valve A143-1 Orientation not in agreement with H-210E Envelope of Areas 8 and 9 should be used in the analysis Yes I Evaluation

ECC-50-E35 Welds not in accordance with H-190-E-3:-5034-5
ECC-50-E36 Welds not in accordance with H-190-E10C-5035-4
ECC-50-E37 Welds not in accordance with H-190-E10C-5036-7
ECC-50-E39 Welds not in accordance with H-190-E10C-5038-5
ECC-50-E40 Structural Numbers not in accordance with H-190-E10C-5039-5
ECC-50-E40 Structural Numbers not in accordance with H-190-E10C-5039-5
ECC-50-E42 Welds not in accordance with H-190-E10C-5041-6
ECC-50-E43 Welds not in accordance with H-190-E10C-5042-5
Extra Eanger UE-1 located next to ECC-50-E9
Extra Eanger UE-2 located between ECC-50-E10 and ECC-50-E11
Extra Eanger UE-3 located between ECC-50-E11 and ECC-50-E12
Extra Eanger UE-5 located next to ECC-50-E20
Extra Eanger UE-6 located next to ECC-50-E31

1265 213

POOR ORIGINAL

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

PAGE

or has he

OF_62

BATE 9/0/2/

CHECKED CA OR ENG! TO DESIGN SYSTEM SYSTEM MAKEUP WATER TREATMENT OPERABILITY STRESS CALCULATION NO. WAYENDES PACKACE NO. CALC CHCS CORRECT TO CORRECT TO IF AFFECTED ANALTSES REQUIRED UNAPPECTE AFFECTED REFER TO REMARK DISCREPANCIES NO. MO TES IF TES, DESCRIPTION OF DISCREPANCIES Extra Manger UH-7 located between BCC-50-843 and BCC-50-844 10 102F Cont Extr. Hanger UH-8 located between BCC-50-847 and Anchor A384 BOC-50-29 moved 1'-6 5/8" West BCC-50-E10 moved 1'-8 3/8" West BCC-50-H13 moved 2'-9" South MCC-50-E18 moved 1'-7 3/4" up ECC-50-E21 moved 1'-7 7/8" East ECC-50-E30 moved 13" East ECC-50-E33 is missing ECC-50-B42 moved 12 7/8 Borth ECC-50-B43 moved 14 1/8" South HCC-50-H44 moved 12' Morth HCC-50-H45 moved 2'-2' Morth HCC-50-H46 moved 2'-2 1/8" West Support BCC-50-E21 Spans Seismic Joint I Evaluation Tes 102F 10 I Evaluation I Bo x 1020 Anchor 4423 Configuration/Structural Numbers not in accordance with C-831 11 Anchor AA24 Structural Numbers not in accordance with C-837 HCC-51-H102 Welds not in accordance with M-190-H10D-A5101-2 MCC-51-H103 Welds not in accordance with M-190-H100-A5102-2 BCC-51-H104 Welds not in accordance with N-190-H10D-A5103-3 108 BCC-51-8103 moved 1'-2 1/8" to West Anchor A424 moved 2'-34" to Borth-West I Evaluatir, Yes I 102H 11 BCC-69-M104 Welds not in accordance with M-190-M10D-A6903-2 MCC-69-M105 Welds not in accordance with N-190-M10D-A6904-3 Extra Hanger UH-1 located mext to BCC-69-H101 108-BCC-69-E102 moved 1'-1" to West 108-BCC-69-H104 moved 1'-0 3/4" to South Anchor A-426 moved 1'-4 5/8" to Borth-West Eve lustion . 1021 12 schor AA27 Structural Members a * in accordance with C-657 MCC-40-M103 Configuration not in accordance with M-190-M10E-44002-1 Anchor A-428 moved 1'-64 Morth-West Evaluation Tee .

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS OK AS IS OR DUG/ CALC CHES REGO CORRECT TO ORIGINAL DESIGN SYSTEM SYSTEM MALEUP WATER TREATMENT OPERABILITY IF AFFECTE APPECTED STRESS CALCULATTO NO. WALKFORM PACKAGE NO. REFER TO REMARK NO. DISCREPANCIES YES IF TES, DESCRIPTION OF DISCREPANCIES Anchor A430 Structural Member set is accordance with C-837 102J 13 Extra Support So. 1 located between BCC-53-E101 and Anchor 4429 108-ECC-53-E104 moved 1'-4" down Anchor A430 moved 1'-11" Borth-West Tes Evaluation I 108 ECC-53-E-111 moved 1'-11" to West 108 ECC-53-E-112 moved 1'-1" to East 108 ECC-53-E-116 moved 1'-0 1/8" to East 108 ECC-53-E-126 moved 2'-2 9/16" Morth-East 102K 13 BCC-53-E115 Spane Seismic Joint Envelope of Areas 7,8, & 9 meed be considered I Evaluation I POOR ORIGINAL 1265 215

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

PACE 52 OF 62
BY Lang Lang Pace H

CHECKET Can DATE 9/20/74

SYSTEM
OPERABILITY

SE SE STABLE OF SAME OF SAME

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS			Cu	1		DATE 9/20/7
				STSTEM SCREEN WALE AND CHLORINATION	15mg/	ICH		51	STE	
ULATION	WALKDOWN PACKAGE NO.	1		DISCREPANCIES	OK AS IS OR DAG!	GINAL DE	ANALTSIS REQUIRED	UNAFECTED	AFFECTED	IF AFFECT REFER TO REMARK NO.
S C	PAC NO.	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	₹ 5	88	2 2	2	5	
03A	14			Anchor Al48 moved 1'-17" East Evaluation			B o	I		:
									6 ,	
				1265 216						

POOR ORIGINAL

:

BY LOS LE DATE CO (B) IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS DATE 10/13/10 QUECKEN OK AS IS OR DAG/ CALC CHGS REQO CORRECT TO ORIGINAL DESIGN TO DESIGN SYSTEM SYSTEM DRAINAGE STEEM OPERABILITY STRESS CALCULATION NO. WALKDOWN PACKAGE NO. IF AFFECTE ANALYSIS REQUIRED GFECTED REFER TO REMARK DISCREPANCIES NO. NO YES IF YES, DESCRIPTION OF DISCREPANCIES Support No. 230 Configuration/ welds/clearances not in accordance with N-260-75-1 1017 ort No. 245 Configuration/welds/not in accordance with M-260-75-1 Support No. 205 Configuration/welds not in accordance with N-260-75-1 Support No. 180 Configuration/welds not in accordance with N-260-75-1 Support No. 155 Configuration/welds/clearances not in accordance with N-260-75-1 Support No. 125 Configuration/welds not in accordance with M-260-75-1 Support No. 90 Welds not in accordance with H-260-74-1 Extra Support ED-1 located mext to Bo. 125 Extra Support Bu-2 located mext to No. 180 Extra Support Bu-3 located next to No. 205 Extra Support ED-4 located mext to So. 230 35 has been relocated to horizontal run. was X-Z Restraint. Now is X+T Restraint 180 moved 2'-6" West A-26 has been relocated to a horizontal run. Pipe configuration has changed. Dimension at H-8 changed from 6'-6" to 5'-3". Evaluation Tes I 1010 Support N-25 Welds/Structural Members not in accordance with Support N-35 Welds not in accordance with N-260-41-1 Support M-40 Welds/Structural Numbers not in accordance with M-260-42-1 Support N-45 Welds/Structural Members not in accordance with N-260-42-1 Support N-90 mot installed Support M-95 mot installed Support M-105 not installed Support M-120 configuration Welds not in accordance with M-260-44-1 Support M-160 not installed Anchor A-1 Pipe not embedded, Anchor point missing Extra Support AH-4 located on 4"-45D Extra Support AB-5 located on 4"-MSD Extra Support All-6 located on 4"-48D Extra Support All-7 located on 4"-MED Extra Support All-6 located on 4"-MSD Extra Support All-9 located on 4"-48D (Continued) 1265 217

:

PAGE \$4 OF 62 BY 1 DATE 9 20/21

				TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS	0	ECKE	. E.	1		MTE 9/30/
		,		SYSTEM STATION AND INSTRUMENT AIR				51	STE	M MILITY
LCULATIO	WALKBOWN PACKAGE NO.			DISCREPANCIES	OK AS IS OR DWG	CORRECT TO ORIGINAL DESIGN	AMALTSIS REQUIRED	UNAFFECTED	AFFECTED	REFER TO REMARK NO.
539	3 2 6	NO	YES	IF YES, DESCRIPTION OF DISCREPANCIES	85	88	¥ 2	5	3	
1284	16		1	Seismic Boundary location not in accordance with N-215 Support 15 ECD-30 E2 not included in the analysis Support 15 ECD-30 E2 not included in the analysis			 Te:	*		•
				1265 218						

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS OK AS IS OR DAG!
CALC CHGS REGO
CORRECT TO
ORIGINAL DESIGN
ANALYSIS
REQUIRED SYSTEM VENT BLADER OPERABILITY. UNAFFECTED STRESS CALCULATION NO. WALKINGWN PACKACK NO. IF AFFECTIVE REFER TO REMARK DISCREPANCIES NO. NO YES IF TES, DESCRIPTION OF DISCREPANCIES 124A 47 ESC-29-E17 Welds not in accordance with H-190-E38-2916-3 BC-29-E20 Configuration not in accordance with H-190-E38-2929-2 BC-29-E21 Configuration not in accordance with B-190-E38-2920-2 ESC-29-E22 Configuration not in accordance with M-190-E38-2921-2 BC-29-E32 Welds not in accordance with H-190-E38-2931-2 ESC-29-E22 moved 12½" South ESC-29-E22 moved 19" South Length of pipe SESC-27 (G-8) shortened to 2'-3" I Evaluation I POOR ORIGINAL 1265 219

POOR ORIGINAL IN MULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS .

	<u> </u>		٠,	SYSTEM DRAINAGE STSTEM	E DUC	TO DESTOR		OPERABILITY		
CALCULATION NO.	PACKAGE PACKAGE NO.			DISCREPANCIES	OK AS IS OR DUG	CORRECT TO	AMALTSIS REQUIRED	UNAPP SCTED	APPECTED	IF AFFECT REFER TO REMARK NO.
		100	TES	IF YES, DESCRIPTION OF DISCREPANCIES	+					
1010	63			No Anchor at D.P. 260 Connection for D.P. 225 has been relocated Connection for D.P. 210 has been relocated No Mangers at D.P.s 90, 95, 105 and 160 Dimension 2'-2" at G-8 is 20'-5" on much model Dimension 14'-6" at M58 is 15'-3" on much model Evaluation				x		*
1C1K	62	T		Anchor A-1 Structural Mamber not in accordance with	T				Γ	
				M-260-34-1 Anchor A-2 Structural Number not in accordance with M-260-34-1 E35 Configuration not in accordance with M-260-35-1 Extra Hanger (E-102) located on 4"-LGE next to Anchor A-2 Extra Hanger (E-103) located on 4"-LGE below slab at E1. 610'-0" Extra Hanger (E-104) located on 4"-LGE between Hanger 35 and slab at E1. 595'-0" Extra Hanger (E-105) located on 4"-LGE below floor slab at E1. 595'-0"					;	
	_	1	1	Evaluation	1	1	Yes	x	L	
1011	62			Extra Hanger (E-106) located on 4"-LGE below floor slab at E1. 623'-0" Hanger 45 Extra Hanger (E-107) located on 4"-LGE between floor slab at E1. 614'-0" and Hanger 35 Extra Hanger (E-106) located on 4"-LGE between floor slab at E1. 603'-0" and Hanger 35 Extra Hanger (E-100) located on 4"-LFE between Anchor A-1 and penetration C-22 A-1 moved 2'-6" South D.P. 15 doesn't show hanger 45 moved 1'-10" up			or Yes			
1017	62	T	T	Two Supports are missing at D.P. 20 4 40	1	T	T	T	T	-
				Evaluation			7	x		
				1265 220						
					1					

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS GRECOED CH CALC CHCS NEGO CONSECT TO ORIGINAL DESIGN SYSTEM STATEM DRAINAGE STATEM OPERABILITY IF APPECTED ANALTSIS CALCULATION
PO.
SALKBON
PACKAGE
NO. REFER TO REMARK DISCREPANCIES TES IF TES. DESCRIPTION OF DIS APPARCIES 101H Anchor A-1 Welds not in accordance with H-260-16-1 62 Anchor A-2 Welds not in accordance with M-260-17-1 Anchor A-3 not installed E30 Clearances not in accordance with M-260-95-1 W75 Configuration not in accordance with H-260-96-1 #105 Configuration not in accordance with M-260-82-1 E115 Configuration not in accordance with M-260-63-1 H150 Configuration not in accordance with M-260-83-1 Extra Banger (E-1) located on 4"-LGE next to Banger 30 Extra Hanger (E-2) located on 4"-LGE next 'to Hanger 30 Extra Hanger (E-3) located on 4"-LCE mext to Hanger 30 Extra Henger (E-4) located on 4"-LGE between Hengers 30 & 40 Extra Benger (E-5) located on 4"-LGE between Bangers 75 & 105 Extra Manger (E-6) located on 4"-LGE between Mangers 105 & 115 Extra Manger (E-7) located on 4"-LGE between Mangers 105 & 115 Extra Manger (E-9) located on 4"-LGE between Manger 150 and penetration C-20 Extra Manger (E-8) located on 4"-LGE between Mangers 125 & 150 Extra Benger (E-10) located on 4"-LGE next to Anchor A-1 Extre Manger (E-11) located on 4"-LGE next to Manger 75 D.P. 40 moved 2'-0" South A-2 moved 1'-4" South 115 moved 1'-11" South 125 moved 1'-2" South Evaluation Tes I Anchor A-1 Configuration not in accordance with N-260-101-1 101N 62 H50 Configuration not in accordance with M-260-100-1 Extre Benger (E-12) located on 4"-LCE text to Banger 35 Extra Hanger (E-13) located on 4"-LCE between Hanger 50 and Anch A-3 moved 3'-2" Borth Evaluation Yes X I Penetration No. C26 minimum clearence is 1" 1016 62 Anchor A-1 Configuration/Structural mamber not in accordance with N-260-38-1 Extra Manger (E-110) located on 4"-LGE mext to Anchor A-1 A-1 moved 1'-7" Borth Evaluation 1 Tes 1265 221

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS TSTEM DEATHAGE SYSTEM OK AS IS OR DUC CORRECT TO ORIGINAL DESIGN BYSTEM OPERABILITY IF AFFECTED ANALTS: CALCULATIONS
NO.
NO. REFER TO REMARK DISCREPANCIES NO TES IF YES, DESCRIPTION OF DISCREPANCIES Piping installation not in accordance with M-180 (P-1) 2018 Hanger No. 30 welds not in accordance with N-260-5-1 Manger No. 45 welds not in accordance with M-260-6-1 Banger Bo. 155 welds not in accordance with N-260-2-1 Manger Bo. 170 welds not in accordance with M-260-3-1 Extra Manger UH-1 located next to Hanger No. 30 Extre Hanger UH-2 located next to Hanger No. 30 Extre Hanger DE-3 located next to Hanger No. 30 Extra Brager US-4 located next to Sanger So. 45 Extre Hanger DE-5 located next to Hanger No. 45 Extra Banger IN-6 located next to Banger No. 70 Extra Hanger UH-7 located next to Hanger No. 70 Extra Hanger UE-8 located next to Hanger No. 70 Extre Hanger UH-9 located next to Manger No. 70 Extra Hanger UH-10 located next to Anchor A-1 Support at 30 moved 22" West Support at 155 moved 144" Borth Yes Eveluation x 1 Hanger No. 25 welds not in accordance with M-260-84-1 101C Hanger No. 40 welds not in accordance with H-260-85-1 Manger No. 70 welds not in accordance with M-260-87-1 Extre Hanger CH-11 located next to Hanger No. 70 Extra Hanger UH-12 located next to Banger No. 65 Extra Hange: UH-13 located next to Banger No. 95 Extre Manger UH-14 located next to Manger No. 95 Extra Hanger UH-15 located next to Hanger No. 95 Extre Manger UH-16 located next to Manger No. 40 Extre Manger UH-17 located next to Manger No. 40 Extra Hanger UH-18 located next to Hanger No. 25 Extra Hanger UH-19 located next to Hanger No. 25 Extra Ranger OH-48 located next to Ranger No. 25 Extra Canger UH073 located next to Manger No. 95 Yes × Eve lustion 1265 222

DATE DATE DATE DATE DATE DATE

JKI	ull	IA	L	SYSTEM DRAINAGE SYSTEM	A BUC/	TO DESIGN			ERA	BILITY
STRESS CALCULATION NO.	PACKACE.			DISCREPANCIES	OK AS IS ON DAG CALC CHGS NEQD	CORRECT TO	ANALTSIS REQUIRED	UNAFFECTED	AFFECTED	IF AFFECT REFER TO REMARK NO.
-0-		NO	YES	17 TES, DESCRIPTION / A DISCREPANCIES	-	-				_
LOID	••		1	Piping installation not in agr. Annt with N-180 (P-6) Banger No. 25 configuration not in accordance with M-260-89-1 Banger No. 45 welds not in accordance with N-260-90-1 Banger No. 75 welds not in accordance with N-260-91-1 Banger No. 90 welds not in accordance with N-260-91-1 Banger No. 310 welds/structural members not in accordance with N-260-94-1 Banger No. 120 welds/structural members not in accordance with N-260-94-1 Banger No. 140 welds not in accordance with N-260-92-1 Banger No. 160 welds not in accordance with N-260-93-1 Anchor A-2 welds/configurer in in accordance with N-260-93-1 Anchor A-2 welds/configurer in in accordance with N-260-15-1 Extra Banger UN-20 located next to Banger No. 25 Extra Banger UN-21 located next to Banger No. 25 Extra Banger UN-22 located next to Banger No. 90 Extra Banger UN-23 located next to Banger No. 90 Extra Banger UN-25 located next to Banger No. 90 Extra Banger UN-26 located next to Banger No. 110 Extra Banger UN-26 located next to Banger No. 110 Extra Banger UN-27 located next to Banger No. 110 Extra Banger UN-28 located next to Banger No. 110 Extra Banger UN-28 located next to Banger No. 120 Support at 45 moved 7'-1" North Support at 50 moved 1'-5" South Evaluation			7	X		
1017	65			Piping installation not in accordance with N-180 (P-13) Hanger Ho. 50 welds not in accordance with N-260-59-2 Hanger Ho. 60 welds/configuration not in accordance with N-260-56-2 Hanger Ho. 100 welds not in accordance with N-260-56-2 Hanger Ho. 115 welds not in accordance with N-260-55-1 Hanger Ho. 155 welds/configuration not in accordance with N-260-57-1 Hanger Ho. 165 welds/configuration not in accordance with N-260-54-2 Hanger Ho. 170 welds/configuration not in accordance with N-260-54-2 Hanger Ho. 185 welds not in accordance with N-260-56-2 Hanger Ho. 205 welds not in accordance with N-260-56-2 Hanger Ho. 225 welds/configuration not in accordance with N-260-56-2 Hanger Ho. 225 welds/configuration not in accordance with N-260-60-1 Hanger Ho. 225 welds/configuration not in accordance with N-260-60-1		e				

	STRIES MAINAZ STSTEN			T DESIGN		SYSTEM OPERABILITY		
CALCULATION IN. WALEDOWN PACKAGE		DISCREPARCIES	OK AS IS OR DW	CORRECT TO ORIGINAL DE	ANALTSIS REQUIRED	DIAFFECTED	AFFECTED	REFER TO REHARK NO.
POESER	NO YES	IF YES, DESCRIPTION OF DISCREPANCIES	-	-		-		
1017 65 mt '4		Hanger No. 385 welds/configuration not in accordance with N-260-69-1 Hanger No. 385 welds/configuration not in accordance with N-260-69-1 Hanger No. 405 welds not in accordance with N-260-69-1 Hanger No. 415 welds not in accordance with N-260-69-1 Hanger No. 425 welds not in accordance with N-260-69-1 Hanger No. 435 welds not in accordance with N-260-69-1 Hanger No. 435 welds not in accordance with N-260-69-1 Hanger No. 435 welds not in accordance with N-260-70-1 Hanger No. 485 welds not in accordance with N-260-70-1 Hattra Hanger UN-57 located next to Anchor A-2 Extra Hanger UN-58 located next to Manger No. 100 Extra Hanger UN-60 located next to Hanger No. 115 Extra Hanger UN-61 located next to Hanger No. 115 Extra Hanger UN-62 located next to Hanger No. 115 Extra Hanger UN-65 located next to Hanger No. 159 Extra Hanger UN-65 located next to Hanger No. 385 Extra Hanger UN-65 located next to Hanger No. 159 Extra Hanger UN-66 located next to Hanger No. 159 Extra Hanger UN-66 located next to Hanger No. 159 Extra Hanger UN-67 located next to Hanger No. 250 Extra Hanger UN-69 located next to Hanger No. 205 Extra Hanger UN-69 located next to Hanger No. 205 Extra Hanger UN-71 located next to Hanger No. 225 Support at 225 moved 2'-7" North Support at 225 moved 2'-7" North Support at 185 moved 2'-7" North						
	1	Evaluation		1	Yes	1		
			T					

POOR ORIGINAL

1011

CALCULATE CALCULATE NO. NALEDONN PACKAGE NO.

YES

TE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS

DATE 40/1 3/ 29 BY_+ Ca DATE A/18/19 CHECKED AS IS OR BRIC/ LC CRCS REQU TO TO SYSTEM BRADNAGE SYSTEM OPERABILITY SYSTEM. UNAFFECTED IF AFFECTED CALC CRGS
CORRECT TO
ORIGINAL 1 ANALTSIS REQUIRED AFFECTED REFER TO REMARK DISCREPANCIES IF YES, DESCRIPTION OF DISCPEPANCIES

Piping Installation not in accordance with M-180 (7-8) Manger No. 25 weles/configuration not in accordance with M-260-35-1 anger No. 40 welds/configuration not in accordance with M-260-25-1 Henger No. 55 welds not in accordance with M-260-25-1 Hanger No. 75 welds/configuration not in accordance with N-260-26-1 Manger No. 90 configuration not in accordance with M-260-26-1 Eanger No. 110 configuration not in accordance with K-260-26-1 Banger No. 130 strucutral member not in accordance with M-260-28-2 Hanger No. 135 configuration not in accordance with N-260-61-1 Hanger No. 145 structural member not in accordance with M-260-28-2 Manger No. 175 structural member not in accordance with M-260-28-2 Bonger No. 190 structurel member not in accordance with N-260-28-2 Hanger No. 235 welds/configuration not in accordance with M-260-61-1 Hanger No. 250 welds not in accordance with M-260-27-1 Hanger No. 270 welds not in accordance with N-260-27-1 Banger Bo. 285 weld/cooff puret ton not in accordance with H-260-27-1 Hanger No. 315 welds not in accordance with M-260-29-1 Hanger No. 325 welds not in accordance with N-260-30-1 Hanger No. 355 welds/configuration not in accordance with N-260-112-1 Extre Henger UE-29 located next to Hanger No. 450 Extra Hanger UH-30 located next to Hanger No. 450 Extra Manger UH-31 located next to Manger No. 450 Extra Hanger UH-32 located next to Hanger No. 485 Extra Hanger UR-33 located next to Hanger No. 425 Extre Hanger UN-34 located next to Hanger No. 425 Extra Hanger UE-35 located next to Hanger No. 415 Extra Hanger UH-36 located next to Hanger No. 405 Extre Hanger UH-37 located next to Hanger No. 285 Extre Hanger UE-38 Located next to Eauger No. 270 Extra Hanger UE-39 located next to Hanger No. 325 Extra Hanger UR-40 located mext to Hanger No. 325 Extre Benger UR-41 located mext to Hanger No. 270 Extra Hanger UB42 located next to Hanger No. 250

SOUTH UED

1265, 225

IE BULLETIN 79-14 DESCRIPTION OF INSPECTION RESULTS .

PAGE 62 OF 62

BY A DATE MAN P

CHECKED CALL DATE 10/13/79

					C	-	DATE 10/
E	7	SYSTEM BRAIRAGE STSTEM	20.00	DESIGN		OP	EMBILITY
CALCULATION WALKBOAN FACKAGE NO.		DISCREPANCIES	OK AS IS OR DUG	CORRECT TO ORIGINAL DE	AVALTSIS REQUIRED	UNAFFECTED	REFER T
32 362	NO YES	IF YES, DESCRIPTION OF DISCREPANCIES		-	-	-	-
1011 65 mt'd 65	1	Extra Hanger UH-43 located next to Hanger Ho. 55 Extra Hanger UH-45 located next to Hanger Ho. 55 Extra Hanger UH-45 located next to Hanger Ho. 40 Extra Hanger UH-46 located next to Hanger Ho. 40 Extra Hanger UH-47 located next to Hanger Ho. 375 Extra Hanger UH-49 located next to Hanger Ho. 385 Extra Hanger UH-50 located next to Hanger Ho. 385 Extra Hanger UH-51 located next to Hanger Ho. 175 Extra Hanger UH-52 located next to Hanger Ho. 175 Extra Hanger UH-53 located next to Hanger Ho. 175 Extra Hanger UH-54 located next to Hanger Ho. 175 Extra Hanger UH-55 located next to Hanger Ho. 190 Extra Hanger UH-56 located next to Hanger Ho. 130 Extra Hanger UH-74 located next to Hanger Ho. 130 Extra Hanger UH-75 located next to Hanger Ho. 110 Extra Hanger UH-76 located next to Hanger Ho. 145 Support at 25 moved 1'-5" East Support at 40 moved 3'-0" form Support at 175 moved 3'-0" form Support at 190 moved 1'-4" form Evaluation			Yes	X	
		POOR ORIGINAL					
		1265 226				-	