

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | W | I | P | B | H | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 0 | 0 | 7 | 1 | 0 | 0 | 3 | 7 | 9 | 8 | 1 | 0 | 1 | 9 | 7 | 9 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 0400 hours, 10-3-79, the 3D emergency Diesel generator (one of two)
03 | failed to start for its monthly technical specification test. The 4D
04 | Diesel generator was started to verify its operability. The 3D Diesel
05 | generator was restored to service at 1720 hours, 10-3-79, after comple-
06 | tion of repairs and a test run. Because the redundant emergency Diesel
07 | generator was operable, the public health and safety was not affected.
08 | This event led to a degraded mode of operation permitted by T. S.

09 | SYSTEM CODE | EE | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | M | E | C | F | U | N | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 | LER NO. REPORT NUMBER | 17 | 7 | 9 | SEQUENTIAL REPORT NO. | 0 | 1 | 6 | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | REVISION NO. | 0 | ACTION TAKEN | A | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED | Y | 23 | NRPD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | X | 25 | COMPONENT MANUFACTURER | W | 2 | 9 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The GM Electromotive Division 999-20 Diesel generator failed to start
11 | because the Woodward UG8 dial control governor (bulletin no. 03004G)
12 | load limit strap stuck in the stop position. The faulty governor was
13 | replaced with a spare and was returned to the factory.

15 | FACILITY STATUS | E | 28 | % POWER | 1 | 0 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator observation | 32

16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36

17 | PERSONNEL EXPOSURES | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39

18 | PERSONNEL INJURIES | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41

19 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | DESCRIPTION | N/A | 43

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | N/A | 45 | 79110503 | NRC USE ONLY

ATTACHMENT TO LICENSEE EVENT REPORT NO. 79-016/03T-0

Wisconsin Electric Power Company
Point Beach Nuclear Plant Unit 1
Docket No. 50-266

At 0400 hours, October 3, 1979, the 3D emergency Diesel generator (one of two) failed to start for its monthly Technical Specification test. The 4D emergency Diesel generator was immediately tested to verify its operability.

The GM Electromotive Division 999-20 Diesel generator failed to start because the Woodward UG8 dial control governor (bulletin or catalogue no. 03004G) load limit strap stuck in the stop or shutdown position.

This governor had been recently installed as a replacement for the identical original governor for preventive maintenance. There were no known problems with the original governor, but it had been in service since the original installation of the Diesel generator and it was felt that it should be replaced as a precautionary measure. The replacement governor had been ordered from the manufacturer and was a rebuilt unit. When the replacement governor was initially installed, the load limit strap did stick in the shutdown position on one occasion. The replacement governor was then removed, disassembled, inspected, reassembled, and installed. The problem did not recur during several pre-service retests and the Diesel was then placed into service.

When the replacement governor failed on October 3, 1979, the original governor was still on site and was reinstalled. After the Diesel generator successfully completed the monthly Technical Specification test, it was returned to service at 1720 hours, October 3, 1979.

The factory replacement governor has been returned to the manufacturer.

The event led to a degraded mode of operation (reduced degree of redundancy) permitted by the Technical Specifications. The public health and safety was not affected due to the operability of the 4D emergency Diesel generator