

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N Y J A F I | 2 | 0 0 - 0 0 0 0 - 0 0 0 | 3 | 4 1 1 1 1 | 4 | _____ | 5

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 5 0 0 0 3 3 3 | 7 | 1 2 0 9 7 8 | 8 | 0 1 0 3 7 9 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
Please See Attachment

0 2 | _____
0 3 | _____
0 4 | _____
0 5 | _____
0 6 | _____
0 7 | _____
0 8 | _____

0 9 | SYSTEM CODE | I B | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | I N S T R U | 14 | COMP. SUBCODE | X | 15 | VALVE SUBCODE | Z | 16

17 | LER NO REPORT NUMBER | 7 8 | EVENT YEAR | 7 8 | SEQUENTIAL REPORT NO. | 1 0 0 | OCCURRENCE CODE | 0 3 | REPORT TYPE | L | REVISION NO. | 0

ACTION TAKEN | X | 18 | FUTURE ACTION | X | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 0 0 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NRPD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | G 0 8 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Please See Attachment

1 0 | _____
1 1 | _____
1 2 | _____
1 3 | _____
1 4 | _____

1 5 | FACILITY STATUS | F | 28 | % POWER | 0 1 9 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance Test | 32

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

1 7 | PERSONNEL EXPOSURES NUMBER | 0 0 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

1 8 | PERSONNEL INJURIES NUMBER | 0 0 0 | 40 | DESCRIPTION | NA | 41

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

2 0 | PUBLICITY ISSUED DESCRIPTION | N | 44 | NAME OF PREPARER | W. Verne Childs | PHONE: 315-342-3840

7901080154

NRC USE ONLY

During normal operation at approximately 19% rated power, Operations Surveillance Test F-ST-5R titled RBM Upscale and Downscale Instrument Functional Check could not be satisfactorily completed on Rod Block Monitor (RBM) A. The test was being conducted to allow a power increase above 30% of rated power. The RBM system is not required to be operational at less than 30% of rated power and power was maintained less than 30% of rated until the test could be completed with satisfactory results.

During trouble shooting to determine the source of failure, the malfunction disappeared and could not be duplicated. The instrument was tested with satisfactory results. On December 13 and 14, 1978 an effort to duplicate the malfunction was again conducted without success. No other corrective action was taken.