

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | C | R | P | 3 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | - | - | 5
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

CON'T
0 1 | L | 0 | 5 | 0 | - | 0 | 3 | 0 | 2 | 1 | 2 | 1 | 5 | 7 | 8 | 0 | 1 | 0 | 8 | 7 | 9 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0530 while performing routine surveillance, a low flow condition was
0 3 | noticed on Auxiliary Building exhaust. AHF-14A and AHF-14C were started and
0 4 | AHF-14B and AHF-14D secured. Subsequent investigations revealed that AHF-14D
0 5 | had ejected all blades. AHF-14D was repaired and returned to service on
0 6 | 19 December 1978. This event is contrary to Technical Specification 3.7.8.1,
0 7 | No effect on public health and safety as redundant fans AHF-14A and AHF-14C
0 8 | were operable. Seven previous occurrences of this type.

0 9 | SYSTEM CODE: AA (11) CAUSE CODE: E (12) CAUSE SUBCODE: B (13) COMPONENT CODE: BLOWER (14) COMP SUBCODE: Z (15) VALVE SUBCODE: Z (16)
17 | LER NO REPORT NUMBER: 78 (21) EVENT YEAR: 78 (22) SEQUENTIAL REPORT NO.: 070 (24) OCCURRENCE CODE: 03 (28) REPORT TYPE: L (30) REVISION NO.: 0 (32)
ACTION TAKEN: A (16) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0000 (22) ATTACHMENT SUBMITTED: Y (23) NRC-4 FORM SUB: N (24) PRIME COMP SUPPLIER: A (25) COMPONENT MANUFACTURER: J127 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event is attributed to possible damage that occurred during
1 1 | event 78-064/03L-0. No corrective action necessary as all fan blades were
1 2 | replaced.
1 3 |
1 4 |

1 5 | FACILITY STATUS: E (28) % POWER: 092 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION: Operator observation (32)
1 6 | ACTIVITY CONTENT: Z (33) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)
1 7 | PERSONNEL EXPOSURES: 000 (37) TYPE: Z (38) DESCRIPTION: NA (39)
1 8 | PERSONNEL INJURIES: 000 (40) DESCRIPTION: NA (41)
1 9 | LOSS OF OR DAMAGE TO FACILITY: Z (42) DESCRIPTION: NA (43)
2 0 | PUBLICITY: N (44) DESCRIPTION: NA (45)

NAME OF PREPARER: J. Cooper PHONE: (904) 795-6486

7901 160253

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/78-70/03L-0
2. Facility: Crystal River Unit #3
3. Report Date: 8 January 1979
4. Occurrence Date: 15 December 1978
5. Identification of Occurrence:

One pair of Auxiliary Building exhaust fans inoperable contrary to Technical Specification 3.7.8.1.

6. Conditions Prior to Occurrence:

Mode 1 power operation (98%).

7. Description of Occurrence:

At 0530 while performing Surveillance Procedure SP-335A (Radiation Monitoring Functional) a low flow condition was noticed on Auxiliary Building exhaust. AHF-14A and AHF-14C were started and AHF-14B and AHF-14D secured. Subsequent investigations revealed that AHF-14D had ejected all blades. AHF-14D was repaired, tested, and returned to service 19 December 1978.

8. Designation of Apparent Cause:

The cause of this event is attributed to possible damage that occurred during event 78-064/03L-0.

9. Analysis of Occurrence:

There was no safety hazard to the plant or general public as redundant fans AHF-14A & C were operable.

10. Corrective Action:

No corrective action necessary as all fan blades were replaced.

11. Failure Data:

Seven previous occurrences, but first occurrence of this type.

/rc