

POOR ORIGINAL

R. H. Engelken, Assistant Director for Inspection & Enforcement
Division of Compliance
THRU: S. Levine, Assistant Director for Reactor Technology, ORL

METROPOLITAN EDISON COMPANY (THREE MILE ISLAND), DOCKET #50-289
CONCRETE VOIDS AT TENDON GALLERY

Division of Compliance Inquiry Memorandum 289/68-A of December 17, 1968, mentions concrete voids near three tendons in the tendon gallery of the containment building, apparently caused by scrap wood and mud being present in the forms at the time of concrete placement.

It appears that, taken in themselves, the observed voids, with the dimensions given, can readily be repaired by some means such as the proposed epoxy cement grout without any question arising as to the integrity of the in-place mat concrete.

However, these voids may indicate that the construction procedures or degree of inspection for the mat may have been inadequate. It would be desirable, therefore, to obtain the following information:

1. Details of pour procedure (number and sequence of pours, height of individual pours, etc.).
2. Description of inspections carried out prior to, and at time of, pour, and the quality and depth of these inspections.
3. Information as to the overall quality of cleanup and form placement.
4. An outline of the repair program, when finalized.

RT-39A

DRL:C&CTB:EGA

C. G. Long, DRL

cc: J. P. O'Reilly, CO
L. Kornblith, Jr., CO
F. Nolan, CO
R. S. Eoyd, DRL

A. W. Dromerick, Chief
Containment & Component Technology Branch
Division of Reactor Licensing

Distribution:
Suppl. C&CTB Reading
DRL Reading ADRT Reading

OFFICE ▶	D. J. Skowholt, DRL	DRL:C&CTB	DRL:C&CTB	DRL:DADRT	DRL:ADRT
	E. G. Case, DRS	ALGluckmann			
SURNAME ▶	A. L. Gluckmann, DRL	G. Arndt:ewe	AWDromerick	RCDeYoung	SLevine
	S. Levine, DRL				
DATE ▶	R. C. DeYoung				
	A. W. Dromerick				
	E. G. Arndt				

1446 226

7910170 613 Q