

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L C R P 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 - - 5

01 REPORT SOURCE L 6 0 5 0 - 0 3 0 2 0 9 3 0 7 9 5 1 0 2 2 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 At 1400 in Mode 1, it was discovered during routine surveillance, SP-300, that
03 the remote shutdown indicator for "B" decay heat cooler outlet temperature
04 DH-40-TI was inoperable. This created an event contrary to Technical Speci-
05 fication 3.3.3.5. No effect upon the plant or general public. This is the
06 first occurrence of this type reported.

09 SYSTEM CODE C I F 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE E 15 VALVE SUBCODE Z 16
17 LER NO REPORT NUMBER 7 9 18 EVENT YEAR 7 9 19 SEQUENTIAL REPORT NO. 0 9 5 20 OCCURRENCE CODE 0 3 21 REPORT TYPE L 22 REVISION NO. 0
23 ACTIVITY TA Z 24 FUTURE ACTION Z 25 EFFECT ON PLANT Z 26 SHUTDOWN METHOD Z 27 HOURS 0 0 0 0 28 ATTACHMENT SUBMITTED Y 29 NRC USE ONLY N 30 PRIVATE COMP SUPPLIER A 31 COMPONENT MANUFACTURER B 0 4 5 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 The cause of this event is attributed to a defective meter movement.
11 The meter movement was replaced with a spare and returned to service on
12 4 October 1979 following satisfactory completion of SP-161, Remote
13 Shutdown Instrument Calibration Procedure.

15 FACILITY STATUS E 33 POWER 0 7 4 34 OTHER STATUS NA 35 METHOD OF DISCOVERY B 36 DISCOVERY DESCRIPTION Operator observation

16 ACTIVITY RELEASED OR RELEASE Z 37 CONTENT Z 38 AMOUNT OF ACTIVITY NA 39 LOCATION OF RELEASE NA

17 PERSONNEL EXPOSURES NUMBER 0 0 0 40 TYPE 2 TYPE 40 DESCRIPTION NA

18 PERSONNEL INJURIES NUMBER 0 0 0 41 DESCRIPTION NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA

20 PLF CITY N 43 DESCRIPTION NA

NAME OF PREPARER J. Cooper PHONE (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

7910300 340

SUPPLEMENTARY INFORMATION

Report No.: 50-302/79-095/03L-0
Facility: Crystal River Unit #3
Report Date: 22 October 1979
Occurrence Date: 30 September 1979

Identification of Occurrence:

Remote shutdown indicator for "B" decay heat cooler outlet temperature DH-40-TI inoperable, contrary to Technical Specification 3.3.3.5.

Conditions Prior to Occurrence:

Mode 1 power operation (74%)

Description of Occurrence:

At 1400 during the performance of SP-300, Operating Daily Surveillance, it was discovered that DH-40-TI was providing erroneous indication. DH-40-TI indicated approximately 240°F in contrast to actual system temperature of approximately 105°F. Maintenance restored operability and DH-40-TI was returned to service following satisfactory completion of SP-161, Remote Shutdown Instrumentation Calibration on 4 October 1979.

Designation of Apparent Cause:

The cause of this event is attributed to a defective meter movement in the indicator for DH-40-TI.

Analysis of Occurrence:

No effect upon the plant or general public.

Corrective Action:

The defective meter movement was replaced with a spare and was returned to service.

Failure Data:

This is the first occurrence of this type reported.

/rc

1224 352