



75

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket Nos. 50-317
50-318


OCT 29 1979

Baltimore Gas and Electric Company
ATTN: Mr. A. E. Lundvall, Jr.
Vice President, Supply
P. O. Box 1475
Baltimore, Maryland 21203

Gentlemen:

The enclosed IE Bulletin 79-17, Revision 1 is forwarded to you for action. A written response is required. If you desire additional information regarding this matter, please contact this office.

Sincerely,


Boyce H. Grier
Director

Enclosures:

1. IE Bulletin No. 79-17, Revision 1 w/Attachment
2. List of IE Bulletin Issued in the Last Six Months

CONTACT: L. E. Tripp
215-337-5282

cc w/encls:

R. M. Douglass, Manager, Quality Assurance
L. B. Russell, Chief Engineer
W. Gibson, General Supervisor, Operational QA
R. C. L. Olson, Senior Engineer
K. H. Sebra, Principal Engineer

1337 237

7911150024

ENCLOSURE 1

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS No.: 6820
Accession No.: 7908220157
3

IE Bulletin No. 79-17
Revision 1
Date: October 29, 1979
Page 1 of 5

PIPE CRACKS IN STAGNANT BORATED WATER SYSTEMS AT PWR PLANTS

Description of Circumstances:

IE Bulletin No. 79-17, issued July 26, 1979, provided information on the cracking experienced to date in safety-related stainless steel piping systems at PWR plants. Certain actions were required of all PWR facilities with an operating license within a specified 90-day time frame. R1
R1
R1
R1

After several discussions with licensee owner group representatives and inspection agencies it has been determined that the requirements of Item 2, particularly the ultrasonic examination, may be impractical because of unavailability of qualified personnel in certain cases to complete the inspections within the time specified by the Bulletin. To alleviate this situation and allow licensees the resources of improved ultrasonic inspection capabilities, a time extension and clarifications to the bulletin have been made. These are referenced to the affected items of the original bulletin. R1
R1
R1
R1
R1
R1
R1

During the period of November 1974 to February 1977 a number of cracking incidents have been experienced in safety-related stainless steel piping systems and portions of systems which contain oxygenated, stagnant or essentially stagnant borated water. Metallurgical investigations revealed these cracks occurred in the weld heat affected zone of 8-inch to 10-inch type 304 material (schedule 10 and 40), initiating on the piping I.D. surface and propagating in either an intergranular or transgranular mode typical of Stress Corrosion Cracking. Analysis indicated the probable corrodents to be chloride and oxygen contamination in the affected systems. Plants affected up to this time were Arkansas Nuclear Unit 1, R. E. Ginna, H. B. Robinson Unit 2, Crystal River Unit 3, San Onofre Unit 1, and Surry Units 1 and 2. The NRC issued Circular No. 76-06 (copy attached) in view of the apparent generic nature of the problem.

During the refueling outage of Three Mile Island Unit 1 which began in February of this year, visual inspections disclosed cracks in the spent fuel cooling system piping and removal system. These cracks were found and later confirmed by liquid penetrant testing. Cracking was reported to the NRC in a letter dated October 1979. A preliminary metallurgical analysis of a section of cracked and leaking weld joint is being completed.

1337 23

R1 - Identifies those additions or revisions

DUPLICATE DOCUMENT

Entire document previously
entered into system under:

ANO

7908220137

No. of pages: 11