

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | B | E | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 14 15 25 26 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 | R | P | O | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 2 | 5 | 7 | 1 | 0 | 2 | 4 | 7 | 9 | 8 | _____ | 9

7 8 60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a normal surveillance tour of the Reactor Building, the auxiliary operator

0 3 | noticed that the torus level instrument 1-CAC-LT-3342, on the remote shutdown panel,

0 4 | was reading six inches low.

0 5 | _____

0 6 | _____

0 7 | _____

0 8 | _____

0 9 | Technical Specification 3.3.5.2, 6.9.9.b _____

0 9 | I | E | 11 | B | 12 | A | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16 |

7 8 9 10 11 12 13 18 19 20

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | 7 | 9 | 21 | 22 | - | 23 | 0 | 8 | 3 | 24 | 26 | / | 27 | 0 | 3 | 28 | 29 | L | 30 | - | 31 | 0 | 32

18 | X | 19 | C | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | Y | 24 | Y | 25 | A | 26 | R | 3 | 6 | 9 | 27

13 34 35 36 37 40 41 42 43 44 47

LER/RO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | CAC-LT-3342 had been calibrated inaccurately due to an erroneous sight glass reading.

1 1 | The temporary sight glass contained debris. The sight glass was replaced and the

1 2 | instrument was recalibrated and returned to service. The calibration instruction has

1 3 | been revised to include a check of the sightglass for cleanliness before calibration

1 4 | begins and to verify sight glass level before and after calibration. (Cont'd)

1 5 | D | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Operator Surveillance | 32

7 8 9 10 12 13 44 45 46 80

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

7 8 9 10 11 44 45 80

ACTIVITY CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

7 8 9 11 12 13 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA | 41

7 8 9 11 12 80

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43

7 8 9 10 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45

7 8 9 10 80

PUBLICITY ISSUED DESCRIPTION

7911210429

80

LER CONTINUATION -- RO# 1-79-83

Facility: BSEP Unit #1

Event Date 10-24-79

An Engineering Work Request has been written to install a permanent sight glass.

1375 094