LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTE DE BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M D C C N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5
CON'T O 1 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 2 During steady state operation, #12 Diesel Generator was placed out
old of service at 0650 for repair of various fuel oil leaks. While #13
0 4 Diesel was inoperable the remaining A.C. power sources were tested in
ols Laccordance with T.S. 3.8.1.1. #12 Diesel Generator was returned to
ole service at 1150. Unit 2 was in Mode 2. LER 77-122 (U-1) describes
017 La similar event.
018
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD4 PRIME COMP. COMPONENT METHOD HOURS 22 SUBMITTED FORMSUB. PRIME COMP. MANUFACTURER MANUFACTURER SUBMITTED FORMSUB. SUPPLIER MANUFACTURER FORMSUB. SUPPLIER MANUFACTURER FORMSUB. SUPPLIER MANUFACTURER FORMSUB. PRIME COMPONENT MANUFACTURER FORMSUB. SUPPLIER FORMSUB.
Various flare and ferrule fittings loose from vibration of diesel were
tightened to stop leaks. One 4" piece of 2" copper tubing was replaced
due to a crack. These small leaks do not degrade service of the diesel;
usually they are detected and eliminated by bi-weekly P.M. Procedures
1 4 1 8 2-24-M-2W-1.
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 [1 5
ACTIVITY CONTENT *ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 N/A N/A N/A N/A 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 0 37 Z 38 N/A
PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41 POR ORIGINAL 12 POR ORIGINAL
Coss of OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 7912310357
PUBLICITY ISSUED DESCRIPTION 45 IN 44 N/A
NAME OF PREPARER J. S. Lagiewski/D. E. Huseby PHONE: (301)234-7942/7997