

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M D C C N 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 _____ 5
7 8 9 14 15 25 26 30 57 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
 0 1 REPORT SOURCE L 0 5 0 0 0 3 1 8 7 1 1 2 7 7 9 8 1 2 2 0 7 9 9
7 8 60 61 68 69 74 75 80
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1130 channel ZG pressurizer pressure transmitter of the engineered
 0 3 safety features system was placed out of service in accordance with
 0 4 T.S. 3.3.2.1 for repair of a conduit and correct a transmitter zero
 0 5 shift. The three redundant channels remained operable during the
 0 6 event. The transmitter was returned to service at 1615. This is not
 0 7 a repetitive occurrence.

0 9 SYSTEM CODE Z Z 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE S U P P O R T 14 COMP. SUBCODE A 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 7 9 21 22
 SEQUENTIAL REPORT NO. 0 4 2 24 26
 OCCURRENCE CODE 0 3 28 29
 REPORT TYPE L 30
 REVISION NO. 0 32
 ACTION TAKEN Z 18 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER I 2 0 0 7 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Found transmitter 2-PT-102D out of calibration; it had zero-shifted to a
 1 1 signal level approximately 28 psi high. The transmitter was recalibrated
 1 2 and its conduit repaired. The cause was the close proximity of the conduit
 1 3 to a fire system water line hanger. Movement of the pipe system caused the
 1 4 hanger to contact the conduit on the transmitter base. (CONT.)

1 5 FACILITY STATUS C 28 % POWER 0 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator Observation 32
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT Z 33 Z 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 13 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 80

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
7 8 9 10 11 12 80

1685 136

NAME OF PREPARER S. M. Davis/P. G. Rizzo PHONE: (301)234-7942/7986

8001040 566

LER NO. 79-42/3L
DOCKET NO. 50-318
EVENT DATE 11/27/79
REPORT DATE 12/21/79
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTION: (CONTINUED)

The hanger will be modified to insure the fire system water line cannot contact the transmitter.

1685 137