LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	A R A N 0 2 2 0 C - 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 1 7 8	SOURCE L 6 0 5 0 0 0 3 6 8 7 1 2 3 0 7 9 8 0 1 2 9 8 0 9
0 2	Immediately following a plant trip the steam driven Emergency Feed Water
0 3	Pump (2P7A) started and then tripped on turbine overspeed. The electric
0 4	Emergency Feed Water Pump (2P7B) was operable and had sufficient flow
0 5	for the transient response. The turbine trip on 2P7A was reset and the
0 6	pump was successfully started 3 times. Similar to LER's 50-368/79-055,
0 7	79-072, & 79-081. Reportable per T.S.6.9.1.9b
0 8	
0 9	SYSTEM CAUSE SUBCODE S
	17 REPORT 10 REPORT NO. 17 PO 21 22 23 24 26 27 28 29 30 31 32 20 32 20 27 28 29 30 30 31 32 20 30 30 31 32 32 30 30 30 30 30 30 30 30 30 30 30 30 30
1 0	A steam trap on the steam supply line was isolated due to a blow-thru
1 1	problem. The isolated steam trap resulted in condensate in the supply
112	line which caused the over-speed trip. Additional administrative controls
1 3	on trap isolation have been instituted to prevent reoccurrence.
1 4	
1 5	STATUS TO POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 AS
	CCTIVITY CONTENT ELEASED OF RELEASE NA NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA NA NA N
1 7	THE DESCRIPTION 39 O O O 37 Z OB NA NA 11 12 13 13 14 15 16 17 18 18 18 18 18 18 18 18 18
1 8	NUMBER DESCRIPTION (41)
7 8	LZ 42 NA
2 0	PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY NRC USE ONLY
7 8	NAME OF PREPARER Rex Pendergraft PHONE 501/968-2519
	TITLE SECTION OF THE PROPERTY