

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

REPORT  
SOURCE

REPORT SOURCE L 60 DOCKET NUMBER 0 5 0 0 0 2 3 7 7 69 EVENT DATE 0 1 1 1 74 REPORT DATE 75

SEQUENCES 10 1501-38B failed t

0 3 operate while securing the "D" LPCI pump after pumping down the torus. The valve

03 operate while securing the D. Miller pump.

04 opened but could not be closed from the control room. The breaker did not trip while

05 and taken out of service. Safety

0 4 | opened but could not be closed from the control room. The valve was manually closed and taken out of service. Safety

0 5 | operating the valve. Valve was manually closed and taken out of service. Safety

0 6 | to the line could be closed to prevent

0 5 operating the valve. Valve was manually

0 6 significance was minimal since a second valve in the line could be closed to prevent

0 6 significance was minimal since a

0 7 flow. This is the first failure of this valve.

07 flow. This is the first failure.

08

COMP. VALVE  
SUBCODE SUBCODE

0 8  
 7 8 9  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE  
 S E (11) E (12) B (13) V A L V O P (14)  
 18  
 COMP. SUBCODE VALVE SUBCODE  
 A (15) Z (16)  
 19 20  
 REVISION

0 9  
7 8

CODE  
S F 11  
9 10

CODE  
E 12  
11

CODE  
B 13  
12

V A L V O P 14  
13 18

CODE  
A 19  
19

CODE  
E 20  
20

REVISION NO.  
0  
21

REPORT TYPE  
L  
22

OCCURRENCE CODE  
1 0 3  
23

SEQUENTIAL REPORT NO.  
1  
24

(17) LER-RO REPORT NUMBER 

7	9
---	---

 EVENT YEAR 

21	22
----	----

23
----

 REPORT NO. 

0	0	4
---	---	---

24	26
----	----

27
----

28
----

0	3
---	---

29
----

30
----

31
----

32
----

 ATTACHMENT 

33
----

 NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

ACTION TAKEN 1 A 2 Z 19  
 FUTURE ACTION 2 Z 20  
 EFFECT ON PLANT 2 Z 20  
 SHUTDOWN METHOD 2 Z 21  
 HOURS 0 C 0 22  
 ATTACH SUBMITTED N 23  
 FORM SUB. Y 24  
 SUPPLIER N 25  
 L 2 0 0 44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 of the failure was a broken pinion gear on the valve operator motor shaft.

The pinion gear was replaced and the valve was successfully cycled three times from

the control room. No further corrective action is planned.

---

DESCRIPTION (22)

8 9  
FACILITY STATUS      % POWER  
OTHER STATUS (30)      METHOD OF DISCOVERY      DISCOVERY DESCRIPTION  
NA      A (31)      Operational Event

E (23) 0 9 1 29 44 45 46  
 8 9 10 12 13  
 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) NA  
 LOCATION OF RELEASE (36)

RELEASED OF RELEASE  
[Z] (33) [Z] (34) NA 44  
2 9 10 11 45

PERSONNEL EXPOSURES		DESCRIPTION (39)	
NUMBER	TYPE		
0	(37)	(38)	N/A

PERSONNEL INJURIES	DESCRIPTION
NUMBER	NTA

0 0 0 20 NA  
8 9 11 12  
LOSS OF OR DAMAGE TO FACILITY (43)

TYPE DESCRIPTION  
9 Z 42 NA  
8 9 10  
NRC USE ONLY

0 N 44 ISSUED PUBLICITY DESCRIPTION 45 NA 7902090397 68 69 790

8 9 10

PHONE 407

7902090344

NAC USE ONLY

PHONE 489