ATTACHED IS A PART 21 REPORT FROM IE MAIL UNIT - ROOM 359E/W

	79-136-001 CMP	, , , , , , , , , , , , , , , , , , , ,			
	DOCKET NO. 50-339				
DATE DISTRIBUTED 7/17/	79 ORIGINAL REPORT	SUPPLEMENTARY 🗹			
DISTRIBUTION:					
REACTOR(R)	FUEL CYCLE &	SAFEGUARDS(S)			
NRR/DOR , DIRECTOR	AD/FRYSI '	AD/SG-IE			
NRR/DPM DIRECTOR	NMSS/FOMS	AD/ROI			
AD/ROI (2)	REGIONS	REGIONS			
AD/RCI	IE FILES	NRR/DOR, DIRECTOR			
REGIONS	PDR	NMSS/SG SS-881			
IE FILES (2)	LPDR	PDR			
CENTRAL FILES	CENTRAL FILES-SS-396	LPDR			
CENTRAL FILES (CHRON)	CENTRAL FILES (CHRON) (016)	TERA			
PUR		IE FILES (2) CENTRAL FILES 016			
LPDR	TERA				
TERA	BOB DEWNIG, MPA	CENTRAL FILES (CHRON)			
BOB DENNIG, MPA		CENTRAL FILES - SS-396			
ACTION:		BOB DEWLIG, MPA			
PRELIMINARY EVUALATION OF FOLLOW-UP AS SHOWN BELOW:	THE ATTACHED REPORT INDICATE	S LEAD RESPONSIBILITY FOR			
IE 🔀	RR I MMSS 1	OTHER			
RCI BOI SG EEMSI					

656333 7908150192 REV. 3/5/79

DATA SHEET

10 CFR PART 21 REPORT IDENTIFICATION AND RECORDING OF IE ACTIONS

PART 21 IDENTIFICATION NO. 79- NAME(S) OF LICENSEE(S), VENDOR(S) PERSON(S) OR OTHER ORGANIZATION(S) REPORTING	epco emc.		wn,	ga.			2 1	
GENERAL SUBJECT OF REPORT					-			7
DATE OF INITIAL NOTIFICATION 48 HOUR REPORT)	DATE(S) OF PART 21 REPORT(S). (5 DAY & SUPPLEMENT)							
FACILITY(IES) INVOLVED: 50-339								
RESPONSIBLE IE ORGANIZATION(S)				1 1				_
LEAD = 1 SUPPORTIVE = 2	FF& MSI	_	SI	-	RCI	_	ROI	-
IE ACTIONS - CHECK	OR PROV	DE DA	TA AS	APPROF	PRIATE			-
LIST OTHER NRC OFFICES INFORMED	ne transcents a elicen			outen de trolué	HATTING TO THE OWNER.		APP SECURIORISMOSTER	Mar was
DISCUSSED WITH INITIATOR?	YFC	NO	REPORT IS REQUIRED UNDER PART 21?			YES	NO.	
REQUEST MADE FOR ADDITIONAL INFO7			INQUIRY?					
PRESS RELEASE(S)			INSPECTION?					1
REVIEWED FOR POTENTIAL A/O (MC 1110) DATE:			INVESTIGATION					
TRANSFERED TO OTHER NRC OFFICE?			ENFORCEMENT					
BULLETIN ISSUED? NO.			CORRECTIVE ACTION TAKEN?					
DATE OF CLOSEOUT:			CIRCULAR ISSUED?					
LOSEOUT METHOD:				-				
E REPORT NUMBERS:		-		-		-		
DATE OF FINAL REVIEW & DISTRIBUTION:							100	
DDITIONAL COMMENTS:								PROTOGRAM:

(Use other side of form if additional space is required)

7/1/78

656334

LISNRO REC

VIRGINIA ELECTRIC AND POWER COMPANY, RICHMOND, VIRGINIA 2126

19 JUL 5 A9: 50

July 2, 1979

Mr. James P. O'Reilly, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303 Serial No. 539 PSE&C/GLP:adw:mc

Docket No. 50-339

Dear Mr. O'Reilly:

On June 27, 1979, a report was made under the provisions of 10CFR50.55(e) concerning errors that can occur in steam generator levels during accident conditions.

In accordance with the reporting requirements of 10CFR21, the following information is submitted:

A. Name and address of reporting individual:

Mr. E. A. Baum, Executive Manager Licensing and Quality Assurance Virginia Electric and Power Company P. O. Box 26666 Richmond, Virginia 23261

B. Facility, activity, and/or component affected;

North Anna Power Station, Unit 2 Steam Generator Level Indication and Trip Signals.

C. Name of firm constructing the facility or supplying the component, activity or service:

Westinghouse Electric Corporation P. O. Box 355 Pittsburgh, Pennsylvania 15230

790258

DEFICIAL COPY

boots

D. Description of defect, deficiency, or failure to comply:

We are informed by Westinghouse that the heating of the Steam Generator level reference legs following a high energy line break inside containment was not taken into account during the original Westinghouse analysis.

An increase in reference leg water column temperature will result in a decrease of the water column density with a consequent apparent increase in the indicated steam generator water level (i.e., apparent level exceeding actual level). The error could result in a delay in reaching the Low Steam Generator Level Reactor trip. This could occur when the temperatures in the containment are in excess of 110°F.

E. Date of determination of reportability:

June 27, 1979

F. Similar components, activities, or services:

North Anna Unit 1, Surry Units 1 and 2

G. Corrective action which has been, is being or will be taken, the individual responsible and the length of time to complete the action:

The problem is being analyzed by Westinghouse to determine the necessary actions to be taken, if any, to insure that these errors are accounted for and that the appropriate safety system actions will occur as required in the safety analysis for this plant. The analysis is being performed as expenditiously as possible, the results should be available within a very short period of time.

H. Other information:

We feel that no immediate action is required at this time, a final report should be available as a part of the 30 day report on this item.

Should you require further information, please contact this office.

San C. Brown, Jr.
Senior Vice President - Power Staylon

Engineering and Construction

cc: Director, Office of Inspection and Enforcement