LICENSEE EVENT REPORT
- CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A P P S 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T O 1
0 2 At 0635 hours on November 1, 1979, Oxygen Analyzer valves AO-5065-10,12,15,16,17,23
old and 26 did not meet the timing requirements for Primary Containment Isolation. All
0 4 valves were placed in the closed position and investigation commenced immediately.
O 5 This condition also caused the Primary Containment Atmospheric Monitor C-19 to
o 6 become inoperable.
07
7 8 9
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
17 REPORT NUMBER 7 9 1 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. COMPONENT MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. COMPONENT MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. COMPONENT MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB PRIME COMP. SUPPLIER MANUFACTURER ACTION FOR SUPPLIER FORM SUB PRIME COMP. SUPPLIER FORM
The investigation revealed faulty position indication lights on AO-5045-12, 15, and
a loose limit switch on AO-5045-26. These valves position problems were corrected
and timing was correct. A0-5045-17 & 23 were checked with no problems found and
timed satisfactorily. A0-5045-10 & 16 were left in the isolated position for future
repairs and the O2 Analyzer & C-19 returned to service on Nov. 2, 1979.
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 1 28 1 0 0 29 N.A. B 31 ROUTINE SURVEILLANCE 7 8 9 10 12 13 44 45 46 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N.A. N.A. LOCATION OF RELEASE (36) N.A. 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 8 9 PERSONNEL INJURIES N.A. N.A.
PERSONNEL INJURIES NUMBER DESCRIPTION (41) N.A.
1 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION N.A. 2012.070 393
7 8 9 10 80
N.A.
NAME OF PREPARER Charles J. Mathis PHONE: 617-746-7900 a