

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] | G | A | E | I | H | 2 | [2] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | [3] | 4 | 1 | 1 | 1 | 1 | 1 | 1 | [4] | _____ | [5]

LICENSEE CODE 9 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T [0 1] | REPORT SOURCE [L 6] | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | [7] | 0 | 1 | 1 | 7 | 8 | 0 | [8] | 0 | 1 | 3 | 1 | 8 | 0 | [9]

DOCKET NUMBER 60 61 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES [10]

[0 2] | While applying an equalizing charge to the 125/250 VDC Station Service Batteries, the

[0 3] | HPCI Automatic Flow Control Power Inverter tripped. Due to the tripping of the

[0 4] | inverter, 2E41-K603, the Automatic Flow Control Loop of HPCI was made inoperative. The

[0 5] | manual mode of HPCI was still operable. RCIC, ADS, CS and LPCI were operable. There

[0 6] | were no effects upon public health and safety due to this event. This is a non-repet-

[0 7] | itive event.

[0 9] | SYSTEM CODE [S 9] [F 10] [11] CAUSE CODE [X 11] [12] CAUSE SUBCODE [Z 12] [13] COMPONENT CODE [I 13] [N 14] [S 15] [T 16] [R 17] [U 18] [14] COMP. SUBCODE [P 19] [15] VALVE SUBCODE [Z 20] [16]

[17] LER/RO REPORT NUMBER [8 21] [0 22] [18] [0 19] [3] [20] [23] [24] [25] [26] [27] [28] [0 29] [3] [30] [L 31] [32] [0 32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [Y 42] [24] [N 43] [25] [T 44] [2] [4] [8] [26] [47]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS [27]

[1 0] | The cause of the occurrence has been attributed to instrument drift. The high volt-

[1 1] | age trip setpoint of 2E41-K603 is 147 ±.5 VDC. The inverter tripped at 141 VDC. The

[1 2] | instrument was recalibrated satisfactorily and put on the annual LCO list.

[1 5] | FACILITY STATUS [E 28] [28] [0 9] [9] [29] [29] OTHER STATUS [30] [30] METHOD OF DISCOVERY [B 31] [31] SURVEILLANCE DISCOVERY DESCRIPTION [32] [32]

[1 6] | ACTIVITY TAKEN [Z 33] [33] [Z 34] [34] AMOUNT OF ACTIVITY [35] [35] LOCATION OF RELEASE [36] [36]

[1 7] | PERSONNEL EXPOSURES NUMBER [0 37] [37] [Z 38] [38] DESCRIPTION [39] [39]

[1 8] | PERSONNEL INJURIES NUMBER [0 40] [40] DESCRIPTION [41] [41]

[1 9] | LOSS OF OR DAMAGE TO FACILITY TYPE [Z 42] [42] DESCRIPTION [43] [43]

[2 0] | PUBLICITY ISSUED [N 44] [44] DESCRIPTION [45] [45]

NAME OF PREPARER R. T. Nix PHONE: 912-367-7781

8002070 279

1938 041

NRC USE ONLY

NARRATIVE REPORT

Georgia Power Company
Plant E. I. Hatch
Baxley, Ga. 31513

Reportable Occurrence Report No. 50-366/1980-03.

While the reactor was at a steady state operation, an equalizing charge was being applied to the 125/250 VDC Station Service Batteries. The HPCI Automatic Flow Control Loop Power Inverter, 2E41-K603, circuit breaker tripped. This caused the Automatic Flow Control Loop of HPCI to be inop due to the tripping of the inverter circuit breaker. The manual mode of HPCI was still operable and the RCIC System was also operable. Also the ADS, CSS, and LPCI Systems were operable.

The operation of the plant was not effected. There were no effects upon public health and safety due to this event. This is a non-repetitive event.

The cause of this occurrence has been attributed to setpoint drift. The setpoint of 2E41-K603 is $147 \pm .5$ VDC and the instrument actually tripped at 141 VDC. The instrument, 2E41-K603, was recalibrated per HNP-2-5272, Topaz Static Inverter Calibration, and returned to service. The instrument, 2E41-K603, was put on the annual LCO calibration list.

Unit I and Unit II utilize this type of instrument, Topaz Static Inverter, Model N250-GWR-125-60-115, in their HPCI, LPCI and Feedwater Control Systems. The instrument failure rate of these instruments do not indicate that there is any generic problems with these instruments.

1938 042