



Public Service Company of Colorado

16805 Weld County Road 19 1/2, Platteville, Colorado 80651

February 7, 1980
Fort St. Vrain
Unit No. 1
P-80019

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Reference: Facility Operating License
No. DPR-34


Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/80-03, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/80-03.

Very truly yours,


Don Warembourg
Manager, Nuclear Production

DW/clh

Enclosure

cc: Director, MIPC

1951 339

8002120

713

D⁰⁰²
S.11

REPORT DATE: February 7, 1980

REPORTABLE OCCURRENCE 80-03

OCCURRENCE DATE: January 10, 1980

ISSUE 0

Page 1 of 2

FORT ST. VRAIN NUCLEAR GENERATING STATION
PUBLIC SERVICE COMPANY OF COLORADO
16805 WELD COUNTY ROAD 19 1/2
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/80-03/03-L-0

FINAL

IDENTIFICATION OF
OCCURRENCE:

On January 10, 1980, the lines supplying backup bearing water from the accumulator to the Loop 2 helium circulators were determined to be impaired due to three impaired hangers.

This is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2 as a degraded mode of LCO 4.3.10.

EVENT
DESCRIPTION:

On January 10, 1980, with the reactor shutdown for maintenance, hangers 11A-H-21235, 11A-H-21236, and 11A-H-21237 were determined to be impaired. These hangers are on the lines supplying backup bearing water to the helium circulators. Although the backup bearing water lines are not safety related, these hangers are included in the analysis of a safety related system; therefore, the hangers being impaired constitutes an impairment of System 21.

CAUSE
DESCRIPTION:

The hangers were removed during previous work and were not re-installed.

CORRECTIVE
ACTION:

The hangers were redesigned to fit current piping configuration and are being re-installed under Change Notice 1178.

No further corrective action is anticipated or required.

1951 340

~~8002120~~ 724

Prepared By: Asa B. Reed, Jr.
Asa B. Reed, Jr.
Technical Services Technician

Reviewed By: J. W. Gahm
J. W. Gahm
Technical Services Supervisor

Reviewed By: F. M. Mathie / by DMR
Frank M. Mathie
Operations Manager

Approved By: Don Warembourg
Don Warembourg
Manager, Nuclear Production

1951 341