

ALABAMA POWER COMPANY
JOSEPH M. FARLEY NUCLEAR PLANT
DOCKET NO. 50-348
ATTACHMENT TO LER 78-066/03X-2

Facility: Joseph M. Farley Unit 1

Report Date: (Update Report - Previous Report Date 10/16/78)

Event Date: 9/14/78

Identification of Event

Air pressure in the 1B diesel generator A and B air start receivers was found to be 210 psig and 80 psig respectively.

Conditions Prior to Event

The Unit was in Mode 1 operating at 100% steady state power.

Description of Event

At approximately 1015 on 9/14/78, an NRC inspector touring the diesel building observed that the air receivers in the starting air system for the 1B diesel generator were reading 210 psig and 80 psig respectively for the A and B receivers. The problem was independently identified by Maintenance personnel shortly thereafter. The Shift Foreman was notified. He declared the 1B diesel generator inoperable at 1030 on 9/14/78, and verified the operability of the remaining A. C. sources. The 1A air compressor, which was previously tagged out for maintenance, was returned to service, and the 1B diesel generator was declared operable at 1230 on 9/14/78.

Designation of Apparent Cause

A leaking relief valve and check valve on the 1B air compressor caused the 1A and 1B air receivers to bleed down. The relief valve had been replaced at approximately 0930 on 9/14/78, and was not properly tested prior to returning the 1B air compressor to service. The test and restoration requirements of FNP-1-AP-52, Equipment Status Control and Maintenance Authorization, were not implemented properly.

Analysis of Event

The 1B diesel generator was restored to an operable status within the time limit specified in Technical Specification 3.8.1.1. Although the air pressure in the 1A and 1B air receivers was 210 psig and 80 psig respectively, it is noted that successful starts on the 1B diesel generator were made during the startup test program at air pressures as low as 140 psig. The other separate and independent diesel generator set (1-2A and 1-C diesel generators) was operable. This occurrence had no affect on the health and safety of the general public.

Effect on Plant

This occurrence had no significant effect on plant operation.

Corrective Action

The operability of the 1B diesel generator was restored when the 1A air compressor was returned to service and the air pressure in the air receivers was restored to normal. Individuals involved in this incident have been instructed in proper implementation of FNP-1-AP-52.

Failure Data

None