PHONE -

NA: (2-7)	LICENSEE EVENT REPORT LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	A L B R F 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 67 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 5 9 7 0 1 2 0 7 9 8 0 3 2 3 7 9 9 EVENT DESCRIPTION AND PROBABLE (ONSEQUENCES 10)
0 2	While in cold shutdown for refueling, local leak rate testing was performed in accord-
0 3	Lance with T.S. 4.7.A.2.g,h, and i. The total leakage (6,042.0179 SCFH) exceeded the al-
0 4	[lowable 60 percent La per 24 hours (707.1 SCFH). There was no hazard to the public
0 5	Lealth or safety. Previous occurrences: 50-259/7723, 50-260/789 and 50-296/7825.
06	
6 7	
08	SYSTEM CAUSE CAUSE COMP. VALVE
0 9 7 8	S A 11 E 12 B 13 V A L V E X 14 X 15 X 16
	17 REPORT 7 9
	ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB SUPPLIER SU
10	There was excessive leakage by the valve seating surface. Eight valves, including
III	[four MSIV's, were found leaking. The nameplate data of the valves is being furnished]
112	Las a supplement to this report. The valves were repaired and retested to demon-
13	L strate compliance.
1 4 a	9 80 FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 5	H 28 0 0 0 0 29 NA B 31 Surveillance Testing 9 10 10 12 13 44 45 46
16	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE NA LOCATION OF RELEASE NA BO
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA 11 12 13 80
1 8	PERSONNEL INJURIES NUMBER 0 0 0 0 0 NA NA 80
19	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 80
20	PUBLICITY (45) 7903280323 NAC USE ONLY (55) NAC USE ONLY (65) NAC

NAME OF PREPARER -