

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

① | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40
A | L | J | M | F | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
① | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30
REPORT SOURCE L ⑥ | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 8 | ⑦ | 1 | 1 | 0 | 3 | 7 | 9 | ⑧ | 1 | 2 | 0 | 3 | 7 | 9 | ⑨
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩
① 2 | At 1345 on 11/3/79 during performance of the surveillance test on the turbine driven
① 3 | auxiliary feedwater pump (TDAFWP), the TDAFWP tripped on overspeed. Tech. Spec.
① 4 | 3.7.1.2 requires at least 3 independent steam generator aux feedwater pumps and
① 5 | associated flow paths to be operable. The Tech. Spec. 3.7.1.2 action statement
① 6 | requirements were met. The health and safety of the general public were not affected.
① 7 |
① 8 |
① 9 |

① 9 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32
SYSTEM CODE SH ⑪ | CAUSE CODE D ⑫ | CAUSE SUBCODE Z ⑬ | COMPONENT CODE INSTRU ⑭ | COMP SUBCODE C ⑮ | VALVE SUBCODE Z ⑯
LER/RO REPORT NUMBER ⑰ | EVENT YEAR 7 | 9 ⑱ | SEQUENTIAL REPORT NO. 0 | 5 | 1 ⑲ | OCCURRENCE CODE ⑳ | REPORT TYPE I ㉑ | REVISION NO. 0 ㉒
ACTION TAKEN E ㉓ | FUTURE ACTION Z ㉔ | EFFECT ON PLANT Z ㉕ | SHUTDOWN METHOD Z ㉖ | HOURS 0 | 0 | 0 | 0 ㉗ | ATTACHMENT SUBMITTED Y ㉘ | NPD-4 FORM SUB. N ㉙ | PRIME COMP SUPPLIER N ㉚ | COMPONENT MANUFACTURER I | 0 | 7 | 5 | ㉛

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉞
① 0 | See Attachment
① 1 |
① 2 |
① 3 |
① 4 |

FACILITY STATUS E ㉟ | % POWER 0 | 0 | 1 ㊱ | OTHER STATUS NA ㊲ | METHOD OF DISCOVERY B ㊳ | DISCOVERY DESCRIPTION Surveillance test FNP-1-STP-22.0 ㊴
ACTIVITY CONTENT Z ㊵ | AMOUNT OF ACTIVITY NA ㊶ | LOCATION OF RELEASE NA ㊷
PERSONNEL EXPOSURES NUMBER 0 | 0 | 0 ㊸ | TYPE Z ㊹ | DESCRIPTION NA ㊺
PERSONNEL INJURIES NUMBER 0 | 0 | 0 ㊻ | DESCRIPTION NA ㊼
LOSS OF OR DAMAGE TO FACILITY TYPE Z ㊽ | DESCRIPTION NA ㊾
PUBLICITY ISSUED N ㊿ | DESCRIPTION NA ①

1528 133 7912110 337

POOR ORIGINAL

GPO 817-726

LER 79-051/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

During performance of the surveillance test on the TDAFWP on 10/26/79, the manual speed adjust in the turbine local panel was adjusted in an attempt to bring the turbine up to speed with low steam pressure. The manual speed adjustment was left misadjusted due to lack of position markings. The manual speed control was adjusted and the TDAFWP was verified operable at 1450 on 11/3/79. A modification will be incorporated to add a knob with a pointer and a scale to allow resetting of the manual speed adjuster to the proper value after maintenance or testing.

1528 134 .