

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [O][H][D][B][S][1] [2] [0][0]-[0][0]N[P]F-[0]3 [3] 4 1 1 1 1 [4] [] [5] LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T [0][1] [L] [6] [0] 5 [0] - [0] 3 4 6 [7] [1] 1 [0] 4 7 8 [8] [0] 1 1 9 7 9 [9] REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0][2] At 02:54:03 hours, operations personnel intending to start Reactor Coolant Pump (RCP) [0][3] 1-1-1, whose essential bus feed breaker undervoltage relays were disconnected for the [0][4] start, started RCP 1-1-2 instead. Essential Bus D1 de-energized at 02:54:08 hours. [0][5] Emergency Diesel Generator 1-2 started and Essential Bus D1 was re-energized at 02:54:18 [0][6] hours. It was also determined that disabling the essential bus undervoltage relays is [0][7] contrary to Technical Specification 3.8.2.1. The total time in which Essential Bus D1 [0][8] was de-energized was ten seconds. The unit was subcritical at the time of the incident. (NP-33-78-148)

[0][9] SYSTEM CODE [E][B][11] CAUSE CODE [A][12] CAUSE SUBCODE [A][13] COMPONENT CODE [C][K][T][B][K][R][14] COMP. SUBCODE [E][15] VALVE SUBCODE [Z][16] LER RO REPORT NUMBER [7][8] EVENT YEAR [] SEQUENTIAL REPORT NO. [1][2][5] OCCURRENCE CODE [0][3] REPORT TYPE [L] REVISION NO. [0] ACTION TAKEN [H][18] FUTURE ACTION [Z][19] EFFECT ON PLANT [Z][20] SHUTDOWN METHOD [Z][21] HOURS [0][0][0][0] ATTACHMENT SUBMITTED [Y][23] NPD-4 FORM SUB. [N][24] PRIME COMP. SUPPLIER [Z][25] COMPONENT MANUFACTURER [Z][Z][Z][Z][26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1][0] This incident was caused by personnel error and design deficiencies. Essential Bus D1 [1][1] was transferred back to its normal power supply and Emergency Diesel Generator 1-2 was [1][2] returned to normal standby status. Operations personnel will now transfer the essen- [1][3] tial bus power supply to the bus tie transformer while starting RCPs or CNPs. FCRs [1][4] have been prepared to install momentary bypassing of the undervoltage relays and modify the T.S.

[1][5] FACILITY STATUS [C][28] % POWER [0][0][0][29] OTHER STATUS [NA] METHOD OF DISCOVERY [A][31] DISCOVERY DESCRIPTION [NA] [1][6] ACTIVITY RELEASED [Z][33] CONTENT OF RELEASE [Z][34] AVG. OF ACTIVITY [NA] LOCATION OF RELEASE [NA] [1][7] PERSONNEL EXPOSURES NUMBER [0][0][0][37] TYPE [Z][38] DESCRIPTION [NA] [1][8] PERSONNEL INJURIES NUMBER [0][0][0][40] DESCRIPTION [NA] [1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z][47] DESCRIPTION [NA] [2][0] PUBLICITY ISSUED [N][44] DESCRIPTION [NA]

790125 0140

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-78-148

DATE OF EVENT: November 4, 1978

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Loss of power to 4.16 KV Essential Bus D1 and removing essential bus undervoltage relays when starting Reactor Coolant Pumps

Conditions Prior to Occurrence: The unit was in Mode 3, with Power (MWT) = 0, and Load (Gross MWE) = 0.

Description of Occurrence: Prior to starting Reactor Coolant Pumps (RCP) 1-1-1 and 1-2-2 on November 4, 1978, unit personnel temporarily disabled 4.16 KV Essential Bus "C1" Feeder Breaker AD110 Undervoltage Relays 27A-1/C1 and 27A-4/C1 per Reactor Coolant Pump Operating Procedure SP 1103.06, Temporary Modification T-2937. This was done to eliminate the possibility of tripping Essential Bus C1 on low voltage when RCP 1-1-1 or RCP 1-2-2 was started. At 02:50:45 hours, RCP 1-2-2 was successfully started.

At 02:54:03 hours, operations personnel, intending to start RCP 1-1-1, started RCP 1-1-2 instead. When RCP 1-1-2 was started, it depressed the voltage of its supply bus, 13.8 KV Bus "B". The 4.16 KV Essential Bus "D1", which is also supplied from Bus "B" through Bus Tie Transformer "BD", suffered a proportional voltage drop which caused Essential Bus "D1" Feeder Breaker AD110 Undervoltage Relays 27A-1/D1 and 27A-4/D1 (still in service) to trip Feeder Breaker AD110 and de-energize Essential Bus D1 at 02:54:08 hours.

The loss of power initiated an emergency start of Emergency Diesel Generator 1-2. As a result, Essential Bus "D1" was re-energized, and its voltage was returned to normal at 02:54:18 hours.

The loss of power to Essential Bus "D1" placed the unit in the Action Statement of Technical Specification 3.8.2.1, which states that 4.16 KV Essential Bus "D1" must be operable and energized while in Mode 3.

The total time in which Essential bus "D1" was de-energized was ten seconds. During an NRC Exit Interview on December 22, 1978, it was determined that this incident was reportable and that disabling the essential bus undervoltage relays as described in Modification T-2937 was contrary to Technical Specification 3.8.2.1.

Designation of Apparent Cause of Occurrence: This incident was caused by personnel error and by design deficiencies. Operations personnel started RCP 1-1-2 instead of RCP 1-1-1; Essential Bus "D1" Feeder Breaker AD110 Undervoltage Relays were still in service and the start of RCP 1-1-2 and the resultant voltage depression caused Essential Bus "D1" to trip. Bus voltage depression caused by starting large motors

such as the Reactor Coolant Pumps necessitated the temporary removal of the essential bus feeder breaker undervoltage relays. This action left the affected bus without undervoltage protection.

Analysis of Occurrence: There was no danger to the health and safety of the public or to unit personnel. The unit was subcritical at the time of the incident. There was only a brief interruption in essential equipment operation as Essential Bus "D1" was re-energized within ten seconds.

Corrective Action: At 02:54:18 hours, the 4.16 KV Essential Bus "D1" was re-energized. At 03:00:38 hours, Essential Bus "D1" was transferred back to its normal power supply and Emergency Diesel Generator 1-2 was returned to normal standby status. Operations personnel have been instructed to be more alert when starting unit equipment.

Modification T-2937 has been replaced by Modification T-3444. T-3444 transfers the affected essential bus's power supply from its normal 13.8 KV/4.16 KV bus tie transformer to the alternate 13.8 KV/4.16 KV bus tie transformer during the start of a Reactor Coolant Pump.

Facility Change Requests 77-430 and 77-430 Supplement 2 were written to request provisions for momentary bypassing of the undervoltage relays when starting the Reactor Coolant Pumps and to change the Technical Specifications to allow the undervoltage relays to be momentarily bypassed when starting Reactor Coolant Pumps and Circulating Water Pumps.