LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOCK:
0 1	A R A N 0 2 3 0 0 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
O 1	REPORT LL 6 0 5 0 0 0 3 6 8 7 1 2 2 7 7 8 8 0 1 12 5 7 9 9 EVENT DESCRIPTION AND RECORD TO A TE 80
0 2	L Mode 1 operation, during Main Turbine roll, Main Steam relief valve
0 3	2PSV1053 lifted, due to steam dump valve failures (reference LER
04	L50-368/78-39), and failed to reseat, causing the RCS temperature to
05	drop 107°F within 52 minutes, exceeding 100°F/hr. limit per T.S.3.4.9.1.b
0 6	for an approximate 10 minute period. No similar occurrences. Reportable
07	per T.S.6.9.1.9(b).
0 8	
0 9 8	SYSTEM CODE CODE SUBCODE SUBCO
	LER/RO EVENT YEAR REPORT NO. OCCURRENCE REPORT TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB SUPPLIER ACTION AND CORRECTIVE ACTIONS (27)
10	The relief valve reseated after > 1 hour of blowdown. RCS Tave was re-
11	stored to 545°F within 30 minutes as required by Action Statement
1 2	T.S.3.4,9.1. An engineering evaluation was performed by the NSSS vendor
13	to determine the effects on the fracture toughness properties of the RCS.
14	It was determined that the RCS remains acceptable for continued operation.
1 5	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF HELEASE 36
	050000000 PURGO - 000
1 7	PERSONNEL EXPOSURES TUMBER TYPE O O O O O O O O O O O O O O O O O O O
1 7 8 1 8	PERSONNEL EXPOSURES NUMBER TYPE O O O O O O O O O O O O O O O O O O O
1 7 8 7 8 1 8 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 9 11 12 13 80 80 80 11 9 11 12 13 80 80 80 80 80 80 80 80 80 80 80 80 80
1 9 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41) 0 0 0 0 0 NA 9 SESCRIPTION 41 12 NA 80 80 80 80 80 80 80 80 80 8