(7.77)	U.S. NUCLEAR REGULATORY COMMISSION
	CONTROL BLOCK:
	$ \begin{array}{ c c c c } \hline 0 & H & D & B & S & 1 \\ \hline 9 & LICENSEE CODE & 14 \\ \hline 14 & 15 \\ \hline 16 $
CON'T	REPORT L 6 0 5 0 - 0 3 4 6 0 0 1 0 9 7 9 8 0 2 0 5 7 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
02	On 1/9/79, during surveillance testing Containment Recirculation Fan 1-1 failed to run;
03	Attempts to reset the breaker and start the fan failed. This placed the unit in the
04	Action Statement of Technical Specification 3.6.4.2. This required the one inoperable
05	Containment Recirculation System to be restored to an operable condition within 30
06	days. There was no danger to the health and safety of the public or unit personnel.
07	The standby Containment Recirculation Fan 1-2 was operational. (NP-33-79-08)
	9
	SYSTEM CODE SUBCODE SU
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
10	[The connections, contacts and components for the controller were inspected. Although]
11	no exact cause has been determined, the cause has been attributed to the buildup of a
12	non-conductive film on the auxiliary controller contacts. The contacts were cleaned.
13	The fan was satisfactorily tested and declared operable. The unit was removed from
14	the Action Statement of Technical Specification 3.6.4.2.
15	ACILITY STATUS B B C B C B C C C C C C C C C C C C C
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 2 33 2 34 NA 9 PERSONNEL EXPOSURES 44 45 80
17 78	PERSONNEL INJURIES OF A STATE OF
18	
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION Z (42) NA
20	9 10 80 9 PUBLICITY 9 SSUED DESCRIPTION (45) NRC USE ONLY N (4) NA
R 79-0	9 10 68 69 80-3 110 NAME OF PREPARER Rick Naylor PHONE 419-259-5000, Ext. 252 3

2.45

t