

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1	L	6	0	5	0	0	0	2	8	2	7	0	5	2	5	7	9	8	0	6	2	2	7	9	9
7	8	60	61	DOCKET NUMBER						68	69	EVENT DATE				74	75	REPORT DATE						80		

0 2 | During refueling shutdown, both NIS source range channels were lost for about three  
0 3 | minutes when all power range channel control power fuses were pulled for installation  
0 4 | work for a Design Change. (When the fuses were pulled all power range channels  
0 5 | tripped high simulating power above the Pl0 permissive and blocking source range  
0 6 | high voltage) No effect on public health and safety. Not repetitive (a once-  
0 7 | only procedure).

SYSTEM CODE I A ⑪		CAUSE CODE D ⑫		CAUSE SUBCODE Z ⑬		COMPONENT CODE I N S I R U ⑭		COMP. SUBCODE I ⑮		VALVE SUBCODE Z ⑯	
LER-RO REPORT NUMBER ⑰		EVENT YEAR 7 9 ⑱		SEQUENTIAL REPORT NO. 0 1 7 ⑳		OCCURRENCE CODE 0 3 ㉑		REPORT TYPE L ㉒		REVISION NO. 0 ㉓	
ACTION TAKEN X ⑲		FUTURE ACTION G ㉔		EFFECT ON PLANT Z ㉕		SHUTDOWN METHOD Z ㉖		HOURS 0 0 0 ㉗		ATTACHMENT SUBMITTED N ㉘	
								NPRD-4 FORM SUB. N ㉙		PRIME COMP. SUPPLIER N ㉚	
										COMPONENT MANUFACTURER Z 9 9 ㉛	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Procedure error. Fuses were quickly reinstalled. Procedure was changed to call

1 1 | for pulling power range fuses one at a time for the installation work.

1 2 \_\_\_\_\_

1 3 \_\_\_\_\_

1 4 \_\_\_\_\_

1 5 H 28 0 0 0 29 NA 30 31 A 32 Operator observation 33 34 Z 35 NA 36 NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES												
NUMBER				DESCRIPTION								
1	2	3	4	5	6	7	8	9	10	11	12	
0	0	0	0	40	NA							41

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 9 2 (42) NA

PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N (44) NA  
7 8 9 10 68 69 70

NAME OF PREPARER A. A. Hunstad

PHONE: 612-388-4767

7906270/65 5