LICENSEE EVENT REPORT

EIGENGEE CYENT HEI ONT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
1 I I I S 2 2 0 0 - 0 0 0 0 - 0 0
CON'T 0 1 SOURCE L 6 0 5 0 0 3 0 4 7 0 4 2 3 7 9 8 0 5 2 2 7 9 9 8 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 86
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2 While changing starting batteries on the 2C diesel driven CS pump,
[0]3 the spray system was inadvertently rendered inoperable without first
[0]4] performing required surveillance (T.S.4.6.1.C). The pump was inoper-
able for approximately eight hours. This is the second occurrence of
this type. (Previous LER 50-295/78-66). Public Health and safety
were not affected because redundant systems were verified operable upon
discovery of error.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
SEQUENTIAL REPORT NO. TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32
ACTION FUTURE SEFECT SHUTDOWN HOURS 22 ATTACHMENT NORD-4 PRIME COMP. COMPONENT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER MANUFACTURER SUPPLIER SU
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1 6 Cause was personnel error. Local battery selector switch placed in
[Ti] ["manual" position, negating safeguards starting capability. Switch
was returned to "Auto" position for safeguards. Warning signs were
posted on control board and local panel. Personnel were misled about
operation of multi-position switch. Station is evaluating modifying switch
7 8 9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 5 E 28 0 7 5 29 NA 3 Operator Observation 7 8 3 10 10 12 13 44 45 46 80
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
7 8 9 PERSONNEL INJURIES 13 NUMBER DESCRIPTION (41) NA 2274 276
1 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTION (45) NA 7906060776 NRC USE ONLY
Alan T. Krawczak (312) 746-2084