(7.77)LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 3 4 CON'T 0 1 0 3 2 4 7 0 5 1 9 7 9 8 0 6 1 5 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operator surveillance of the control panel, the operator noticed that 0 2 | 2-CAC-ATH-1263-2 was providing a downscale reading. When this instrument was returned 0 3 to service, 2-CAC-ATH-1259-2 was checked and found out of calibration. 0 4 instruments monitor oxygen concentration in the drywell. (Technical Specifications 3.6.6.4.6.9.1.9b) 0 7 SYSTEM CAUSE CAUSE COMP CODE COMPONENT CODE SUBCODE 0 9 SEQUENTIAL OCCURRENCE REPORT REVISION LER/RO REPORT NO. CODE NO. REPORT 13 0 NUMBER EFFECT ON PLANT SHUTDOWN NPRD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT ATTACHMENT SUBMITTED HOURS (22) (18) Z 0 0 0 Y 24 (25 13 A CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 1 0 instruments were out of calibration. They were recalibrated and returned to A monthly calibration was implemented in July 1978, due to excessive instrument drifting. As this is the second occurrence of being out of calibration in the past month, the calibration frequency for the CAC-ATH-1259 and CAC-ATH-1263 is 1 4 being changed to a two week interval, OTHER STATUS (30) METHOD OF % POWER DISCOVERY DESCRIPTION (32) E (28) 0 2 0 (31) Operator Surveillance ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) OF RELEASE Z 33 Z 34 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER 0 0 (37) Z (38) PERSONNEL INJURIES 2347 272 DESCRIPTION (41) NUMBER 12 LOSS OF OR DAMAGE TO FACILITY DESCRIPTION PUBLICITY DESCRIPTION (45) NRC USE ONLY 7906220420 N (44)

919-457-6701

PHONE:

NAME OF PREPARER A. C. Tollison, Jr.