

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

January 18, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Serial No. 056  
PO/MTC/baw  
Docket No. 50-339

Dear Mr. O'Reilly:

Pursuant to the provisions of 10CFR 50.55(e), the NRC Region II was notified on December 20, 1979, that the differential pressure switches on the service water strainers to the Unit 2 control room air conditioning chillers were not seismically qualified. These switches (PDS-HV-2223 A and B) serve to automatically initiate operation of self-cleaning strainers HV-S-1A and 1B on high differential pressure.

Equivalent differential pressure switches, with previous seismic qualification on file, have been ordered to replace the existing switches. This replacement will be completed prior to initial fuel loading of North Anna 2.

This report constitutes our final report on this matter. If further information is required please contact this office.

Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

cc: Mr. Victor Stello, Director  
Office of Inspection and Enforcement

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation

B019  
SE  
1/0

S

8001230, 122