

LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 O H D B S 1 2 Ø Ø - Ø Ø N P F - Ø 3 3 4 1 1 1 1 4 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	-	0	3	4	6	7	0	5	1	7	7	9	8	0	6	1	3	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On May 17, 1979, a hole was discovered through a fire barrier floor which had not been

0 3 sealed. Technical Specification 3.7.10 requires all penetration fire barriers to be

0 4 functional at all times. The hole was through the floor of essential low voltage

0 5 switchgear room 428. Conduit filled most of the hole, but the gap between the hole

0 6 and the conduit had not been sealed. There was no danger to the health and safety of

0 7 the public or station personnel. The gap was no wider than 3/8 inch, and there were

0 8 no combustible materials in the immediate area. (NP-33-79-61)

SYSTEM CODE A B (11)		CAUSE CODE D (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE Z Z Z Z Z Z Z (14)						COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)			
EVENT YEAR 7 9 (21) (22)		SEQUENTIAL REPORT NO. 0 5 9 (24) (25) (26)		OCCURRENCE CODE 0 3 (28) (29)		REPORT TYPE L (30)		REVISION NO. 0 (32)									
ACTION TAKEN X (18)		FUTURE ACTION H (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22) (23) (24) (25)		ATTACHMENT SUBMITTED Y (26)		NPRD-4 FORM SUB. N (27)		PRIME COMP. SUPPLIER Z (28)		COMPONENT MANUFACTURER Z 9 9 9 (29) (30) (31) (32)	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (33)																	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Station personnel did not complete a survey of all previously completed work items

1 1 since this hole was drilled on 10/2/78, and a similar occurrence was reported on

1 2 11/24/78. The gap was sealed within one hour of notification by QC personnel.

1 3 ST 5016.11 is being conducted to verify no further such violations exist. A training

1 4 meeting was held with maintenance and construction supervisors.

7 8 9 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 OTHER STATUS 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 METHOD OF DISCOVERY 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 DISCOVERY DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA 44

NA LOCATION OF RELEASE (36) 45 80

7		8		9		10		11		12		13		14		15		16		17	
PERSONNEL EXPOSURES																					
NUMBER						TYPE		DESCRIPTION (39)													
1	7	0	0	0	(37)	Z	(38)	NA													

2353 301

PERSONNEL INJURIES		DESCRIPTION		(41)
NUMBER				
1	2	3	4	5
0	0	0	(40)	NA

7	8	9	11	12
LOSS OF OR DAMAGE TO FACILITY (43)				
TYPE		DESCRIPTION		
7	(42)	NA		

7 8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
7906180551  
NRC USE ONLY

2 0 N NA 68 69  
7 8 9 10  
RPN 30 073 Richard W. Naylor PHONE: 419-259-5000, Ext. 252

NRC USE ONLY

7906180551

PHONE: 419-259-5000, Ext. 252

017-926

TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE  
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-61

DATE OF EVENT: May 17, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Failure to fire block a core drill through a fire barrier.

Conditions Prior to Occurrence: The unit was in Mode 5, with Power (MWT) = 0, and Load (Gross MWE) = 0.

Description of Occurrence: On May 17, 1979, it was discovered that during the implementation of Facility Change Request (FCR) 78-373, which was the installation of several new electrical system feeders, a core drill had been made through the floor of essential low voltage switchgear room 428. Technical Specification 3.7.10 requires all penetration fire barriers protecting safety related areas shall be functional at all times. The Action Statement requires that if a fire barrier is not functional, a continuous fire watch be established on at least one side of the affected penetration within one hour.

This penetration remained unblocked from approximately October 2, 1978 until May 17, 1979.

This report is being submitted in accordance with Technical Specification 6.9.1.9c.

Designation of Apparent Cause of Occurrence: The instructions for the implementation of FCR 78-373 did not identify the significance of a fire wall and also failed to state any requirements of the Technical Specification 3.7.10. When a previous similar occurrence was discovered (see Licensee Event Report NP-33-78-137), the Facility Change Request was modified to assure all subsequent work was performed in accordance with technical specifications. However, plant personnel did not complete a comprehensive survey of all previously completed work items to insure that the requirements were met.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. The fire barrier affected only provides protection for one of two separate essential buses. The only open path was the gap between the conduit and the hole in the floor which was not wider than 3/8 inch. There were no combustible materials in the immediate area.

Corrective Action: Within one hour of notification from station Quality Control personnel, the penetration was blocked. Surveillance Test ST 5016.11 is being conducted to identify any further unblocked fire barrier penetrations. An information meeting was conducted with maintenance and construction supervisory personnel instructing them on fire barrier requirements and of the station procedures pertaining to the proper method of working on fire barriers.

Failure Data: There has been one previously reported similar occurrence, see Licensee Event Report NP-33-78-137.

LER #79-059

2353 303