LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT 58
CON'T 0 1 REPORT L 6 0 5 0 - 0 3 2 4 7 1 2 1 5 7 8 8 0 1 1 5 7 9 9
During the performance of "HPCI Steamline High Differential Pressure Channel Test"
(P.T.2.1.1 P) on 12/15/78, instrument E41-DPIS-NO05 failed to operate due to an
inoperable relay. The HPCI system would have operated normally except when a steam
ols line high flow signal was received. Inboard HPCI isolation valve E41-F002 would not
have closed, but outboard isolation valve E41-F003 would have. (Technical Specifica-
0 7 tion 3.3.2).
0 B L 8 9
SYSTEM CAUSE CODE SUBCODE SUBC
LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER H 18 H 19 Z 20 Z 21. 0 0 0 0 0 Y 23 N 24 Z 25 Z 19 9 9 9 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Maintenance work on the relay was performed on 12/4/78 during which a relay wire was
not returned to its proper position. The wire was left unterminated. A technician
doing the maintenance work did not follow the wire removal procedure or demonstrate
system operability after work was completed. Immediately after discovery of the im-
proper wire position on 12/15/78, the wire was reterminated and P.T. 2.1.1 P completed
FACILITY STATUS
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 N/A N/A LOCATION OF RELEASE 36 N/A N/A 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 7 8 9 PERSONNEL INJURIES 13 80
1 B O O O O O O O O O O O O O O O O O O
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
7 8 9 10 PUBLICITY ISSUED DESCRIPTION 45 N/A N/A 7901230138 NRC USE ONLY
7 8 9 10 68 69 80 NAME OF RESPARSE A. C. Tollison, Jr. 840NE, 919-457-6701

LER SUPPLEMENT -- RO# 2-78-77

Facility: BSEP Unit #2 Event Date 12/15/78

Cause Description and Corrective Actions, Cont'd.

satisfactorily that same day. This event will be reviewed by all I&C Technicians and Electricians. The review will include a presentation of both wire removal procedures and system operability requirements after maintenance work has been performed. This should prevent similar events from occurring.