

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(IF USE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 11LQAD2 2000-000-000 3411111 4 5
8 9 14 15 25 26 30 57 CAT 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

DON'T 1 L05000265 7021179 8030679 9
61 69 74 75
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

While the shutdown cooling mode of RHRS was being taken off, suction isolation
 valve M0 2-1001-50 failed to close from the control room. The safety implications
 of this occurrence are minimal due to the fact the second isolation valve, M0 2-1001-47,
 in the shutdown cooling line is fully operable. Because the requirements of
 Technical Specification 3.7.D.3 have been met, reactor power operation will be
 continued.

SYSTEM CODE SD E A VALVOP A Z
9 10 11 12 13 14 15 16
 CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE
 LER/RO REPORT NUMBER 79 004 03 L 0
21 22 23 24 25 26 27 28 29 30 31 32
 EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 ACTION TAKEN X B Z Z 0000 Y Y N L200
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
 FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

An initial investigation indicated a component failure of the circuit breaker in
 the valve's motor control center. The M0 2-1001-50 valve was electrically taken
 out-of-service, closing the valve. During an outage when the valve can be appropriately
 operated and tested, the necessary repairs will be made.

FACILITY STATUS G 000 NA A Operational Event
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY NA NA NA
5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION NA
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 PERSONNEL INJURIES NUMBER DESCRIPTION NA
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION NA
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 PUBLICITY ISSUED DESCRIPTION NA 7903290035 NA
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 NAME OF PREPARER G. Tietz PHONE: 309-654-2241, ext. 247

NRC USE ONLY

08-7-215

- I. LEI. NUMBER: LER/RO 79-04/03L-0
- II. LICENSEE NAME: Commonwealth Edison Company
Quad-Cities Nuclear Power Station
- III. FACILITY NAME: Unit Two
- IV. DOCKET NUMBER: 050-265
- V. EVENT DESCRIPTION:

On February 11, 1979, Unit Two was in the REFUEL mode and the shutdown cooling mode of RHRS was operating. At 10:30 a.m., the control room operator was taking shutdown cooling off when he discovered that the suction valve, MO 2-1001-50, would not close from the control room. Upon notifying the Shift Engineer, it was decided to take the valve out-of-service by tripping the breaker and thus closing the valve. The second isolation valve, MO 2-1001-47 was also closed. There has been no previous occurrences of this nature involving the MO 2-1001-50 valve.

VI. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

The safety implications of this occurrence are minimal due to the fact the second isolation valve, MO 2-1001-47, in the shutdown cooling suction line was fully operable at all times. Therefore, had a Group II isolation signal occurred the 47 valve would have isolated the line.

VII. CAUSE:

The initial investigation indicated that equipment failure was the probable cause of this occurrence. A contact in the valve breaker was not operating properly. During a future maintenance outage, a full investigation of the problem and the necessary repairs will be completed.

VIII. CORRECTIVE ACTION:

The immediate corrective action was to take the valve out-of-service electrically, closing it. During a maintenance outage, when the valve can be appropriately operated and tested, the necessary repairs will be completed. Until that time, primary containment isolation is assured by the closure of MO-2-1001-50, and the operability of valve MO-2-1001-47.