

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 0 H D B S 1 2 0 0 - 0 0 N P F - 0 3 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE 60 61 L 6 0 5 0 - 0 3 4 6 7 0 2 0 5 7 9 8 0 2 2 8 7 9 9

DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 It was noted on February 5, 1979 by the Nuclear Regulatory Commission that a required

0 3 thirty day written report had not been submitted. As a result of surveillance testing

0 4 conducted on July 21, 1978, ten of the eighteen main steam safety valves were found

0 5 outside the setpoint range. This placed the unit in the Action Statement of Tech

0 6 Spec 3.7.1.1. The valves were returned to operable status within four hours. There

0 7 was no danger to the health and safety of the public or unit personnel. The valves

0 8 would still have served their intended function. (NP-33-79-25)

80

0 9

SYSTEM CODE 9 10 C C 11 CAUSE CODE 11 E 12 CAUSE SUBCODE 12 B 13 COMPONENT CODE 13 V A L V E X 14 COMP. SUBCODE 19 P 15 VALVE SUBCODE 20 B 16

17 LER/RO REPORT NUMBER 21 22 7 9 23 24 25 26 27 28 29 0 3 30 31 L 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

EVENT YEAR 21 22 7 9 SEQUENTIAL REPORT NO. 24 25 26 27 OCCURRENCE CODE 28 29 0 3 REPORT TYPE 30 31 L REVISION NO. 32 33

ACTION TAKEN 33 E 34 FUTURE ACTION 35 Z 36 EFFECT ON PLANT 37 Z 38 SHUTDOWN METHOD 39 Z 40 HOURS 41 0 0 0 42 ATTACHMENT SUBMITTED 43 Y 44 NRPD-4 FORM SUB. 45 Y 46 PRIME COMP. SUPPLIER 47 N 48 COMPONENT MANUFACTURER 49 D 50 2 51 4 52 3 53

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause of the variation is believed to be due to changing ambient conditions at the

1 1 location of the valves. Subsequent lifting of safety valves from numerous unit trips

1 2 may have also affected their lift setpoint. The valves were adjusted and retested

1 3 satisfactorily and declared operable by 1600 hours on July 21, 1978. Facility Change

1 4 Requests have been issued which will help control ambient conditions.

80

1 5

FACILITY STATUS 7 8 C 28 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

% POWER 29 30 NA METHOD OF DISCOVERY 31 B 32 Surveillance Test

ACTIVITY CONTENT 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

RELEASED OF RELEASE 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

AMOUNT OF ACTIVITY 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LOCATION OF RELEASE 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL EXPOSURES 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NUMBER 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

TYPE 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DESCRIPTION 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL INJURIES 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NUMBER 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DESCRIPTION 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LOSS OF OR DAMAGE TO FACILITY 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

TYPE 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DESCRIPTION 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PUBLICITY 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ISSUED 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DESCRIPTION 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

7903060475

NRC USE ONLY

68 69 70 71 72 73 74 75 76 77 78 79 80

DVR 79-029 NAME OF PREPARER Richard A. Brown PHONE: 419-259-5000, Ext. 250

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-25

DATE OF EVENT: February 5, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Main Steam Safety Valves were tested and found to be outside of $\pm 1\%$ design setpoint range

Conditions Prior to Occurrence: On July 21, 1978, the unit was in Mode 3, with Power (MWT) = 0, and load (Gross MWE) = 0.

Description of Occurrence: It was noted on February 5, 1979, by the Nuclear Regulatory Commission that a required thirty day written report covering the out of tolerance setpoint of ten main steam safety valves had not been submitted.

As a result of surveillance testing conducted on July 21, 1978, ten of the eighteen valves during the initial lift were found to be outside of $\pm 1\%$ design setpoint range.

This placed the unit in the Action Statement of Technical Specification 3.7.1.1, which required the valves to be operable in Modes 1, 2, and 3. The Action Statement required the valves to be restored to operable status within four hours or the high flux trip setpoint be reduced or the unit be in Hot Shutdown (Mode 4) within six hours and Cold Shutdown within thirty hours. The valves were returned to operable status within four hours.

Designation of Apparent Cause of Occurrence: The apparent cause of the slight variation in relief valve lift pressure is believed to be due to changing ambient conditions at the location of the valves. The ambient conditions at the location of the valves were different from the last test conducted in January, 1978.

Subsequent lifting of safety valves from numerous unit trips may have also affected their lift setpoint.

Analysis of Occurrence: There was no danger to the health and safety of the public or to unit personnel. The unit was being started up at the time of the conduct of the test. The valves would still have served their intended function of relieving pressure if a unit trip had occurred.

Corrective Action: The valves were adjusted and retested per Maintenance Work Order 78-800 and the last was declared operable by 1600 hours on July 21, 1978.

Facility Change Requests 77-322 and 77-319 have been issued for implementation to install hoods on the main steam safety valves exhaust stack for protection during the winter months and provide ventilation during the summer months. Both FCRs will help control ambient conditions. Temporary ventilation will be provided if ambient temperature becomes excessive.

Failure Data: There have been two previously reported occurrences of incorrect safety valve lift setpoints. See Licensee Event Reports NP-33-77-117 and NP-33-78-145.

LER #79-020