

Mr. Boyce M. Grier, Director
 Office of Inspection & Enforcement, Region I
 U.S. Nuclear Regulatory Commission
 631 Park Avenue
 King of Prussia, PA 19406

Update Report - Previous Report Date 3/5/79

No. 3-79-006/03L-1

Dear Mr. Grier:

This updated LER refers to setpoint drift of a time delay relay. The original LER No. 3-79-006/03L-0 was submitted March 5, 1979 and is being updated to correct an error in the listing of the component manufacturer and the cause and component subcodes. The governing Technical Specification is Table 3.2.B

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | P | B | S | 3 | 2 | 2 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
 7 8 9 | 14 15 | 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T
 G 1 | L | 6 | 0 | 5 | 0 | - | 0 | 2 | 7 | 8 | 7 | 0 | 2 | 1 | 2 | 7 | 9 | 8 | 0 | 3 | 1 | 4 | 7 | 9 | 9
 7 8 9 | 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 0 2 | While at power, during performance of a surveillance test the setpoint
 0 3 | of the B Core Spray Pump start timer was found to be 0.32 seconds less
 0 4 | than the Tech Spec limit of 5.0 seconds. Safety significance was minimal
 0 5 | since the redundant system was operable.
 0 6 |
 0 7 |
 0 8 |

SYSTEM CODE: S F (11)
 CAUSE CODE: E (12)
 CAUSE SUBCODE: B (13)
 COMPONENT CODE: R E L A Y X (14)
 COMP SUBCODE: H (15)
 VALVE SUBCODE: Z (16)
 LER NO REPORT NUMBER: 7 9 (17)
 EVENT YEAR: 7 9 (18)
 SEQUENTIAL REPORT NO.: 0 0 6 (19)
 OCCURRENCE CODE: 0 3 (20)
 REPORT TYPE: L (21)
 REVISION NO.: 1 (22)
 ACTION TAKEN: E (23)
 FUTURE ACTION: Z (24)
 EFFECT ON PLANT: Z (25)
 SHUTDOWN METHOD: Z (26)
 HOURS: 0 0 0 0 (27)
 ATTACHMENT SUBMITTED: N (28)
 NPD-4 FORM SUB.: N (29)
 PRIME COMP. SUPPLIER: N (30)
 COMPONENT MANUFACTURER: G O 8 0 (31)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 1 0 | The cause was setpoint drift on GE Model CR-2820 time delay relay. The
 1 1 | time delay relay was immediately readjusted, tested satisfactorily, and
 1 2 | returned to service.
 1 3 |
 1 4 |

FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS: N/A (30) | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION: Surveillance Test (32)
 ACTIVITY CONTENT RELEASED: Z (33) | AMOUNT OF ACTIVITY: N/A (34) | LOCATION OF RELEASE: N/A (35)
 PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION: N/A (39)
 PERSONNEL INJURIES NUMBER: 0 0 0 (40) | DESCRIPTION: N/A (41)
 LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) | DESCRIPTION: N/A (43)
 PUBLICITY ISSUED: N (44) | DESCRIPTION: N/A (45)

7903210130 NAME OF PREPARER: M. J. Cooney
 NRC USE ONLY
 PHONE: (215) 841-5020

Handwritten: Add 5/11