(7.77)	UPDATE REPORT - PREVIOUS REPORT DATE 2/0/79 LICENSEE EVENT REPORT LER 79-01/3L, Rev. 1
	CONTROL BLOCK:
	V T V X S 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T	REPORT SOURCE L 6 0 5 0 0 0 2 7 1 0 0 1 1 0 7 9 8 0 5 2 3 7 9 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	VENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
03	See attached sheet
0 4	
0 5	
06	
0 7	
0 P 7 8	B B SYSTEM CAUSE CAUSE COMP. VALVE 80
09 78	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER C 18 Z 19 Z 20 Z 21 0 0 0 0 0 0 V 40 41 23 V 42 43 25 E 0 6 5 (2 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	
11	See attached sheet
12	L
13	L
14	80
15	ACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32 LE 28 10 12 13 44 45 46 Operator Observation 80
	CTIVITY CONTENT LEASED OF RELEASE AMOUNT OF ACTIVITY 35 2 33 2 34 10 11 LOCATION OF RELEASE 36 NA 44 45 NA 80
[1]7]	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 0 (37) Z (38) NA 2015 273
7 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 80
1 8 7 8	0 0 0 40 NA
19	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA
7 8	9 10 PUBLICITY ISSUED DESCRIPTION 45 ISSUED DESCRIPTION 45
2 0	9 10 68 69 80 5
	NAME OF PREPARER W. F. Conway PHONE: 802-257-7711 790529040

LER 79-01/3L, Rev. 1 VTVYS1 05000271

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During normal operation, while performing routine maintenance, leakage was observed adjacent to a 2" flange on the Reactor Water Cleanup System suction piping. Investigation revealed a through wall leak near the piping weld between the 2" flange and the adjoining tee. Further investigation revealed a through wall leak in the spare nozzle of the Electro Chemical Potential Autoclave located upstream of the 2" flange. The Reactor Cleanup System was secured, the flange replaced, and the spare nozzle connection repair welded.

Conductivity monitoring of main coolant was shifted to the recirculation loop sample point during the repairs. The RWCU System was returned to service approximately 19 hours after the discovery. Reactor water chemistry was maintained within Tech. Spec. limits and there were no consecuences to the health and safety of the public. A similar incident was reported as RO 77-22/1P.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause of the cracks in the Reactor Water Cleanup weld neck flange is Intergranular Stress Corrosion. The cracks initiated on the inside surface parallel to the weld in the sensitized heat affected zone adjacent to the weld and were intergranular in nature. One crack completely penetrated the wall of the flange. No fatigue striations were found. The appearance of the cracking indicates typical boiling water reactor type stress - corrosion cracking with residual stresses from welding or possibly slow cyclic bending stresses as being the scurce of the tensile stress.

2045 274