

POOR ORIGINAL

Dear Mr. Griest:

This L.E.R. refers to the failure of a main steam radiation monitor. The governing Technical Specification is Table 3.1.1.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

1. LEASE PRINT OR TYPE ALL REQUIRED INFORMATION

1. PLANT REGION: 1 2 3 4 5 6 7 8 9 0

2. PLANT NAME: P A B C D E F G H I J K L M N O P Q R S T U V W X Y Z

3. PLANT NUMBER: 1 2 3 4 5 6 7 8 9 0

4. EVENT DATE: 1 2 3 4 5 6 7 8 9 0

5. REPORT DATE: 1 2 3 4 5 6 7 8 9 0

6. EVENT DESCRIPTION AND PROBABLE CAUSE(S) (REQUIRED):

While at power during surveillance tests on the main steam line radiation monitors, the 'D' monitor failed to actuate the hi-11 trip to initiate a 'B' channel 1/2 scram and Group I isolation. The monitor was immediately placed in the tripped position. Previous similar occurrence was 3-79-17/3L.

7. MONITOR LOGS: I A X Z INSTRU E Z

8. COMP SUBCODE: 1 2 3 4 5 6 7 8 9 0

9. VALVE SUBCODE: 1 2 3 4 5 6 7 8 9 0

10. REPORT TYPE: 1 2 3 4 5 6 7 8 9 0

11. PLANT REGION: 1 2 3 4 5 6 7 8 9 0

12. MANUFACTURER: C Z Z Z 0 0 0 N Y N G 0 6 6 0

13. CHOICE DESCRIPTION AND CORRECTIVE ACTION(S) (REQUIRED):

The defective radiation monitor was replaced with a similar monitor within 2 hours. Bench tests could not duplicate the failure mode. As a precautionary measure, test switch contacts were cleaned and transistors and diodes that drive the trip actuating relays were replaced. The monitor unit was tested and returned to service in another location.

14. METHOD OF DISCOVERY: E 0 9 15 NA

15. DISCOVERY DESCRIPTION: B Surveillance Testin.

16. REASON FOR DISCOVERY: 1 2 3 4 5 6 7 8 9 0

17. LOCATION OF RELEASE: NA

18. PERSONNEL INVOLVED: 1 2 3 4 5 6 7 8 9 0

19. DESCRIPTION: 1 2 3 4 5 6 7 8 9 0

20. MANUFACTURER: 1 2 3 4 5 6 7 8 9 0

21. NAME OF OPERATING FACILITY: 1 2 3 4 5 6 7 8 9 0

22. FACILITY: 1 2 3 4 5 6 7 8 9 0

23. NAME OF MANUFACTURER: 1 2 3 4 5 6 7 8 9 0

M. J. Co...
 80 81 82 83 84 85 86 87 88 89
 (215) 841-403
 8002110
 S
 PDF