

LICENSEE EVENT REPORT

CONTROL BLOCK: [1] [] [] [] [] [] [] [] [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [7] [8] [9] W I P B H 1 [2] [0] [0] [-] [0] [0] [0] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [1] [4] [] [] [5]
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T [0] [1] [7] [8]
 REPORT SOURCE [L] [6] [0] [5] [0] [0] [0] [2] [6] [6] [7] [1] [2] [2] [6] [7] [9] [8] [0] [1] [0] [9] [8] [0] [9]
DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 [0] [2] [7] [8] [9] During steady state operation, the "B" safety injection pump failed to
 [0] [3] [7] [8] [9] start during an operational and system leak test because the power
 [0] [4] [7] [8] [9] supply breaker did not completely close when the pump was returned to
 [0] [5] [7] [8] [9] service following a cold shutdown of the unit 12-11-79. The unit was
 [0] [6] [7] [8] [9] taken critical at 1941 hours on 12-22-79 and operated with one brief
 [0] [7] [7] [8] [9] shutdown until 0430 on 12-26-79 with only one safety injection pump
 [0] [8] [7] [8] [9] operational because of incomplete breaker closure on the second pump.

[0] [9] [7] [8]	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE		
[S] [F] [11]	[A] [12]	[B] [13]	C K T B R K [14]	[A] [15]	[Z] [16]			
(17) [L] [R] [R] [O] [R] [E] [P] [O] [R] [T] [N] [U] [M] [B] [E] [R]	EVENT YEAR		SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.		
[7] [9]	[] []	[0] [2] [2]	[] [] [] []	[T] []	[0]			
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
[X] [18]	[G] [19]	[Z] [20]	[Z] [21]	[0] [0] [0] [0]	[Y] [23]	[N] [24]	[N] [25]	W 1 2 0 [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 [1] [0] [7] [8] [9] When discovered, the incompletely closed breaker was completely closed
 [1] [1] [7] [8] [9] and the safety injection pump test was satisfactorily completed. To
 [1] [2] [7] [8] [9] prevent future occurrence of this event, the safety injection pump
 [1] [3] [7] [8] [9] return to service procedure following a cold shutdown will be modified
 [1] [4] [7] [8] [9] to include an operational check.

FACILITY STATUS [E] [28] **% POWER** [0] [7] [8] [29] **OTHER STATUS** [N/A] [30] **METHOD OF DISCOVERY** [C] [31] **DISCOVERY DESCRIPTION** [Operator observation] [32]

ACTIVITY RELEASED [Z] [33] **CONTENT OF RELEASE** [Z] [34] **AMOUNT OF ACTIVITY** [N/A] [35] **LOCATION OF RELEASE** [N/A] [36]

PERSONNEL EXPOSURES
NUMBER [0] [0] [0] [37] **TYPE** [Z] [38] **DESCRIPTION** [N/A] [39]

PERSONNEL INJURIES
NUMBER [0] [0] [0] [40] **DESCRIPTION** [N/A] [41]

LOSS OF OR DAMAGE TO FACILITY
TYPE [Z] [42] **DESCRIPTION** [N/A] [43]

PUBLICITY ISSUED
DESCRIPTION [N/A] [45]

NAME OF PREPARER C. W. Fay PHONE 414/277-2811

8001240
427
1794 143

ATTACHMENT TO LICENSEE EVENT REPORT NO. 79-022/01T-0

Wisconsin Electric Power Company
Point Beach Nuclear Plant Unit 1
Docket No. 50-266

On December 11, 1979, the unit was taken off line and placed in cold shutdown for steam generator eddy current inspection and tube plugging. As required by NRC, the pumps were removed from service by racking out the pump breakers to prevent the possibility of overpressurization of the reactor coolant system due to an inadvertent start of the pumps during the cold shutdown. The safety injection pumps were returned to service on December 22, 1979, prior to the unit being taken critical at 1941 hours on the same day. Following a reactor trip before the generator was phased, the reactor was again taken critical at 0153 hours on December 23, 1979. The unit was placed on line at 0430 hours on December 23, 1979, and was operating at steady state 78% power when the "B" safety injection pump failed to start during an operational system leak test at 0430 hours on December 26, 1979.

Proper valve and electrical lineup was verified; however, investigation revealed that the power supply breaker was approximately one inch open from its closed position, although the control room pump status lights indicated the breaker was closed. The breaker was properly closed, and the operational system leak test was satisfactorily performed at 0450 hours the same day. An operational test of the "A" safety injection pump had been satisfactorily completed prior to discovering the problem with "B".

Because of incomplete closure of the "B" safety injection pump breaker when returned to service, only one safety injection pump was operable when the unit was initially taken critical at 1941 hours on December 22, 1979, and until discovery and correction of the problem at 0430 hours on December 26, 1979. This violates Technical Specification 15.3.3.A.1.c and 15.3.3.A.2.a.

To prevent future occurrence of this event, the safety injection pump return to service procedure following a cold shutdown will be modified to include an operational check similar to that currently performed following any refueling outage or maintenance of the pumps.

The event is reportable in accordance with Technical Specification 15.6.9.2.A.2.