

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 14 15 25 26 30 37 38  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT  
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 9 | 7 | 0 | 2 | 0 | 1 | 8 | 0 | 8 | 0 | 2 | 2 | 9 | 8 | 0 | 9  
7 8 60 61 68 69 74 75 80  
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 0 2 | With Unit 1 in a scheduled refueling outage, preventative maintenance \_\_\_\_\_  
 0 3 | revealed damaged electrical and mechanical overspeed protection assemblies \_\_\_\_\_  
 0 4 | on the reactor core isolation cooling turbine. There was no danger to the \_\_\_\_\_  
 0 5 | health or safety of the public, no release of activity, and no significant \_\_\_\_\_  
 0 6 | resulting occurrences. See Technical Specifications 3.5.F.1. There have been \_\_\_\_\_  
 0 7 | no previous similar occurrences. Since the plant was in cold shutdown redundancy \_\_\_\_\_  
 0 8 | was not required. \_\_\_\_\_

0 9 | C | E | 11 | D | 12 | Z | 13 | I | N | S | T | R | U | 14 | C | 15 | Z | 16 |  
9 10 11 12 13 14 15 16 19 20  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
 17 | 8 | 0 | 0 | 1 | 2 | 0 | 3 | L | 0 |  
21 22 23 24 26 27 28 29 30 31 32  
 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER  
 G 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 L 25 T 1 4 7  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 1 0 | Unclear installation instructions in the terry turbine manual resulted in \_\_\_\_\_  
 1 1 | damaging the electronic overspeed, which in turn may have allowed damage to the \_\_\_\_\_  
 1 2 | mechanical overspeed. Both overspeed assemblies were repaired and the manual \_\_\_\_\_  
 1 3 | clarified. Overspeed trip tests will be run when unit is returned to operational \_\_\_\_\_  
 1 4 | readiness. \_\_\_\_\_

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | B | 31 | Preventative Maintenance | 32  
7 8 9 10 12 13 44 45 46 80  
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | NA | NA | 36  
7 8 9 10 11 44 45 80  
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
7 8 9 11 12 13 80  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA | 41  
7 8 9 11 12 80  
 PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43  
7 8 9 10 80  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45  
7 8 9 10 68 69 80  
 PUBLICLY ISSUED DESCRIPTION NRC USE ONLY

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8012 Technical Specification Involved 3.5.F.1  
Reported Under Technical Specification 6.7.2.b.2  
Date of Occurrence 2-1-80 Time of Occurrence 2:00 pm Unit 1

Identification and Description of Occurrence:

While disassembling the RCIC Terry Turbine during preventative maintenance it was discovered that the electrical and mechanical overspeed trip mechanisms were damaged.

Conditions Prior to Occurrence:

Unit 1 - scheduled refueling outage  
Unit 2 - 76% steady state power  
Unit 3 - 94% steady state power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

NA - Unit in refueling outage

Apparent Cause of Occurrence:

Unclear installation instructions in the Terry Turbine manual resulted in damage to the electrical overspeed which may have damaged the mechanical overspeed.

Analysis of Occurrence:

No danger to health or safety of the public, no release of activity, no damage to plant or equipment, no significant resulting occurrences.

Corrective Action:

Mechanical and electrical overspeed mechanisms repaired and manual clarified. Overspeed tests to be run when unit is returned to operational readiness.

Failure Data:

NA

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 