LICENSEE EVENT REPORT

EXHIBIT A

| | CONTROL BLOCK: |
|-------|--|
| 0 1 | A R A N 0 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5 57 CAT SE |
| CON'T | SOURCE 60 61 DOCKET NUMBER 60 60 EVENT DATE 74 75 HEPORT CATE 60 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) |
| 0 2 | While performing Surveillance Test 1304.70 Supplement I, CV-7444 (A hydrogen |
| 0 3 | purge supply isolation valve) failed to close. Immediately the redundate |
| 0 4 | Lvalve, CV-7443 was verified closed. There have been no similar |
| 0 5 | occurrences. Reportable per 6.12.3.2.(d). |
| 0 6 | |
| 0 7 | |
| 0 8 | 50 |
| 0 9 | SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SU |
| | LERING EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE NO. |
| | NUMBER 2: 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP COMPONENT METHOD HOURS (22) SUBMITTED FORM SUH SUPPLIER MANUFACTURER |
| | IB 18 Z 19 Z 20 JO 10 10 L 12 10 10 10 10 10 10 10 10 10 10 10 10 10 |
| 1101 | The Torque Switch contacts had oxidation on them. This caused a high |
| | resistance contact, which would not permit the valve to go closed. The |
| 1 2 | Corrosion was cleaned off the contacts and the valve was verified |
| 13 | operable. |
| 114 | |
| 15 | FACILITY STATUS STATU |
| | ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA LOCATION OF RELEASE 36 |
| 1 7 | DESCRIPTION 39 O O O O O NA NA NA NA O O O O O O O O O O O O O O O O O O O |
| 1 × | PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA |
| | LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA |
| 20, | PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY NAC USE ONLY |
| | NAME OF PREPARER Lindsley S. Bramlett PHONE 501/968-2519 |
| | 8002210 5 |