

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

01 | N | C | B | E | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5

CONT
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 2 | 5 | 7 | 1 | 2 | 1 | 8 | 7 | 9 | 8 | 0 | 1 | 2 | 9 | 8 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | While performing PT 3.1.5PC, Reactor Vessel Shroud Level Channel Calibration, switch
03 | #1 on 1-B21-LITS-N037 was found to be out of calibration. The switch was actuating
04 | at 288" H₂O, whereas the setpoint is 257.19 + 5.7" H₂O and the reportable limit is
05 | ≥ 262.94" H₂O (≥ 39 inches below top of active fuel).
06 |
07 |

08 | Technical Specification 3.3.3, 6.9.1.9a | 80

09 | SYSTEM CODE | S | F | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | G | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16 |
17 | LER NO REPORT NUMBER | 7 | 9 | 21 | 22 | SEQUENTIAL REPORT NO. | 1 | 1 | 0 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 1 | 32 |
ACTION TAKEN | E | 18 | FUTURE ACTION | G | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | Y | 23 | 41 | NPRD-4 FORM SUB. | Y | 24 | 42 | PRIME COMP. SUPPLIER | N | 25 | 43 | COMPONENT MANUFACTURER | Y | D | 1 | 0 | 44 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | It is believed that the instrument may have been bumped by scaffolding located near
11 | the instrument or that the switch operation could have been affected by the calibration
12 | of the Brooks converter, which had just been calibrated. The switch was recalibrated
13 | and returned to service. Maintenance Instruction 3-1P will be revised to require the
14 | calibration of the switches whenever the Brooks converter is calibrated. (Continued) | 80

15 | FACILITY STATUS | G | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Periodic Test | 32

16 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521

8002210520

LER CONTINUATION - RO # 1-79-110

Facility: Unit No. 1

Date: 01-29-80

These switches are to be replaced during the 1980 refueling outages with new analog instrumentation. No other instruments are affected by the calibration of the Brooks converter.