

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A L B R F 1 | 0 0 - 0 0 0 0 0 0 - 0 0 | 3 4 1 1 1 1 | 4 | 5
7 8 9 | LICENSEE CODE 14 15 | LICENSE NUMBER 25 26 | LICENSE TYPE 30 | 57 CAT 58

CON'T
0 1 | REPORT SOURCE | L | 0 5 0 0 0 2 5 9 | 7 | 0 1 2 2 8 0 | 8 | 0 2 2 0 8 0 | 9
7 8 | 60 61 | DOCKET NUMBER 68 69 | EVENT DATE 74 75 | REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During refueling operations CRD accumulator level switch on CRD unit 38-11 was found
0 3 | to be inoperable contrary to Technical Specification 3.3.A.2.e. There were no signi-
0 4 | ficant resulting events. There was no danger to health or safety of the public. No
0 5 | redundant systems. Previous occurrence: BFRO-50-260/7909.
0 6 |
0 7 |
0 8 |

0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE
I A | E | E | I N S T R U | S | Z
9 10 | 11 12 | 13 14 | 15 16
17 | LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
8 0 | - | 0 6 | 0 3 | L | - | 0
21 22 | 23 24 | 25 26 | 27 28 | 29 30 | 31 32
ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
A | Z | Z | Z | 0 0 0 0 | Y | Y | N | G o s b
33 34 | 35 36 | 37 38 | 39 40 | 41 42 | 43 44 | 45 46 | 47 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the failure of switch LS-1-305-129, Gem's Inc., liquid level switch, GE
1 1 | part NR117C1434P1, was a broken reed switch. The switch was replaced and operates
1 2 | satisfactorily. No recurrence control required. Failure was random in nature.
1 3 |
1 4 |

1 5 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
H | 0 0 0 | NA | B | Scheduled maintenance
7 8 9 | 10 11 12 | 13 14 | 15 16 | 17 18 | 19 20

1 6 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
Z | Z | NA
7 8 9 | 10 11 12 | 13 14 | 15 16

1 7 | PERSONNEL EXPOSURES | DESCRIPTION
0 0 0 | Z | NA
7 8 9 | 10 11 12 | 13 14

1 8 | PERSONNEL INJURIES | DESCRIPTION
0 0 0 | NA
7 8 9 | 10 11 12 | 13 14

1 9 | LOSS OF OR DAMAGE TO FACILITY | DESCRIPTION
Z | NA
7 8 9 | 10 11 12 | 13 14

2 0 | PUBLICITY ISSUED | DESCRIPTION
N | NA
7 8 9 | 10 11 12 | 13 14

NAME OF PREPARER _____

PHONE: _____

8002260 636

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8006 Technical Specification Involved 3.3.A.2.e

Reported Under Technical Specification 6.7.2.b.1

Date of Occurrence 1/22/80 Time of Occurrence 1430 Unit 1

Identification and Description of Occurrence:

During refueling operations CRD accumulator level switch on CRD unit 38-11 was found to be inoperable.

Conditions Prior to Occurrence:

Unit 1 @ 0%.
Unit 2 @ 77%.
Unit 3 @ 96%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe. _____

NA

Apparent Cause of Occurrence:

The cause of the failure of switch LS-1-305-129 was a broken reed switch.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

The switch was replaced and returned to service.

Failure Data:

BFRO-50-260/7909.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 