

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | D | C | C | N | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T 01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 8 | 7 | 0 | 1 | 1 | 2 | 1 | 8 | 0 | 8 | 0 | 2 | 1 | 9 | 8 | 0 | 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | During steady state operation received indication of several spurious

03 | loss of load trips on Channel B. At 2215 channel B loss of load trip

04 | unit was bypassed per T.S. 3.3.1.1. Three redundant channels remained

05 | operable throughout this event. Channel B loss of load trip unit was

06 | returned to service at 1720 hrs, on 1/23/80. LER 77-11 (U-2) describes

07 | a similar event.

09 | SYSTEM CODE | I | A | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | X | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16

9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | EVENT YEAR | 8 | 0 | 21 22 | SHUTDOWN METHOD | Z | 21 | SEQUENTIAL REPORT NO. | 0 | 0 | 4 | 24 26 | OCCURRENCE CODE | 0 | 3 | 28 29 | REPORT TYPE | L | 30 31 | REVISION NO. | 0 | 32

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN | Z | 18 | FUTURE ACTION | X | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 40 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | U | 0 | 7 | 5 | 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The cause of this event has not been determined. Matrix trip lights

11 | were not lighted. Only trip and pretrip bistable relays had actuated.

12 | Troubleshooting, including a check for grounds and inspection of field

13 | components, revealed electrical noise on input leads. However, the symptoms

14 | did not recur, and have not recurrence in the interim.

15 | FACILITY STATUS | E | 28 | % POWER | 0 | 6 | 0 | 29 | OTHER STATUS | A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32

7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | A | 38 | DESCRIPTION | NA | 39

7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

7 8 9 10 80

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

7 8 9 10 80

8002290 367

NAME OF PREPARER J. S. Lagiewski/P. G. Rizzo PHONE: (301)269-4747/4786

LER NO. 80-04
DOCKET NO. 50-318
EVENT DATE 01/21/80
REPORT DATE 02/19/80
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: (CONTINUED)

Status of the problem is being maintained as a corrective maintenance item. If the problem recurs, troubleshooting efforts will continue.