

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 | A | I | J | M | F | 1 | 2 | 0 | 0 | - | 4 | 0 | 1 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 1 | 3 | 3  
LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JU 31 CAT 3d

7 8 9 | 0 | 5 | L | 5 | 0 | 5 | 0 | 0 | 0 | 1 | 3 | 4 | 8 | 7 | 0 | 2 | 0 | 3 | 8 | 0 | 2 | 0 | 2 | 2 | 5 | 8 | 0 | 9 | 9  
REPORT SOURCE 60 67 SOCKET NUMBER 74 80 EVENT DATE 74 75 REPORT DATE 80

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 1 | At 0045 on 2-3-80, during the performance of surveillance test FNP-1-STP-610.2 (Hydraulic  
0 3 | Snubber Visual Test), component cooling water snubber CW4-R121 was declared inoperable  
0 4 | due to the reservoir line being disconnected. Tech. Spec. 3.7.9.1, in part, requires  
0 5 | snubber CW4-R121 to be operable. Tech. Spec. 3.7.9.1 action statement requirements  
0 6 | were met. Health and safety of the public were not affected.

7 8 9 \_\_\_\_\_ 80

7 8 9 | X | X | 11 | A | 12 | C | 13 | S | U | P | P | O | R | T | 14 | D | 15 | Z | 16 | 15  
SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP. SUBCODE 17 18 VALVE SUBCODE 19 20

17 | 8 | 0 | 21 | 22 | 0 | 0 | 8 | 23 | 24 | 25 | 0 | 3 | 26 | 27 | 0 | 3 | 28 | 29 | L | 30 | 0 | 31 | 0 | 32  
LER/RO REPORT NUMBER 33 34 EVENT YEAR 35 36 SHUTDOWN METHOD 37 38 HOURS 39 40 ATTACHMENT SUBMITTED 41 42 NPRO-4 FORM 549 43 44 PRIME COMP. SUPPLIER 45 46 COMPONENT MANUFACTURER 47 48

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 0 | See Attachment.  
0 1 |  
0 2 |  
0 3 |  
7 8 9 \_\_\_\_\_ 80

7 8 9 | G | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Performance of surveillance test | 32  
FACILITY STATUS 33 34 % POWER 35 36 OTHER STATUS 37 38 METHOD OF DISCOVERY 39 40 DISCOVERY DESCRIPTION 41 42

7 8 9 | Z | 33 | Z | 34 | NA | 35 | NA | 36  
ACTIVITY CONTENT 37 38 RELEASED OF RELEASE 39 40 AMOUNT OF ACTIVITY 41 42 LOCATION OF RELEASE 43 44

7 8 9 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39  
PERSONNEL EXPOSURES 40 41 NUMBER 42 43 TYPE 44 45 DESCRIPTION 46 47

7 8 9 | 0 | 0 | 0 | 40 | NA | 41  
PERSONNEL INJURIES 42 43 NUMBER 44 45 DESCRIPTION 46 47

7 8 9 | Z | 43 | NA | 44  
LOSS OF OR DAMAGE TO FACILITY 45 46 TYPE 47 48 DESCRIPTION 49 50

7 8 9 | Z | 45 | NA | 46  
PUBICITY 47 48 ASSURED DESCRIPTION 49 50

7 8 9 | N | 45 | NA | 46  
ISSUED DESCRIPTION 47 48

8002290401

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156

POOR ORIGINAL

ATTACHMENT

LICENSEE EVENT REPORT LER 80-008/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The reservoir line was not reconnected when the snubber was reinstalled following functional testing in the summer of 1979. (While the snubber was removed for functional testing, the reservoir outlet was capped.) Due to the reservoir line/snubber configuration (reservoir contained adequate fluid and reservoir line was placed next to reservoir connector such that it appeared to be connected), confirmation of operability by visual inspection was erroneously made following the testing. Personnel involved in snubber inspections have been reinstructed. The snubber was purged and vented, the line to the reservoir reconnected and the snubber was declared operable following functional testing at 1035 on 2-5-80.