

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

NAME OF PREPARER

PHONE:

8002290464

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8008 Technical Specification Involved 3.6.G & 5.6, & 6.7.2.a.9

Reported Under Technical Specification 6.7.2.b.2

Date of Occurrence 1/27/80 Time of Occurrence 1400 Unit 1

Identification and Description of Occurrence:

While painters were performing preparations for painting the HPCI turbine, a crack was observed in the coupling bearing support pedestal.

Conditions Prior to Occurrence:

Unit 1 - scheduled refueling outage; HPCI tagged for maintenance.

Unit 2 - 73% steady state power.

Unit 3 - 100% steady state power.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None - unit in cold shutdown for refueling.

Apparent Cause of Occurrence:

While warming the HPCI the unit operator noticed a water hammer in the Main Steam supply line which may have cracked the support pedestal. A formal study of the cause is in progress by the turbine maintenance section.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, and no resulting significant occurrences.

Corrective Action:

Pedestal is being replaced. Units 2 and 3 are being inspected.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 