

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4	5			
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57 CAT 58		80

0	1	L	6	0	5	0	-	0	3	2	5	7	1	0	0	2	7	9	8	0	2	2	7	8	0	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER						68	69	EVENT DATE				74	75	REPORT DATE				80		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While attempting to establish RHR service water flow for an engineering evaluation,

0 3 | the operator could not get the E11-F068B valve to open. This is the RHR service

0 4 | water flow control valve for the "B" loop subsystem. This event occurred in a similar

0 5 | manner on January 28, 1980.

0 6 | _____

0 7 | _____

0 8 | Technical Specifications 3.7.1.1, 6.9.1.9b

0	9	S	H	11	E	12	B	13	I	N	S	T	R	U	14	X	15	Z	16						
7	8	SYSTEM CODE		9	10	CAUSE CODE		11	CAUSE SUBCODE		12	COMPONENT CODE					13	COMP SUBCODE		19	VALVE SUBCODE		20		
17	LER/RO REPORT NUMBER		EVENT YEAR		SHUTDOWN METHOD		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
21	22	23	24	26	27	28	29	30	31	32															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
33	34	35	36	37	40	41	42	43	44	47															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | An investigation showed that relay R1 in the position modulator had contacts sticking,

1 1 | causing the valve to see a constant "close" signal. As the relay is a sealed unit,

1 2 | the contacts were freed by tapping the relay body by hand. A replacement relay has

1 3 | been ordered and will be installed upon receipt.

1 4 | _____

1	5	E	28	0	9	6	29	N/A	30	A	31	Operator Surveillance	32						
7	8	FACILITY STATUS		9	10	% POWER		12	13	OTHER STATUS		44	METHOD OF DISCOVERY		45	DISCOVERY DESCRIPTION		46	80
1	6	Z	33	Z	34	N/A	35	N/A	36	N/A	36								
7	8	ACTIVITY RELEASED		9	10	CONTENT OF RELEASE		11	AMOUNT OF ACTIVITY		44	LOCATION OF RELEASE			45	80			
1	7	0	0	0	37	Z	38	N/A	39										
7	8	PERSONNEL EXPOSURES		9	10	NUMBER		11	TYPE		12	DESCRIPTION				13	80		
1	8	0	0	0	40	N/A	41												
7	8	PERSONNEL INJURIES		9	10	NUMBER		11	DESCRIPTION							12	80		
1	9	Z	42	N/A	43														
7	8	LOSS OF OR DAMAGE TO FACILITY		9	10	TYPE		11	DESCRIPTION							12	80		
1	9	Z	42	N/A	43														
2	0	N	44	N/A	45														
7	8	PUBLCITY ISSUED		9	10	DESCRIPTION		11	80										

LER CONTINUATION - RO #1-79-76

Facility: BSEP Unit No. 1

Event Date: October 2, 1979

Upon occurrence of the second event, an extensive search was performed to find a replacement relay, as the vender could not provide those on order for at least another month. A relay was located, purchased, and is being flown to the site, and is in the process of being installed.