


FGE



Portland General Electric Company
Trojan Nuclear Plant
P.O. Box 439
Rainier, Oregon 97048

March 7, 1980
CPY-243-80

Mr. R. H. Engelken, Director
Nuclear Regulatory Commission, Region V
1990 North California Blvd.
Walnut Creek, California 94596

Dear Sir:

In accordance with the Trojan Plant Operating License, Appendix A, US NRC Technical Specifications, Paragraph 3.7.1.2, attached is Licensee Event Report No. 80-02. This report identifies a situation where the diesel driven auxiliary feedwater pump was inoperable due to a broken cooling water hose.

Sincerely,

C. F. Yundt
General Manager

CPY/JCP:na
Attachments

c: LER Distribution List

A002
3/11

5
8008180 383

REPORTABLE OCCURRENCE

1. Report No.: 80-02
2. a. Report Date: March 7, 1980
b. Occurrence Date: February 7, 1980
3. Facility: Trojan Nuclear Plant, P. O. Box 439, Rainier, Oregon 97048
4. Identification of Occurrence:

During a routine room inspection a flexible jacket cooling water hose was found to be broken on the diesel driven auxiliary feedwater pump.

5. Conditions Prior to Occurrence:

The plant was in Mode 1 at 90% of rated power.

6. Description of Occurrence:

A routine shift inspection of the diesel driven auxiliary feedwater pump room discovered a broken flexible hose on the jacket cooling water system.

7. Designation of Apparent Cause of Occurrence:

The apparent cause of this event is attributed to deterioration of the rubber hose.

8. Analysis of Occurrence:

This event had no effect on either plant or public safety. The redundant auxiliary feedwater pump was operable and available for use if required.

9. Corrective Action:

The immediate corrective action was to take the diesel driven auxiliary feedwater pump out of service and replace the flexible hose. The permanent corrective action was to initiate a flexible hose inspection and replacement program for that engine.