MEMORANDIM FOR: Karl V. Seyfrit, Chief

Reactor Operations Analysis Branch Office for Analysis and Evaluation

of Operational Data

FROM:

Dorothy J. Zukor, Engineer Reactor Systems Section 2

Reactor Operations Analysis Branch Office for Analysis and Evaluation

of Operational Data

SUBJECT:

TECHNICAL REVIEW REPORT: "FLOODING OF SAFETY-RELATED VALVES

AEOD/T513

50.338

IN PITS"

The subject Technical Review Report is enclosed for your information.

Between February 15 and 18, 1985, testing of the recirculation spray valves at North Anna Unit 1 indicated that one of these valves was sticking in the 75% open position. Maintenance personnel found mineral deposits on the valve yoke nut and valve stem which prevented the valve from operating properly. The valve had beer submerged and impurities in the water had solidified on the valve. Groundwater infiltration is a chronic problem at the North Anna site. This particular problem does not appear to have generic implications. It can, however, have safety implications for specific sites. The resident inspector is tracking North Anna's resolution of the problem. AEOD plans no further action.

> Dorothy J. Zukor, Engineer Reactor Systems Section 2

Reactor Operations Analysis Branch Office for Analysis and Evaluation

protty of Zakoz.

of Operational Data

Enclosure: As stated

cc: D. Thatcher

J. Wermiel

Distribution PORV

AEOD SF

ROAB CF

ROAB SF DZukor

WLanning

KSevfrit

FHebdon

KB1ack

Tippolito

CHeltemes

SC: ROABAYA DZukor: |as

11/6/85

8603120302 851108 ADDCK 05000338 PDR

> C: ROAB KSeyfrit 11///85

DD: AEODJO TIppolito 11/7/85