

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | L | B | R | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33
LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO 57 CAT 58

CON'T
01 | L | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 0 | 2 | 1 | 3 | 8 | 0 | 8 | 0 | 3 | 1 | 2 | 8 | 0 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operation "B" steam line radiation monitor 2-RM-90-138 failed
03 | downscale resulting in a half scram and half isolation. Reference T.S. 3.2.A.
04 | There was no danger to health or safety of the public. No previous occurrences.
05 | The other main steam line radiation monitor channel was available.
06 |
07 |
08 |

09 | I | A | E | A | T | R | A | N | S | F | Z | Z | 8 | 0 | 0 | 0 | 9 | 0 | 3 | L | 0 | 0 | 0 | 0 | Y | N | L | 8 | 2 | 4 | 5 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The radiation monitor failed down scale due to loss of power output from power
11 | drawer. Problem was traced to Sola power transformer catalog No. 21936, 115V/240-26.
12 | The entire power drawer was replaced and functional test was satisfactorily performed.
13 | No recurrence control required (nongeneric failure).
14 |

15 | E | 0 | 5 | 0 | NA | A | Operator observed
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
PERSONNEL INJURIES NUMBER DESCRIPTION
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER _____ PHONE _____

8003180544

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8009 Technical Specification Involved 3.2.A
Reported Under Technical Specification 6.7.2.b.(2)
Date of Occurrence 2/13/80 Time of Occurrence 1744 Unit 2

Identification and Description of Occurrence:

"B" main steam line radiation monitor 2-RM-90-138 failed downscale due to loss of power. This resulted in a half scram and half isolation.

Conditions Prior to Occurrence:

Unit 1 @ 0% refueling outage

Unit 2 @ 50%

Unit 3 @ 100%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Replacement power drawer was functional tested.

Apparent Cause of Occurrence:

Radiation monitor failed downscale due to power loss. The loss of power was contributed to a Sola power transformer failure.

Analysis of Occurrence:

There was no damage to plant equipment other than the Sola transformer. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

The entire power drawer was replaced and functionally tested.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 