

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE A L B R F 2
LICENSE NUMBER 0 0 - 0 0 0 0 0 0 - 0 0
LICENSE TYPE J 0
CAT 58

REPORT SOURCE L
DOCKET NUMBER 6 0 5 0 0 0 2 6 0
EVENT DATE 7 0 2 1 3 8 0
REPORT DATE 8 0 3 1 2 8 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During normal operation "B" steam line radiation monitor 2-RM-90-138 failed downscale resulting in a half scram and half isolation. Reference T.S. 3.2.A.

There was no danger to health or safety of the public. No previous occurrences.

The other main steam line radiation monitor channel was available.

SYSTEM CODE I A
CAUSE CODE E
CAUSE SUBCODE A
COMPONENT CODE TRANSF
COMP SUBCODE Z
VALVE SUBCODE Z

LER NO REPORT NUMBER 8 0
EVENT YEAR 8 0
SEQUENTIAL REPORT NO 0 0 9
OCCURRENCE CODE 0 3
REVISION 0
ACTION TAKEN C Z
FUTURE ACTION Z
EFFECT ON PLANT Z
SHUTDOWN METHOD Z
HOURS 0 0 0
ATTACHMENT SUBMITTED Y
NPRD-4 FORMS SUB N
PRIME COMP SUPPLIER L
COMPONENT MANUFACTURER S 2 4 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The radiation monitor failed down scale due to loss of power output from power drawer. Problem was traced to Sola power transformer catalog No. 21936, 115V/240-26.

The entire power drawer was replaced and functional test was satisfactorily performed.

No recurrence control required (nongeneric failure).

FACILITY STATUS E
% POWER 0 5 0
OTHER STATUS NA
METHOD OF DISCOVERY A
DISCOVERY DESCRIPTION Operator observed

ACTIVITY CONTENT RELEASED OF RELEASE Z Z
AMOUNT OF ACTIVITY NA
LOCATION OF RELEASE NA

PERSONNEL EXPOSURES
NUMBER 0 0 0
TYPE Z
DESCRIPTION NA

PERSONNEL INJURIES
NUMBER 0 0 0
DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY
TYPE Z
DESCRIPTION NA

PUBLICITY ISSUED N
DESCRIPTION NA

NRC USE ONLY

NAME OF PREPARER _____

PHONE

8003 180 344

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8009 Technical Specification Involved 3.2.A

Reported Under Technical Specification 6.7.2.b.(2)

Date of Occurrence 2/13/80 Time of Occurrence 1744 Unit 2

Identification and Description of Occurrence:

"B" main steam line radiation monitor 2-RM-90-138 failed downscale due to loss of power. This resulted in a half scram and half isolation.

Conditions Prior to Occurrence:

Unit 1 @ 0% refueling outage

Unit 2 @ 50%

Unit 3 @ 100%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Replacement power drawer was functional tested.

Apparent Cause of Occurrence:

Radiation monitor failed downscale due to power loss. The loss of power was contributed to a Sola power transformer failure.

Analysis of Occurrence:

There was no damage to plant equipment other than the Sola transformer. There was no activity release, no personnel exposure or injury and no danger to health or safety of the public.

Corrective Action:

The entire power drawer was replaced and functionally tested.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 