

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	C	O	F	S	V	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	2	0	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
LICENSEE CODE						LICENSE NUMBER										LICENSE TYPE JO					57 CAT 58					

01	L	6	0	5	0	0	0	2	6	7	7	0	2	1	9	8	0	8	0	3	1	8	8	0	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During testing, it was discovered that two of twelve helium circulator seal malfunc-

03 | tion pressure differential switch units tripped outside the limits of LCO 4.4.1,

04 | Table 4.4-3. Reactor operation during test interval. Reportable per Technical Speci-

05 | fication AC 7.5.2(b)1 and AC 7.5.2(b)2. No effect on public health or safety. Re-

06 | dundant system available and operable. Similar reports are RO 77-47, Final, and Pre-

07 | liminary reports RO 78-27, RO 79-32, and RO 79-56.

09	C	B	11	E	12	E	13	I	N	S	T	R	U	14	S	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
SYSTEM CODE			CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE			

17	8	0	21	22	23	0	0	7	24	25	26	27	0	3	28	29	L	30	31	0	32		
LER/RO REPORT NUMBER		EVENT YEAR		SHUTDOWN METHOD		SEQUENTIAL REPORT NO.		HOURS		ATTACHMENT SUBMITTED		OCCURRENCE CODE		REPORT TYPE		PRIME COMP. SUPPLIER		REVISION NO.		COMPONENT MANUFACTURER			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		OCCURRENCE CODE		REPORT TYPE		PRIME COMP. SUPPLIER		REVISION NO.		COMPONENT MANUFACTURER			
X	18	X	19	Z	20	Z	21	0	0	0	0	22	Y	23	N	24	N	25	B	0	8	0	26
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		OCCURRENCE CODE		REPORT TYPE		PRIME COMP. SUPPLIER		REVISION NO.		COMPONENT MANUFACTURER			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | ITT Barton Model 289 pressure differential switches failed to actuate at trip point

11 | due to dirt accumulation in electrical switches. Affected switches re-adjusted to

12 | proper trip points. Trip settings being checked on a monthly basis. Redesign of

13 | system being evaluated.

15	G	28	0	0	0	29	N/A	30	C	31	Operability Test	32
7	8	9	10	11	12	13	14	15	16	17	18	19
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				

16	Z	33	Z	34	N/A	35	N/A	36
7	8	9	10	11	12	13	14	15
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		

17	0	0	0	37	Z	38	N/A	39
7	8	9	10	11	12	13	14	15
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION		

18	0	0	0	40	N/A	41
7	8	9	10	11	12	13
PERSONNEL INJURIES		NUMBER		DESCRIPTION		

19	Z	42	N/A	43	
7	8	9	10	11	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION	

20	N	44	N/A	45	
7	8	9	10	11	
PUBLICITY		ISSUED		DESCRIPTION	

8008250 555

*Handwritten signature*