(7-77) LICENSEE EVENT REPORT
CONTROL BLOCK:
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T 0 1 8 BEPORT L 6 0 5 0 0 2 8 2 0 0 3 1 0 8 0 8 0 4 0 9 8 0 9 7 8 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2] During normal operation, Nuclear Power Range Channel 1N44 was inoperable for a few
0 3 minutes. Immediately after loss of the channel, its bistables were put in trip. No
0 4 effect on public health and safety. Redundant channels were operable. Tech Spec
0 5 [3.5 applies.
06
$\begin{array}{c} 0 \\ 7 \\ 8 \end{array} \\ \begin{array}{c} 8 \\ 7 \\ 8 \end{array} \\ \begin{array}{c} \\ 9 \\ 7 \\ 8 \end{array} \\ \begin{array}{c} \\ \\ \\ \\ 9 \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \\ \end{array} \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \end{array} \\ \\ \end{array} \\ \begin{array} \\ \\ \end{array} \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \begin{array}{c} \\ \\ \\ \\ \end{array} \\ \\ \end{array} \\ \\ \\ \end{array} \\ \\ \end{array} \\ \\ \end{array} \\ \\ \\ \\ \\ \\ \end{array} \\ \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\ \\ \\ \\ \\ \\ \\ \\ \end{array} \\$
17 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REPORT NO. 17 NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT X 18 Z 19 Z 20 Z 21 0 0 0 0 0 0 N 41 23 N 23 N 24 N 25 W 1 2 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 The high voltage power supply for the detector "latched up" due to a spike on the
[1] Yellow Instrument Bus. This is characteristic of these power supplies. Removal and
1 2 reinsertion of the power supply fuses allowed the circuitry to reset.
13
FACILITY STATUS 1 5 E 28 1 0 12 13 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 2 3 3 2 34 NA LOCATION OF RELEASE 36 PERSONNEL EXPOSURES 44 45 80
1 7 8 9 11 12 13 PERSONNEL IN JUBIES 13 80
1 H H D
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION B 9 10 B0
2 0 N 44 NA NRC USE ONLY 8 9 10 68 69 80 8
NAME OF PREPARER <u>A. A. Hunstad</u> 8 0041 4 0 440