

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 0 1 | G A E I H 2 | 2 0 0 - 0 0 0 0 0 0 - 0 0 | 3 4 1 1 1 1 | 4 1 1 | 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
7 8 9 0 1 | REPORT SOURCE L | 6 0 5 | 0 0 0 | 3 6 6 | 7 0 3 2 7 8 0 | 8 0 4 0 6 8 0 | 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | During performance of 18-month surveillance requirements on station bat-
0 3 | tery chargers 2A, 2B, and 2C, the chargers were unable to maintain the
0 4 | load required by Tech Specs 4.8.2.3.2.c.3, making them inoperable. Even
0 5 | though the chargers failed their surveillance tests, they were capable of
0 6 | carrying their respective normal loads as well as performing their re-
0 7 | charge function. There were no effects upon public health and safety due
0 8 | to this event. This is a non-repetitive event for these battery chargers |
7 8 9

0 9 | SYSTEM CODE E C | 11 | CAUSE CODE E | 12 | CAUSE SUBCODE Z | 13 | COMPONENT CODE B A T T R Y | 14 | COMP. SUBCODE Z | 15 | VALVE SUBCODE Z | 16

9 10 11 12 13 14 15 16 17 18 19 20

17 | LER/RO REPORT NUMBER 8 0 | EVENT YEAR 8 0 | SEQUENTIAL REPORT NO. 0 3 1 | OCCURRENCE CODE 0 1 | REPORT TYPE T | REVISION NO. 0

21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN E | FUTURE ACTION Z | EFFECT ON PLANT Z | SHUTDOWN METHOD Z | HOURS 0 0 0 | ATTACHMENT SUBMITTED Y | NRC-4 FORM SUB. N | PRIME COMP. SUPPLIER A | COMPONENT MANUFACTURER E 3 5 5 | 26

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The 2A and 2B station battery chargers required the loading of their
1 1 | respective silicon control rectifiers (SCRs) to be balanced. The 2C char-
1 2 | ger required adjustment of the current limit module. All three chargers
1 3 | were successfully tested on 3-27-80. The unit is now in full compliance
1 4 | with the requirements. |
7 8 9

1 5 | FACILITY STATUS G | % POWER 0 0 0 | OTHER STATUS NA | METHOD OF DISCOVERY B | DISCOVERY DESCRIPTION Surveillance Tests

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE Z | AMOUNT OF ACTIVITY NA | LOCATION OF RELEASE NA

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 | TYPE Z | DESCRIPTION NA

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 | DESCRIPTION NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z | DESCRIPTION NA

2 0 | PUBLICITY ISSUED Z | DESCRIPTION NA

NAME OF PREPARER C. L. Coggin, Supt. Plt. Eng. Serv. PHONE: 912-367-7781

8004150 481

LER #: 50-366/1980-031
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1980-031

On 3-27-80, station battery chargers 2A, 2B, and 2C failed their 18-month surveillance requirements. At the time of the occurrence the unit was in cold shutdown in order to perform 18-month surveillance requirements as well as perform the vent header deflection modification. The aforementioned chargers were unable to maintain the load required by Tech Specs 4.8.2.3.2.c.3, thereby making the chargers inoperable.

The 2A and 2B station chargers required the loading of their respective silicon control rectifiers (SCRs) to be balanced, while the 2C charger required adjustment of the current limit module. All three chargers were successfully tested on 3-27-80 bringing the unit into full compliance with the requirements.

The station battery chargers on Unit 1 are identical to those on Unit 2 which makes the occurrence applicable to Unit 1. The chargers on Unit 1 will be checked during the next cold shutdown of sufficient duration.