

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	F	L	Q	R	P	3	0	0	-	0	0	0	0	0	0	-	0	0	4	1	1	1	1	-	-	
LICENSEE CODE														LICENSE NUMBER						LICENSE TYPE					STATE	

01	L	0	5	0	-	0	3	0	2	0	8	0	4	7	8	0	8	3	0	7	8
REPORT SOURCE		DOCKET NUMBER								EVENT DATE						REPORT DATE					

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

On 4 August 1978 a telecopy of the B&W Report on Reactor Vessel Weld Material was received. The report informed Florida Power Corporation and CR-3 staff that atypical weld material may have been used in the construction of the CR-3 Reactor Vessel. No redundant system. Public health and safety is not a factor, as the revised operating curves, assuming atypical weld material is present, are based on the same criteria as the original operating curves and have been extrapolated to 5 EFF.

03	C	A	B	B	V	E	S	S	E	L	A	7	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE	
17	7	8	0	3	7	0	1	T	1	1	1	1	
LEAD NO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
15	Z	Z	0	0	0	0	0	0	0	N	B	0	
ACTION TAKEN		EFFECT ON PLANT		SPRINT CODE METHOD		HOURS		ATTACHMENT SUBMITTED		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

B&W reported that weld filler wire used in construction of vessels was unknowingly intermixed in a shipment from a supplier. Three weld areas of concern are: closure head-to-flange; outlet nozzle-to-nozzle belt; and beltline region. To ensure Reactor Vessel integrity, we have administratively employed revised pressure-temperature heatup, cooldown and inservice leak and hydrostatic test curves.

15	H	0	0	0	NA	D	Notification from NSSS			
FACILITY STATUS		N POWER			OTHER STATUS		METHOD OF DISCOVERY		SCENARIO DESCRIPTION	
16	Z	Z	NA	NA	NA	NA	POOR ORIGINAL			
ACTIVITY RELEASED		CONTENT		AMOUNT OF ACTIVITY				LOCATION OF RELEASE		
17	0	0	0	0	Z	NA	8002270645			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION				
18	0	0	0	0	NA					
PERSONNEL INJURIES		NUMBER		TYPE		DESCRIPTION				
19	Z	NA								
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION						
20	Z	NA								
PLANT DESCRIPTION		REACTOR		DESCRIPTION						
21	N	NA								

NAME OF PREPARER: J. Cooper PHONE: (904) 795-6486

SUPPLEMENTARY INFORMATION

1. Report No.: 50-302/78-037/01T-1
2. Facility: Crystal River Unit #3
3. Report Date: 30 August 1978 (11 August 1978 report revised)
4. Occurrence Date: 4 August 1978
5. Identification of Occurrence:

B&W reported atypical weld material may have been used in construction of CR-3 Reactor Vessel.

6. Conditions Prior to Occurrence:

Mode 6 refueling.

7. Description of Occurrence:

On 4 August 1978, a telecopy of the B&W Report on Reactor Vessel Weld Material was received. The report informed Florida Power Corporation and CR-3 staff that atypical weld material may have been used in the construction of the CR-3 Reactor Vessel. Three weld areas of concern are: closure head-to-head flange; outlet nozzle belt; and beltline region.

8. Designation of Apparent Cause:

B&W has reported that weld filler wire, atypical of that used in the construction of nuclear pressure vessels, was unknowingly intermixed in a shipment of typical weld material from a supplier.

9. Analysis of Occurrence:

Public health and safety is not a factor as the revised operating curves, assuming the atypical weld material is present, are based on the criteria of the original operating curves and have been extrapolated to 5 EFPY.

10. Corrective Action:

To ensure Reactor Vessel integrity, we have administratively employed revised pressure temperature heatup, cooldown, and inservice leak and hydrostatic test curves. These will be employed until a revision to Tech. Spec. has been received.

11. Failure Data:

First occurrence of this type of event.